Toolwear Charts

Summary

The **Toolwear Charts** procedure creates control charts for a single numeric variable where the measurements are expected to change in a linear fashion due to the wear of a tool. Unlike most other control charts, the control limits are not horizontal, but instead follow the expected trend due to the tool wear. Normally, specification limits are added to the chart to help determine when it is time to change the tool.

There are two Toolwear menu selections, one designed for data collected in subgroups and the other for individuals. The procedure creates both a toolwear chart and an R chart, S chart, or MR(2) chart. The charts may be constructed in either *Initial Study* (Phase 1) mode, where the current data determine the slope and spacing of the control limits, or in *Control to Standard* (Phase 2) mode, where the limits come from either a known standard or from prior data.

Sample StatFolio: toolwear chart.sgp

Sample Data:

The file *toolwear.sgd* contains 7 samples of 5 measurements each, taken once every hour from the use of a cutting tool. The data are from Duncan (1986). The data in that file are shown below:

Time	X1	X2	X3	X4	X5
9:00	0.255	0.256	0.256	0.257	0.258
10:00	0.255	0.256	0.257	0.258	0.258
11:00	0.257	0.257	0.258	0.258	0.259
12:00	0.258	0.258	0.259	0.260	0.261
1:00	0.259	0.260	0.260	0.260	0.262
2:00	0.260	0.262	0.262	0.263	0.264
3:00	0.263	0.263	0.264	0.264	0.265

The specification limits for the dimension of the part are 0.255 to 0.265 inches. Note the increase in the measurements from hour to hour as the tool wears.

Data Input

There are two menu selections that create toolwear charts, one for individuals data and one for grouped data. In the case of grouped data, the original observations may be entered, or subgroup statistics may be entered instead.

Case #1: Individuals

The data to be analyzed consist of a single numeric column containing n observations. The data are assumed to have been taken one at a time.

Toolwear Individuals Chart		X
time diameter	Observations: diameter (Date/Time/Labels:) time (LSL:) (Nominal:) (USL): (Select:) (Select:)	_
🔲 Sort column names		
OK Cancel	Delete Transform Help	

- **Observations:** numeric column containing the data to be analyzed.
- Date/Time/Labels: optional labels for each observation.
- LSL, Nominal, USL: optional lower specification limit, nominal (target) value, and upper specification limit.
- **Select:** subset selection.

<u>Case #2: Grouped Data – Original Observations</u>

The data to be analyzed consist of one or more numeric columns. The data are assumed to have been taken in groups, in sequential order by rows.

STATGRAPHICS - Rev. 7/7/2009

Toolwear Chart	\mathbf{X}
Time X1 X2 X3 X4 X5	Data Observations X1 X2 X3 X4 X5
	Subgroup Statistics Means: Ranges: Sizes:
	Date/Time/Labels or Size: Time (LSL:) (Nominal:) .255 .265
Sort column names	
Sort column names	(LSL:) (Nominal:) (USL): .255 .265 (Select:) .265 Delete Transform

- **Observations:** one or more numeric columns. If more than one column is entered, each row of the file is assumed to represent a subgroup with subgroup size *m* equal to the number of columns entered. If only one column is entered, then the *Date/Time/Labels or Size* field is used to form the groups.
- **Date/Time/Labels or Size**: If each set of *m* rows represents a group, enter the single value *m*. For example, entering a 5 implies that the data in rows 1-5 form the first group, rows 6-10 form the second group, and so on. If the subgroup sizes are not equal, enter the name of an additional numeric or non-numeric column containing group identifiers. The program will scan this column and place sequential rows with identical codes into the same group.
- LSL, Nominal, USL: optional lower specification limit, nominal (target) value, and upper specification limit.
- **Select:** subset selection.

Case #3: Grouped Data – Subgroup Statistics

In this case, the statistics for each subgroup have been computed elsewhere and entered into the datasheet, as in the table below:

Sample	Means	Ranges	Sizes
1	0.2564	0.003	5
2	0.2568	0.003	5
3	0.2578	0.002	5
4	0.2592	0.003	5
5	0.2602	0.003	5
6	0.2622	0.004	5
7	0.2638	0.002	5

Toolwear Chart	
<mark>time</mark> MEANS RANGES SIZES	Data Observations
	Subgroup Statistics Means: MEANS
	Ranges: RANGES Sizes:
	(Date/Time/Labels:)
	(LSL:) (Nominal:) (USL):
Sort column names	Delete Transform Help

Copyright © 2009 by StatPoint Technologies, Inc.

- **Subgroup Statistics**: the names of the column containing the subgroup means, subgroup ranges, and subgroup sizes.
- Date/Time/Labels: optional labels for each subgroup.
- LSL, Nominal, USL: optional lower specification limit, nominal (target) value, and upper specification limit.
- Select: subset selection.

Toolwear Chart

The Toolwear chart plots the observations or subgroup means together with a trend line and control limits.



The centerline of the chart is defined by

$$\mu_j = A + Bj \tag{1}$$

where *B* is the slope of the line and *A* is the Y-intercept. The control limits are drawn around the centerline at

$$\hat{\mu} \pm k \frac{\hat{\sigma}}{\sqrt{n}} \tag{2}$$

where k is the multiple (usually equal to 3) specified on the *Control Charts* tab of the *Preferences* dialog box, accessible from the *Edit* menu. This allows for the natural variability around the regression line, but does not account for any error in estimating the line. In *Initial Studies* mode, the intercept and slope of the line are obtained from the least squares regression line of the plotted points against *j*. The analyst may choose to include the model estimation error using the *Analysis Options* dialog box, in which case the limits are placed at

$$\hat{A} + \hat{B}j \pm k\hat{\sigma} \sqrt{\frac{1}{\bar{n}} \left(1 + \frac{(j - \bar{j})^2}{\sum_{i=1}^m n_i (i - \bar{j})^2} \right)}$$
(3)

where \overline{j} is the average of the period numbers used to fit the line. The standard deviation around the line may be estimated using either the mean squared error (MSE) of the fitted regression model or through the average range or standard deviation, as described below.

In the current example, all points remain well inside the control limits, indicating no significant departure from the estimated trend line at any point in time.

Analysis Summary

This pane displays the fitted trend model and summarizes the control charts.

Toolwear Chart - X1-X5
Number of subgroups $= 7$
Subgroup size = 5.0
0 subgroups excluded
Upper spec. limit: 0.265
Lower spec. limit: 0.255
Distribution: Normal
Transformation: none
Toolwear Chart
Period #1-7
UCL: +3.0 sigma = 0.264927
Centerline 0.263279
LCL: -3.0 sigma 0.261631
0 bevond limits
Range Chart
Period #1-7
UCL: +3.0 sigma 0.0060414
Centerline 0.00285714
LCL: -3.0 sigma 0.0
0 beyond limits
Estimates
Period #1-7
Process mean 0.254429+0.00126429*t
Process sigma 0.00122835
Average range 0.00285714
Sigma estimated from average range

Included in the table are:

- **Subgroup Information**: the number of observations or subgroups and the average subgroup size.
- **Specification Limits**: the specification limits for the variable of interest.

Copyright © 2009 by StatPoint Technologies, Inc.

- **Distribution:** the assumed distribution for the data. By default, the data are assumed to follow a normal distribution. However, one of 26 other distributions may be selected using *Analysis Options*.
- **Transformation:** any transformation that has been applied to the data. Using *Analysis Options*, you may elect to transform the data using either a common transformation such as a square root or optimize the transformation using the Box-Cox method.
- **Toolwear Chart:** a summary of the centerline and control limits for the toolwear chart, together with a count of any points beyond the control limits.
- MR(2)/R/S Chart: a summary of the centerline and control limits for the dispersion chart.
- Estimates: estimates of the fitted trend line and the process standard deviation σ . The trend line assumes that the first point was plotted at j = 1. The method for estimating the process sigma depends on the settings on the *Analysis Options* dialog box, described below.
- Mean residual MR(2), Average Range, or Average S: the average of the values plotted on the dispersion chart.

Analysis Options

Toolwear Chart Options					
Type of Study	Estimate Sigma From	Control to Standard			
Initial Study	R or S Chart	Intercept: -6.27744E66			
Control to Standard	C Model MSE	Slope: -6.27744E66			
Include Model Estimatio	Sigma: 0.00281144				
X-bar Control Limits	R or S Control Limits	J			
✓ Upper: I 3.0 Sigma	Upper: 3.0 Sigma				
✓ Lower: -3.0 Sigma	✓ Lower: -3.0 Sigma				
OK Cancel Exclude Transform Help					

• **Type of Study:** determines how the control limits are set. For an *Initial Study* (Phase 1) chart, the limits are estimated from the current data. For a *Control to Standard* (Phase 2) chart, the control limits are determined from the information in the *Control to Standard* section of the dialog box.

- Estimate sigma from: specifies whether the process sigma should be estimated from the dispersion chart, or whether it should be estimated from the residual mean squared error of the fitted regression model.
- **Control to Standard:** To perform a Phase 2 analysis, select *Control to Standard* for the *Type of Study* and then enter the established standard process sigma (or other parameters if not assuming a normal distribution) and the intercept and slope of the trend line.
- **Include Model Estimation Error**: for initial studies mode, whether the estimation error of the regression line should be added to the estimate of the process sigma. In small samples, this could increase the width of the control limits substantially.
- **X-Bar Control Limits:** specify the multiple *k* to use in determining the upper and lower control limits on the toolwear chart. To suppress a limit completely, enter 0.
- **R** or **S** Control Limits: specify the multiple *k* to use in determining the upper and lower control limits on the MR(2), R, or S chart. To suppress a limit completely, enter 0.
- Exclude button: Use this button to exclude specific subgroups from the calculations.
- Transform Button: Use this button to specify a transformation or non-normal distribution.

For a discussion of the *Exclude* and *Transform* features, see the documentation for *Individuals Control Charts*.

MR(2)/R/S Chart

A second chart is also included to monitor the process variability.



For individuals data, the chart displayed is an MR(2) chart, described in the *Individuals Control Charts* documentation. For grouped data, either an R chart or an S chart is plotted, depending on the setting on the *Control Charts* tab of the *Preferences* dialog box:

STATGRAPHICS - Rev. 7/7/2009

Preferred Dispersion Chart—
Range
🔿 Sigma

These charts are described in the X-Bar and R Charts and the X-Bar and S Charts documents.

Pane Options			
Control Chart Options	×		
Outer Warning Limits	ОК		
Sigma: 2.0	Cancel		
Inner Warning Limits	Help		
Sigma 1.0			
Moving Average			
Orden <mark>9</mark>			
Exponentially Weighted Moving Av	erage		
Lambda: 0.2			
Decimal Places for Limits:			
4			
✓ Mark Runs Rules Violations			
Color Zones			
Display specification limits			

- **Outer Warning Limits**: check this box to add warning limits at the specified multiple of sigma, usually at 2 sigma.
- **Inner Warning Limits**: check this box to add warning limits at the specified multiple of sigma, usually at 1 sigma.
- Moving Average: check this box to add a moving average smoother to the chart. In addition to the subgroup means, the average of the most recent q points will also be displayed, where q is the *order* of the moving average. The default value q = 9 since the 1-sigma inner warning limits for the original subgroup means are equivalent to the 3-sigma control limits for that order moving average.
- Exponentially Weighted Moving Average: check this box to add an EWMA smoother to the chart. In addition to the subgroup means, an exponentially weighted moving average of the subgroup means will also be displayed, where λ is the smoothing parameter of the EWMA. The default value λ = 0.2 since the 1-sigma inner warning limits for the original subgroup means are equivalent to the 3-sigma control limits for that EWMA.
- **Decimal Places for Limits:** the number of decimal places used to display the control limits.

- Mark Runs Rules Violations: flags with a special point symbol any unusual sequences or runs. The runs rules applied by default are specified on the *Runs Tests* tab of the *Preferences* dialog box.
- Color Zones: check this box to display green, yellow and red zones.
- **Display Specification Limits**: whether to add horizontal lines to the chart displaying the location of the specification limits (if any).

Toolwear Chart Report

This pane tabulates the values plotted on the control charts:

Toolwear C	hart R	eport	
All Subgrou	ps	-	
X = Exclude	ed	* = Beyor	nd Limits
Subgroup	Size	X-bar	Range
9:00	5	0.2564	0.003
10:00	5	0.2568	0.003
11:00	5	0.2578	0.002
12:00	5	0.2592	0.003
1:00	5	0.2602	0.003
2:00	5	0.2622	0.004
3:00	5	0.2638	0.002

Out-of-control points are indicated by an asterisk. Points excluded from the calculations are indicated by an X.

Pane Options



• **Display:** specify the observations or subgroups to display in the report.

Runs Tests

The *Runs Tests* pane displays the results of standard tests designed to look for unusual sequences of points.

```
Runs Tests
Rules
(A) runs above or below centerline of length 8 or greater.
```

Copyright © 2009 by StatPoint Technologies, Inc.

For a detailed description of these tests, see the X-Bar and R Charts documentation.



Select the runs tests to be applied and the parameters that define those tests. For example, some practitioners prefer to test for runs of length 7 rather than 8.

Tolerance Chart

The Tolerance Chart plots the data together with the specification limits.



Pane Options

Tolerance Chart Options				
Specifications		OK		
Upper: 0.265		Cancel		
, Nominal:		Help		
0.26	- Plo	t		
Lower:		Points		
10.200		Nominal		
Decimal Places for Limits:				
3				

- Nominal: enter a nominal or target value, if any.
- **Decimal Places for Limits**: the number of decimal places to use for the limits.
- Plot Points: select to display each observation. Otherwise, only the ranges will be plotted.
- **Plot Nominal**: select to draw a line at the nominal value.

Save Results

The following results can be saved to the datasheet, depending on whether the data are individuals or grouped:

- 1. Observations or means the original observations or subgroup means.
- 2. Ranges, sigmas, or moving ranges the values plotted on the dispersion chart.
- 3. *Sizes* the subgroup sizes.
- 4. *Labels* the subgroup labels.
- 5. Process Mean the estimated process mean.
- 6. *Process Sigma* the estimated process standard deviation.
- 7. *Residuals* the residuals from the trend model.