

2017 Volkswagen Atlas

Weak Key Fob - Failure to Recognize



When an Atlas proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in the Atlas is on the right side of the steering column.

Immediately replace the weak key fob battery.