

## McLaren 570S

Weak Key Fob -  
Failure to Recognize



When a McLaren proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated areas will aid in key recognition and help start the vehicle.

The designated areas in this model are indicated above, circled in red.

Immediately replace the weak key fob battery.