

ClareHome v6.0.7 and Fusion v6.0.1

Release Notes

Content

- Introduction...1
- Fusion...1
- Resolved issues...2
- Contact information...2

Last modified: 08/27/18

Introduction

The ClareHome v6.0.7 and Fusion v6.0.1 release notes address bug fixes and minor Fusion changes.


Fusion

The Fusion v6.0.1 release contains an updated myClareHome tab and Location sub-tab changes.

Profile sub-tab

This release updates the myClareHome sub-tab, changing the name to **“Profile”**.


Figure 1: Fusion Profile sub-tab



Location sub-tab

The location sub-tab in Fusion is now view only. The location is set using the ClareHome app.

Figure 2: Fusion Locations sub-tab



Resolved issues

The following issues were identified and corrected in the ClareHome v6.0.7 releases.

Resolved issues

Bug #	Description
EPI-9367	The Honeywell Lyric integration now supports TLSv1.2, required for continued Honeywell use after the Honeywell firmware update.
EPI-9309	Nest Thermostats no longer require re-authentication after the ClareHome v6.0.0 update.
EPI-9353	Areas removed from entertainment services no longer cause service problems.
CHP-1524	Z-Wave dimmers set to 100% in Scenes now operate normally.

Contact information

Clare Controls, LLC.
7519 Pennsylvania Ave, Suite 104
Sarasota, FL 34243

General: 941.328.3991
Fax: 941.870.9646
www.clarecontrols.com

Integrator/Dealer Support: 941.404.1072
claresupport@clarecontrols.com

Homeowner Support (ClareCare): 941.315.2273 (CARE)
help@clarecontrols.com