



This Service Letter is FAA/DMC Form 1 Approved

This Service Letter reidentified  
Service Bulletin M-20-128  
per Service Instruction M20-15.

**SUBJECT:** Tail Light Assy. Bulb Change

**MODELS AFFECTED:** M20 1002 - 1200  
M20A 1201 - 1700  
M20B 1701 - 1851, 1853 - 1939  
M20C 1852, 1940 - 3043  
M20D 1, 101 - 258  
M20E 101 - 701

**TIME OF COMPLIANCE:** At the next 100 hour inspection

**INTRODUCTION:** It will be necessary for the owners of the above mentioned aircraft to replace the tail light bulb.

- INSTRUCTIONS:**
1. Remove the No. 93 light bulb.
  2. Install the new No. 1777 light bulb.
  3. Turn on navigation lights and check for operation.
  4. Make log book entry to show compliance with this service letter.

**COMPLIANCE:** Upon compliance of this service letter, please fill out the enclosed compliance card and return it to Mooney Aircraft, Inc. for our files.

**SERVICE LETTER KIT 20-128**

No. 1777 Light Bulb 1

This kit may be ordered from your local Mooney distributor. Direct factory orders will not be accepted.