

This Service Letter reidentified as
Service Bulletin M *20-18*
per Service Instruction M20-15.

MOONEY AIRCRAFT INC.
KERRVILLE, TEXAS

SERVICE LETTER 20-18

DATE: 12-11-56
SUBJECT: Inspection of welded joint between rudder
control horn and rudder spar.
MODELS AFFECTED: M-20 Serial No. 1002 thru 1126
TIME OF COMPLIANCE: Immediately and thereafter at regular
25 hour inspection.

Compliance with the above is necessary due to the possibility
of cracks developing at the joint in question. This inspection
may be made without removal of the tail cone fairing.