

MO. NEY AIRCRAFT INC.

SERVICE LETTER NO. 20-29

DATE: 12-4-57

SUBJECT: Inspection-Aileron & Flap Fabric under Metal Gap Strips.

MODELS AFFECTED: M-20 All Models

TIME OF COMPLIANCE: Immediately and at Subsequent Regular 100 Hour Inspection.

Recent reports indicate the possibility of damage to aileron and flap fabric due to rubbing action of the gap strips.

It is therefore necessary that the following inspection be accomplished:

- (1) Deflect control surfaces to full down position.
- (2) Remove aluminum marks from fabric.
- (3) Inspect for fabric wear.

Please return the enclosed compliance card with details of any damage discovered.