This Service Letter reidentified as Service Bulletin M 20-39 per Service Instruction M20-15.

MOONEY AIRCRAFT INC. KERRVILLE, TEXAS

SERVICE LETTER 20-39

DATE:

August 28, 1958

SUBJECT:

Inspection - Aileron Counterweight

MODELS AFFECTED:

M20, Serial No. 1006, 1011, 1012, 1015, 1016, 1020, 1024, 1027, 1028, 1030-1035. 1037-1039, 1046, 1048, 1050, 1052-1065.

TIME OF COMPLIANCE:

Immediately

ENCLOSURE:

Compliance Card

Some aircraft remain which have not been modified in accordance with Mooney Service Letter 20-7 kev. A, issued on 10-28-57. It is Necessary that the above listed aircraft be inspected to determine if the brace has been added to the aileron counterweight arm (see sketch). Check also to determine that the lead weight is securely in place on the tubular arm.

Please complete and return the enclosed compliance card so that Service Letter 20-7 (Kit-Aileron Counterweight Balance Arm Reinforcement) can be issued as necessary and our records brought up to date.

