



(FAA Approved)

This Service Bulletin reidentified as
Service Instruction M.26-28
per Service Instruction M20-15

SUBJECT: Fuel Filler cap alignment decals.

MODELS AFFECTED:

M20C	2623 - 2690
M20D	201 - 241
M20E	101 - 263

TIME OF COMPLIANCE: At Owner's Discretion

INTRODUCTION:

There have been a few instances where the left-hand fuel cap was damaged due to line personnel's trying to install the cap improperly. We, therefore, suggest that the enclosed decals be applied to the filler cap and wing so that it will aid line personnel and therefore, eliminate filler cap damage.

INSTRUCTIONS:

1. Make sure the fuel filler caps are on properly.
2. Place the decals for the left wing per Figure 1.
3. Place the decals for the right wing per Figure 2.

Service Bulletin No. 5

Parts List

	No. Req.
1. 150010 - 57 decal	4
2. 150010 - 59 decal	2

