

**TR100**  
Extreme UNIVERSAL



**HEAT:** 500 °C  
**SPEED:** 40%

**T3**  
Extreme



**HEAT:** 430 °C  
**SPEED:** 4


**T300**  
Extreme



**Hot Air Welding**  
**HEAT:** 500 °C  
**SPEED:** 4 M/MIN

**Hot Wedge Welding**  
**HEAT:** 450 °C  
**SPEED:** 5 M/MIN


**T600**  
Extreme



**Hot Air Welding**  
**HEAT:** 500 °C  
**SPEED:** 4 M/MIN

**Hot Wedge Welding**  
**HEAT:** 450 °C  
**SPEED:** 5 M/MIN

**112**  
Extreme



**HEAT:** 730 °C  
**SPEED:** 10 M/MIN

\*\*All published weldi settings are estimate ranges. The settings of your machine may vary greatly. The testing of all seams and all fabrics is the exclusive responsibility of the operator.

**MILLER WELDMASTER®**  
The First Choice Globally

4220 Alabama Ave  
Navarre | Ohio | 44662 USA  
Phone. 330 - 833 - 6739 | Fax. 330 - 837 - 2828  
[www.weldmaster.com](http://www.weldmaster.com) | [sales@weldmaster.com](mailto:sales@weldmaster.com)