

Product ID: 7007

Software Version: 6.0.2

Release Date: February 13, 2020

Overview:

This document describes the fixes implemented for this release. The previous version was 5.1.14 from May 17, 2019.

Improvements / New Features:

- 1. ACORN-2358, ACORN-2355, ACORN-2356, ACORN-2357, ACORN-2367, ACORN-2364**
Addressed critical fault configuration issue while performing a GUI Update.
- 2. ACORN-2246 LAN IP is set to 169.254.100.1 and it is constantly displayed on LCD**
LCD resets to show a valid LAN IP.
- 3. ACORN-2251 Cannot set Tamper zone to Bypass**
Tamper zone may be set to Bypass.
- 4. ACORN-2247 Change the default TTL of IntelliTap packets to 3 hrs**
Increased default TTL of IntelliTap packets.
- 5. ACORN-2264 Not showing receiver 8 connected**
Receiver 8 info now shows in TOOLS – IP Traffic.
- 6. ACORN-1901 Rename 'Upload and Download' words in System Page of Acorn GUI according to what Alarm Industry uses**
Adjusted titles to "Download Current Settings from Subscriber" & "Upload Preconfigured Settings to Subscriber" due to the ability to use different devices to access the config web GUI; pad, phone, Mac, PC, etc..

Bug Fixes:

- 1. ACORN-2386 2.0 Subscriber - Timer Test Lag**
A problem has been fixed where there was a significant error in requested check-in times versus actual check-in origination time. This timing error could exceed expected limits for declaring a missed check-in.
- 2. ACORN-2207 Support Product Specific Package Files for Update - Web GUI**
The BURG products previously supported the upgrade pkg filename format of **rootfs** (rootfs-*.pkg). They now also support a **model#** format (i.e. 7007_Release_*.pkg). If your subscriber is currently running installed firmware of 'rootfs-5.1.14.3622.pkg' or earlier, upgrade via the standard rootfs-*.pkg format, otherwise you may upgrade via model# filename format.