# Rebooting Micros Workstation 5/5a

- **WS5 and WS5a**
    1. **When facing the touch screen side of the Workstation:**

    The power button is under the power light. Tilt workstation back:

    To reboot the workstation using the power button, simply hold the button down for approx 10 seconds. Once the workstation is off push and release the power button to turn it back on.

    2. **To reboot the workstation using the power cord (not recommended, should be last resort only!) simply unplug the power cord from the wall for 10 seconds and then plug it back in. The workstation will usually load automatically. If this does not happen push and release the power button.**