

Profile



©2010 National Coatings Corporation.
All Rights Reserved.

North Garner Middle School

Size: 10,600sf

Location: Garner, North Carolina

Challenge *Aged EPDM Roofing*

- Aging EPDM
- Damaged from years of heat, sunlight and rain
- Replacement was not an option
- Excessive roof temps

Solution *ARM Roofing System*

- AcryShield A502 Basecoat - excellent adhesion to EPDM
- No need for corrosive pretreatment primer
- Sustainable roofing
- EPDM was restored

National Coatings' AcryShield A502/A500 system was the choice for this restoration. This coating system is unique in the roof coating industry as it is not only waterborne, but also does not require a corrosive primer that is normally used to achieve adequate adhesion to EPDM.

During the inspection the contractor noted that the National Coatings Corporation roof coatings sprayed very well and was particularly impressed with the adhesion of the A502 primer. The adhesion of the A502 to the EPDM was found to be excellent.



**NATIONAL
COATINGS**

1201 Calle Suerte, Camarillo, CA 93012
(800) 423-9557, Fax (800) 294-3866

www.nationalcoatings.com, info@nationalcoatings.com