



MOTOROLA SOLUTIONS FM APPROVED INTRINSICALLY SAFE RADIOS INTENT-TO-CANCEL NOTICE

OVERVIEW

Motorola Solutions announces the cancellation of the FM approved battery options for all Professional radios. Intrinsically Safe 2-way radios approved to the FM3610_88 standard can only be manufactured through the end of December 2015. The deadline affects all Land Mobile Radio manufacturers.



MODEL CANCELLATION ROLLOUT

The Motorola Solutions 2-way radio FM battery options listed below will be cancelled and no longer available for order after DECEMBER 15, 2015. The last ship date will be DECEMBER 31, 2015.

LAST ORDER DATE	LAST SHIP DATE
DECEMBER 15, 2015	DECEMBER 30, 2015

OPTION	RADIO
QA02309	XPR7350, XPR7550, XPR7380, XPR7580
QA00366	XPR6380, XPR6580
QA00051	PR860, HT750, HT1250, HT1250LS+
Q390	HT750, HT1250, HT1250LS+
QA00668	EX500, EX560XLS, EX600XLS
Q393	PR1500
QA00746	PR400 VHF & UHF
Q869	PR400 VHF & UHF

NEW PRODUCTS

Motorola is adapting to a new TIA-4950 standard for Hazardous Location certification of 2-way radios, which is similar to the FM3610_88 standard. UL approved XPR7350, XPR7550, XPR7380 and XPR7580 radios and batteries have been available since Q1 2015.

SERVICE SUPPORT

FM approved radios that are deployed in the field will maintain the FM Intrinsically Safe approval status, provided that any service and repairs are done at an FM audited repair facility. FM approved battery and accessory replacements will continue to be sold.

CONTACT INFORMATION

For questions regarding the cancellation of the FM3610_88 options for all radios please contact:

Motorola Solutions Customer Support Center

In the US, call 1-800-422-4210
In Canada, call 1-800-543-3222