

KUDUwave Keyboard Shortcuts

Here is a list of Keyboard Shortcuts you can print and keep as a quick reference.

Space Bar	Present a Tone
Enter	Mark Threshold on the grid
Right Ctrl	Mark Threshold on the grid if the patient did not respond at low thresholds due to loud ambient noise levels
Delete	Delete a Threshold Mark
A	Air Conduction Mode
B	Bone Conduction Mode
U	Uncomfortable Loudness Level (UCL)
M	Most Comfortable Loudness Level (MCL)
L	Left Ear
R	Right Ear
T / Esc	Talk Forward On / Off
Page Down	Make Masking Level Louder
Page Up	Make Masking Level Softer
Home	Mute Masking
Left Arrow	Move to a Lower Frequency
Right Arrow	Move to a Higher Frequency
Up Arrow	Decrease Intensity
Down Arrow	Increase Intensity