



Clare Video Doorbell Firmware v2.1.0 Build 180802 Release Notes

Content

Introduction...1
Resolved issues...2
Contact information...2

Last modified: 10/15/18

Introduction

The Clare Video Doorbell (CVD) v2.1.0 firmware build 180802 contains several feature improvements and bug resolutions.

Improved features:

- Removed the doorbell's audio response when the call is unanswered. The doorbell no longer says; "Caller is unavailable."
- The CVD's time is automatically set when it is registered in the cloud.
- Optimized stability of motion detection when in IR mode.
- Doorbell is now auto-discoverable on NVRs, supporting live view, record, and playback.

Resolved issues

The following issues and bugs are resolved with the v2.1.0 firmware release.

General resolved issues:

- Audio digital noise is reduced and has clearer sound and voice pronunciation.
- Video recordings now include audio on all supported phone models.

Resolved issues

Bug #	Resolution
CV-617	Fixed motion notifications related to 2-way audio.
CV-605	When connecting to Wi-Fi, the doorbell no longer says “connection failed” before the connection attempt.
CV-631	Doorbell SD cards are not set to a “Not Initialized” state after being set to “Normal.”
CV-640	The doorbell no longer displays a solid blue light when Cloud registration fails.

Contact information

Clare Controls, LLC.
7519 Pennsylvania Ave, Suite 104
Sarasota, FL 34243

General: 941.328.3991
Fax: 941.870.9646
www.clarecontrols.com

Integrator/Dealer Support: 941.404.1072
claresupport@clarecontrols.com

Homeowner Support (ClareCare): 941.315.2273 (CARE)
help@clarecontrols.com