



TECH BULLETIN

TECHNICAL SUPPORT

© 16MAY14 Clare Controls, Inc.

HDBaseT Products Requiring an HDMI 1x2 Splitter

Introduction

The following products do not work with HDBaseT extender sets without a 1x2 Splitter.


Affected products

- Cisco Explorer 4742HDC and 8642HDC DVR cable boxes
- Cisco RNG150 and RNG200 DVR cable boxes
- Cisco 164X HDC boxes
- Scientific Atlanta 8240 and 8300HDC cable boxes provided by Time Warner Cable or Comcast/Xfinity
- Samsung BD-ES6000 Blu-ray player
- Motorola DCX3200M P2
- Motorola RNG-series boxes

Corrective action

To allow the HDBaseT to work with these products, insert a Clare Controls HDMI 1x2 Splitter (model number CM-SP1210-HD) between the device and the HDBaseT extender, as shown in the following figure.

Connecting the 1x2 Splitter



Contact information

Clare Controls, Inc.
7519 Pennsylvania Ave, Suite 104
Sarasota, FL 34243
Support: 941.404.1072
Fax: 941.870.9646
claresupport@clarecontrols.com
www.clarecontrols.com