




Eaton Issues Recall for Heavy Duty 30A and 60A Safety Switches

Safety switches can potentially supply power when the handle is in the “off” position

This issue affects 30A and 60A Heavy Duty safety switches manufactured between November 19, 2015 and January 23, 2018. Affected catalog numbers that are included in this recall include:

	Catalog Numbers			
	DCG110	DEM362	DH361	STS262
	DCG210	DH161	DH362	STS321
	DCG306	DH162	DH661	STS322
	DCG606	DH261	DH662	STS361
	DCU110	DH262	OLI361	STS362
	DCU210	DH321	OLI362	
	DCU306	DH322	STS261	

Mark affected switches (outside the switch near the handle) with a highly visible tag/markings containing the following language: **“Danger—This safety switch may not disconnect power even when the handle is in the “off” position. Eaton has been contacted and a repair kit has been requested. For removing power from the circuit or performing lock-out, the up-stream device should be utilized to switch or isolate downstream equipment.”**

For more detailed information related to the recall, on-site inspection, and repair instructions; visit www.eaton.com/hdss-advisorybulletin , email hdssadvisorybulletin@eaton.com , or call Eaton’s Technical Resource Center at 1-877-ETN-CARE.



Safe**ALERT**



ORCIG 2018 SafeAlert Series

This material is intended to be a broad overview of the subject matter and is provided for informational purposes only. Old Republic Contractors Insurance Group, Inc. does not endorse or recommend any products or services nor does it make any representation or warranty regarding the accuracy or completeness of the information. Old Republic Contractors Insurance Group, Inc. shall have no liability or responsibility to any person or entity with respect to any loss, action or inaction alleged to be caused directly or indirectly as a result of the information contained herein.

