

Cooper Tire & Rubber Company is Recalling Certain Roadmaster RM852 EM Tires

National Highway Traffic Safety Commission NHTSA

Name of Product: Roadmaster RM852 EM/295/75R22.5 Tires

NHTSA Campaign Number: 19T006000 Manufacturer: Cooper Tire & Rubber Co. Potential Number of Units Affected: 4,045

Recall Date: August 30, 2019

Recall #: 173

Production Dates: 11/18/2018 - 12/08/2018

DOT Date Codes: 4618 through 4818

Hazard: A sidewall failure may cause the tire to rapidly deflate, increasing the risk of a crash.

Incidents/Injuries: No incidents or injuries were reported in this recall.

Remedy: Cooper Tire has notified owners, and dealers will inspect and, if necessary, replace the tires, free

of charge.

Recall Details: This recall involves certain Roadmaster RM852 EM tires, size 295/75R22.5, with DOT date

codes 4618 through 4818. The innerliner gauge may be too thin, allowing the tire sidewall to fail.

Consumer Contact: Owners may contact Cooper Tire customer service at 1-800-854-6288, or go to

www.safercar.gov.

Owners may also contact the National Highway Traffic Safety Administration (NHTSA) Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153).

https://www.nhtsa.gov/recalls?nhtsald=19T006000&refurl=rss

http://us.coopertire.com/for-owners/voluntary-recall-information



This material is intended to be a broad overview of the subject matter and is provided for informational purposes only. Old Republic Contractors Insurance Group, Inc. does not endorse or recommend any products or services nor does it make any representation or warranty regarding the accuracy or completeness of the information. Old Republic Contractors Insurance Group, Inc. shall have no liability or responsibility to any person or entity with respect to any loss, action or inaction alleged to be caused directly or indirectly as a result of the information contained herein.

