PETROLEUM PRODUCTION & REFINING



FACILITY:	APPLICATION PROBLEM:	SOLUTION:	SUCCESS SINCE:
Large Refinery	Waste Water	DFT® Model	9 Years of
in the	Treatment	Excalibur®	Maintenance free
Ohio Valley, USA	Water Hammer	Check Valve	Service

Challenge:

A large refinery in the Ohio Valley was experiencing severe water hammer with swing check valves installed in their waste water process treatment system.

The swing checks were installed in a pump discharge configuration with a long vertical pipe run after the valves. Operators said that when the swing check valves were installed, the ground would shake due to the severe water hammer caused by the valves cycling. The swing checks had repairs performed on them every year to replace the internals of the valves.

Solution:

The DFT® model Excalibur® was the solution to their problem. Two - 16" 150# WCB/SS Excaliburs were installed in 2004 and one was replaced in 2013, giving the company 9 years of maintenance free service. Operators at the refinery commented that when the Excaliburs cycled it made a click noise compared to the boom noise caused by the swing check valves cycling.

DFT® Model Excalibur® Features:

- 2" to 24" line size*
- ASME class 150 to 1500
- RF & RTJ flanged ends, butt weld ends
- ASME B16.10 face-to-face dimensions
- Stainless steel trim
- · Center-guided/dual-guided
- Spring assisted silent closing, non-slam
- Tight shutoff lapped disc & seat
- Two-piece body




· Horizontal or vertical installation

*For larger sizes, contact DFT

Tel: 610.363.8903

hen the Excaliburs cycled it made a click noise, compared to the boom noise caused by the swing check valves cycling."

Shown below is the design layout: The Excalibur is installed in a horizontal position on the discharge side of a pump with a 200 foot horizontal pipe run after the Excalibur feeding into a process pond.



Contact DFT for a solution to your problem.



www.dft-valves.com

Fax: 610.524.9242 Toll Free: 1.800.206.4013

email: dft@dft-valves.com