

THIS BULLETIN IS FAA APPROVED FOR ENGINEERING DESIGN

SERVICE BULLETIN M20-242
DATE: 2-17-89

SUBJECT: PORSCHE POWERED MOONEY M20L AIRCRAFT, INSPECTION OF STARTER
MOUNTING FLANGE AND INSPECTION OF UPPER FORWARD ENGINE MOUNT
FLANGE PER PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, dated 12-15-88

MODEL/S/N
AFFECTED: M20L, MOONEY PFM, S/N 26-0001 THRU 26-0041

TIME OF
COMPLIANCE: SEE PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, DATED 12-15-88.

INTRODUCTION: SEE PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, DATED 12-15-88.

INSTRUCTIONS: SEE PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, DATED 12-15-88.

WARRANTY: SEE PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, DATED 12-15-88.

REFERENCE
DATA: SEE PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, DATED 12-15-88.

PARTS LIST: SEE PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, DATED 12-15-88.

FIGURES/
TABLES: SEE PORSCHE PFM 3200 SERVICE BULLETIN No. N/300-026, DATED 12-15-88.

NOTE

To obtain referenced Service Bulletin, contact either of the following addresses:

1) EUROPE, AUSTRALIA, ASIA & AFRICA

2) NORTH & SOUTH AMERICA

DR. ING.h.c.f. Porsche
Aktiengesellschaft
Abt. VF
Porschestrasse 15-19
Postfach 1108
D-7140 Ludwigsburg
Telefon: 07141/39-8396 oder 8398
Telefax: 07141/39-8330
Telex: 7 264 761

Porsche Aviation Products, Inc.
1600 Holcomb Avenue
Attn: Gary Butcher
(702) 329-3937
Fax: (702) 329-0426