



MOONEY

May 14, 2001

NOTICE TO RECIPIENTS OF MOONEY SERVICE BULLETINS M20-275 AND M20-276

Due to delays in the mailing of Mooney Service Bulletins M20-275 and M20-276, the warranty time periods detailed in each service bulletin have been extended as follows:

Service Bulletin M20-275 – Warranty period expires September 22, 2001

Service Bulletin M20-276 – Warranty period expires October 9, 2001

Mooney Technical Publications




FIGURE SB M20-275- 1




FIGURE SB M20-275- 2




FIGURE SB M20-275- 3




FIGURE SB M20-275- 4




FIGURE SB M20-275- 5




FIGURE SB M20-275- 6




FIGURE SB M20-275- 7