

MOONEY AIRCRAFT INC.

SERVICE LETTER 20-31

SERVICE BULLETIN M 20-31

DATE: 5-5-58

SUBJECT: Installation of Decal & Revision to Flight Manual

MODELS AFFECTED: For installation of Decal M20 & M20A Serial No. 1002 - 1225
For Rev. B. to Flight Manual M20 Serial No. 1002 - 1200

TIME OF COMPLIANCE: Immediately

ENCLOSURES: P/N 8214-20 Decal (For M20 & M20A Serial No. 1002 - 1225)
Revision B to M20 Flight Manual Pages as follows
(For M20 Serial No. 1002 - 1200)
1) Log of Revisions
2) Page 3

In order to comply with CAA requirements the enclosed placard (P/N 8214-20) must be installed on the instrument panel under the cabin heat control knob on the affected airplanes. Follow the instruction below.

- 1) Clean area under cabin heat control knob
- 2) Soak decal in water for about 30 sec. until tissue paper is loose and decal will slide on backing card
- 3) Hold backing card in position under knob and slide decal from card smoothing it out with fingers
- 4) Gently remove excess water with a blotter

All M20 Flight Manuals must be revised by replacement of old pages affected with the new pages inclosed. Please note that your flight manual should already include Revision A (changes made for cowl flap installation). If Revision A is needed it may be obtained from the Spare Parts Department. Mooney Aircraft Inc., Box 72, Kerrville, Texas. Please include airplane serial number with request.