

SERVICE BULLETIN M 20-32

MOONEY AIRCRAFT INC.  
KERRVILLE, TEXAS

SERVICE LETTER 20-32

DATE: 3-18-58  
SUBJECT: Trim Wheel Friction Lock  
MODELS AFFECTED: M-20 Serial Number ~~1002-1200~~

In order to overcome the tendency of the trim wheel to vibrate out of position, a spring loaded friction lock has been added to the trim drive assembly. This part may be installed on airplanes noted above. Order S. L. 20-33 Kit-Trim Wheel Friction Lock from the Spare Parts Department, Mooney Aircraft Inc., Box 72, Kerrville, Texas. Price \$5.52 including postage. Please include airplane serial number with request.