

MOONEY AIRCRAFT INC.

SERVICE LETTER 20-33

SERVICE BULLETIN #

DATE: 3-18-58

SUBJECT: Kit-Trim Wheel Friction Lock

MODELS AFFECTED: M20 Ser. No. 1002 - 1200

PARTS LIST:
8247
AN363-1032
AN960-10

The installation of this kit will eliminate the tendency of the trim wheel to vibrate out of position.

INSTRUCTIONS: (See Sketch Below)

- 1) Remove trim wheel and turn down in lathe just enough to smooth and true surface for contact with spring loaded ball.
- 2) Replace AN3 bolt & nut with enclosed parts.

