

Vehicle Information

Date:	September 21, 2018
Vehicle:	2014 Mercedes-Benz E Class Sedan 4D E550 AWD 4.6L V8
	Turbo
VIN:	WDDHF9BBXEA983426
Weight:	4,145

New Cars/Trucks Values

Powered by Chrome Data	Base	Options	Destination	Adjusted Value
Base MSRP	\$61,400	\$12,085	\$925	\$74,410
NADA New Vehicle Values				
Low	N/A	N/A	N/A	N/A
Average	N/A	N/A	N/A	N/A
High	N/A	N/A	N/A	N/A
Optional Equipment			Invoice	MSRP
3-SPOKE FLAT-BOTTOMED WOOD	LEATHER STEERING W	HEEL	\$549.00	\$590.00
Code: 314 BLACK ASH WOOD TRIM	\$0.00	\$0.00		
Code: 736			•	·
ELECTRONIC TRUNK CLOSER	\$521.00	\$560.00		
Code: 881			•	•
KEYLESS-GO			\$605.00	\$650.00
Code: 889			• • • • • • •	• • • • • • •
KEYLESS-GO PACKAGE	\$921.00	\$990.00		
-inc: KEYLESS-GO, Control Code, Hand	• • • • • • •	•		
LANE TRACKING PACKAGE			\$814.00	\$875.00
-inc: Lane Keeping Assist Package Coo 993	le, Blind Spot Assist, Lane Ke	eping Assist Code:		
LIGHTING PACKAGE			\$1395.00	\$1500.00
-inc: Adaptive Highbeam Assist, Full LE				
PARKTRONIC W/ACTIVE PARKING	\$902.00	\$970.00		
Code: 235			• · · · · · · ·	•
POWER TILT/SLIDING PANORAMA	\$1014.00	\$1090.00		
Code: 413			• • • • • • • • •	* (* * * * * * * *
PREMIUM 1 PACKAGE			\$4018.00	\$4320.00
-inc: Power Rear-Window Sunshade, C0 music register, Active Ventilated Front S SiriusXM Traffic and SiriusXM Weather Sound System, Dolby Digital 5.1 Code:	eats, Rear View Camera, SIR (w/6 month trial), harman/kardo	IUS Satellite Radio,		
SPLIT FOLDING REAR SEATS			\$409.00	\$440.00

Code: 287

NADA Used Car Guide assumes no responsibility or liability for any errors or omissions or any revisions or additions made by anyone on this report. NADA Used Car Guide and its logo are registered trademarks of National Automobile Dealers Association, used under license by J.D. Power and Associates. ©2018 J.D.Power and Associates

NADA		9/21/2018
Velues	NADA New Cars/Trucks	
Licensed to J.D. Power	Invoice	MSRP
STANDARD PAINT	\$0.00	\$0.00
Code: -PAINT		
COMFORT BOX	\$270.00	\$290.00
(PIO) Code: 137-0		
REAR TRUNKLID SPOILER	\$279.00	\$300.00
(PIO) Code: 104-0		
IRIDIUM SILVER METALLIC	\$670.00	\$720.00
Code: 775		
BLACK, LEATHER UPHOLSTERY	\$0.00	\$0.00
Code: 211		

Standard Equipment

ENTERTAINMENT

- 8 Speakers
- Audio Theft Deterrent
- Radio w/Seek-Scan, MP3 Player, Clock, Speed Compensated Volume Control, Steering Wheel Controls and Radio Data System ٠
- Radio: COMAND AM/FM/WB/In-Dash DVD/CD Player inc: indash memory card slot, auxiliary input jack, Bluetooth interface for hands free calling and central controller w/high-mounted ٠ display
- Regular Amplifier
- Window Grid Antenna

EXTERIOR

- Black Side Windows Trim and Black Front Windshield Trim
- Body-Colored Bodyside Moldings and Chrome Bodyside Insert •
- Body-Colored Front Bumper w/Body-Colored Rub Strip/Fascia Accent and Chrome Bumper Insert •
- Body Colored Power Heated Side Mirrors w/Driver Auto Dimming, Manual Folding and Turn Signal Indicator •
- Body-Colored Rear Bumper w/Body-Colored Rub Strip/Fascia Accent and Chrome Bumper Insert .
- Chrome Door Handles
- **Chrome Grille**
- **Clearcoat Paint** ٠
- **Compact Spare Tire Mounted Inside Under Cargo** ٠
- Express Open/Close Sliding And Tilting Glass 1st Row Sunroof w/Sunshade ٠
- ٠ Fixed Rear Window w/Defroster
- Fully Automatic Projector Beam Led Low Beam Daytime Running Headlamps w/Delay-Off .
- Galvanized Steel/Aluminum Panels •
- LED Brakelights
- **Light Tinted Glass** •
- Perimeter/Approach Lights
- Rain Detecting Variable Intermittent Wipers w/Heated Jets And Reservoir ٠
- Rear Fog Lamps .
- Steel Spare Wheel
- Tires: P245/40R18 AS ٠
- **Trunk Rear Cargo Access**
- Wheels: 18" AMG Twin 5-Spoke Alloy -inc: 8.5 x 18.0 front and 8.5 x 18.0 rear

INTERIOR

- 2 Seatback Storage Pockets
- 3 12V DC Power Outlets
- Air Filtration
- Analog Display ٠
- Ashtray
- Bench Front Facing Rear Seat Cargo Space Lights
- .
- Carpet Floor Trim and Carpet Trunk Lid/Rear Cargo Door Trim
- Cruise Control .
- Day-Night Auto-Dimming Rearview Mirror •
- **Delayed Accessory Power** •
- Driver And Passenger Heated-Cushion, Driver And Passenger Heated-Seatback .
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination, Driver And Passenger Auxiliary Mirror •
- **Driver Foot Rest** .
- Driver Seat •
- Dual Zone Front Automatic Air Conditioning
- Engine Immobilizer .
- Fade-To-Off Interior Lighting





- FOB Controls -inc: Trunk/Hatch/Tailgate, Windows and Sunroof/Convertible Roof
- Front And Rear Map Lights
- Front Center Armrest and Rear Center Armrest w/Storage
- Front Cigar Lighter(s)
- Front Cupholder
- Full Carpet Floor Covering inc: Carpet Front And Rear Floor Mats
- Full Cloth Headliner
- Full Floor Console w/Covered Storage, Mini Overhead Console and 3 12V DC Power Outlets
- Gauges inc: Speedometer, Odometer, Engine Coolant Temp, Tachometer, Trip Odometer and Trip Computer
- Homelink Garage Door Transmitter
- HVAC -inc: Underseat Ducts, Residual Heat Recirculation, Headliner/Pillar Ducts and Console Ducts
- Illuminated Locking Glove Box
- Instrument Panel Covered Bin, Driver / Passenger And Rear Door Bins
- Interior Trim inc: Genuine Wood/Metal-Look Instrument Panel Insert, Genuine Wood/Metal-Look Door Panel Insert, Genuine Wood/Metal-Look Console Insert and Chrome Interior Accents
- Leather Steering Wheel w/Auto Tilt-Away
- Leather Upholstery
- Leather/Metal-Look Gear Shift Knob
- Leatherette Door Trim Insert
- Outside Temp Gauge
- Passenger Seat
- Perimeter Alarm
- Power 1st Row Windows w/Front And Rear 1-Touch Up/Down
- Power Adjustable Front Seats inc: lumbar adjustment and 3-position memory
- Power Anti Whiplash Adjustable Front Head Restraints and Power Adjustable Rear Head Restraints
- Power Door Locks w/Autolock Feature
- Power Fuel Flap Locking Type
- Power Rear Windows
- Power Tilt/Telescoping Steering Column
- Rear Cupholder
- Rear HVAC w/Separate Controls
- Redundant Digital Speedometer
- Remote Keyless Entry w/Integrated Key Transmitter, 4 Door Curb/Courtesy, Illuminated Entry, Illuminated Ignition Switch and Panic Button
- Remote Releases Inc: Power Cargo Access and Keyfob Fuel
- Seats w/Leatherette Back Material
- Selective Service Internet Access
- Steering Wheel and Head Restraints
- Systems Monitor
- Tracker System
- Trip Computer
- Valet Function

MECHANICAL

- 100-Amp/Hr 850CCA Maintenance-Free Battery
- 180 Amp Alternator
- 2.47 Axle Ratio
- 21.1 Gal. Fuel Tank
- 4-Wheel Disc Brakes w/4-Wheel ABS, Front And Rear Vented Discs, Brake Assist and Hill Hold Control
- Dual Stainless Steel Exhaust w/Chrome Tailpipe Finisher
- Electric Power-Assist Speed-Sensing Steering
- Engine: 4.6L Bi-Turbo DOHC V8 Direct Injection
- Front And Rear Anti-Roll Bars
- Full-Time 4MATIC All-Wheel Drive
- Gas-Pressurized Shock Absorbers
- Multi-Link Rear Suspension w/Coil Springs
- Strut Front Suspension w/Coil Springs
- Transmission: Driver Adaptive 7 Speed Automatic inc: sport and economy shift modes and steering wheel shift paddles

SAFETY

- ABS And Driveline Traction Control
- Airbag Occupancy Sensor
- Curtain 1st And 2nd Row Airbags
- Driver Knee Airbag, Driver And Passenger Pelvic Airbag
- Dual Stage Driver And Passenger Front Airbags
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Electronic Stability Control (ESC)
- First Aid Kit
- mbrace2 Emergency Sos
- Outboard Front Lap And Shoulder Safety Belts -inc: Rear Center 3 Point, Height Adjusters and Pretensioners
- PRESAFE
- Rear Child Safety Locks
- Side Impact Beams
- Tire Specific Low Tire Pressure Warning

Vehicle Information

NADA Used Car Guide assumes no responsibility or liability for any errors or omissions or any revisions or additions made by anyone on this report. NADA Used Car Guide and its logo are registered trademarks of National Automobile Dealers Association, used under license by J.D. Power and Associates ©2018 J.D.Power and Associates



CRASH TEST RATING

US NHTSA CRASH TEST RESULTS:

Overall Rating: * * * *

Overall Frontal Barrier Crash Rating: * * * *

Overall Side Crash Rating: * * * * *

Side Barrier Rating: * * * * *

Combined Side Barrier and Pole Ratings: Front Seat Rating: ***** Rear Seat Rating: *****

Overall Rollover Rating: ***** Dynamic Test Result: No Tip Risk of Rollover: 9.9%

Note Regarding Driver Rating:

Male: Average sized adult male dummy in 35-MPH crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs. Female: Small-sized adult female dummy in 35-mph crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs.

Rollover Note: Dynamic (moving) test results (Tip or No Tip) and measured rollover-related properties determine vehicle's risk of rollover in single vehicle crash and its rollover rating. The Rollover Resistance Rating utilizes a "fishhook" maneuver which is a series of abrupt turns at varying speeds to see how "top-heavy" a vehicle is.

RECALL

US NHTSA CAMPAIGN ID: 15V792000

Mfg's Report Date: NOV 23, 2015

Component: FUEL SYSTEM, GASOLINE:DELIVERY

Potential Number Of Units Affected: 809

Summary:

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain model year 2014 E350 and E350 4Matic sedans manufactured June 4, 2014, to July 9, 2014. The affected vehicles were built with a fuel feed line that has a single flare fitting instead of a double flare fitting.

Consequence:

If the fuel feed line has the incorrect flare fitting, the connection between the fuel hose and the fuel feed line might develop a leak or may completely disconnect. Leaking fuel in the presence of an ignition source increases the risk of a fire and if the fuel feed line disconnects, the vehicle would stall, increasing the risk of a crash.

Remedy:

MBUSA will notify owners, and dealers will install the correct fuel line, free of charge. This recall began on January 11, 2016. Owners may contact Mercedes-Benz customer service at 1-800-367-6372.

Dates of Manufacture: JUN 03, 2014 to JUL 08, 2014

Manufacturer Recall Number: 2015110006 US NHTSA CAMPAIGN ID: 15V088000

Mfg's Report Date: FEB 12, 2015

Component: STRUCTURE:BODY:HOOD

Potential Number Of Units Affected: 147224

Summary:

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain model year 2013-2015 E350 Sedan, E350 4Matic Sedan, E350 4Matic Station Wagon, E400 Hybrid Sedan, CLS 550 CGI, and CLS550 4Matic, 2013-2014 E550 4Matic Sedan, 2013 E63 Sedan, E63 Station Wagon and CLS63, 2014-2015 CLS63 4Matic, E63 4Matic Sedan, E63 4Matic Sedan "S", and E63 4Matic Station Wagon, 2015 CLS60, 2015 E400 Sedan, E400 4Matic Sedan and CLS400 4Matic and 2014 CLS63 "S". The affected vehicles have a rubber seal at the back of the engine bay that may temporarily stick to the hood when it is opened and then may fall into the engine bay when the hood is closed.

Consequence:



If the rubber seal falls into the engine compartment, it may contact parts of the exhaust system, increasing the risk of a fire.

Remedy:

MBUSÁ will notify owners, and dealers will attach four additional retaining clips to the rubber seal, free of charge. The recall began March 6, 2015. Owners may contact MBUSA customer service at 1-201-573-5339. MBUSA's number for this recall is 2015020001.

Dates of Manufacture: JUL 01, 2012 to NOV 30, 2014

Manufacturer Recall Number: 2015020001 US NHTSA CAMPAIGN ID: 16V899000

Mfg's Report Date: DEC 13, 2016

Component: STEERING:ELECTRIC POWER ASSIST SYSTEM

Potential Number Of Units Affected: 70

Summary:

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain model year 2013-2015 SL550, 2013-2014 SL63 AMG, 2014-2016 E350, 2014 E350 Cabriolet, E350 Coupe, 2014-2015 S550, 2015 E350 Bluetec, 2015-2016 E400, 2016 E550 Coupe, and Maybach S600 vehicles manufactured August 23, 2012, to August 14, 2015. The affected vehicles use an electric power steering system that may have improperly soldered contacts inside the control unit, potentially resulting in the power steering system deactivating while driving.

Consequence:

If the control unit pins lose connection, there would be a loss of electric power steering assist, increasing the risk of a crash. The increase in pin contact resistance can also increase the risk of a fire, even while the vehicle is parked and ignition is off.

Remedy:

MBUSÁ will notify owners, and dealers will replace the electric power steering control unit, free of charge. The recall began October 13, 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture: AUG 22, 2012 to AUG 13, 2015 US NHTSA CAMPAIGN ID: 17V177000

Mfg's Report Date: MAR 13, 2017

Component: AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Potential Number Of Units Affected: 51

Summary:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2016 AMG GT-S, GLC300, CLA250 and GLE300d 4Matic vehicles, 2013 C250, E350 BlueTec and G63 AMG vehicles, 2008-2014 C300 vehicles, 2013-2014 C300 4Matic and ML350 4Matic vehicles, 2009 C350 vehicles, 2014 CLS550, E350 4Matic, E350 Coupe 4Matic, E350 Wagon 4Matic, GLK350 and SL550 vehicles, 2012 CLS550 4Matic vehicles, 2012-2016 E350 vehicles, 2016-2017 GL450 4Matic vehicles, 2012-2014 ML350 4Matic BlueTec vehicles, 2015 S550, S550 4Matic and C300 4Matic Sedan vehicles, 2015-2016 C300 Sedan vehicles, and 2017 SL63 AMG vehicles. Various control units on these vehicles may have been updated with incorrect software, potentially affecting the correct deployment of the air bags in the event of a crash.

Consequence:

If the air bags do not deploy as intended in the event of a crash, there would be an increased risk of injury in the event of a crash.

Remedy:

MBUSA will notify owners, and dealers will update software in the affected control units, free of charge. The recall began April 21, 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture: DEC 31, 2007 to DEC 31, 2016 US NHTSA CAMPAIGN ID: 17V627000

Mfg's Report Date: OCT 05, 2017

Component: AIR BAGS:FRONTAL

Potential Number Of Units Affected: 495290

Summary:

Mercedes-Benz USA, LLC. (MBUSA) is recalling these vehicles: 2014-2018 CLA250, CLA250, CLA250 4Matic, CLA45 AMG 4Matic, 2015-2018 GLA250, GLA250 4Matic, GLA45 AMG 4Matic, C300



4Matic, C63S AMG, 2012-2014 C250, C350, C300 4Matic, E550 4Matic, 2013-2014 C63 AMG, 2012-2015 C250 Coupe, C350 Coupe, C63 AMG Coupe, 2013-2015 C350 4Matic Coupe, GLK250 4Matic BlueTec, GLK350, GLK350 4Matic, 2016-2017 C350e, C43 AMG, 2015 C400 4Matic, 2016-2018 C63 AMG, GLC300, GLC300, 4Matic, 2017-2018 C300 Coupe, C300 4Matic Coupe, C43 AMG, C63 AMG Coupe, C63S AMG Coupe, C300 Cabriolet, C300 4Matic Cabriolet, C43 AMG Cabriolet, C63 AMG Cabriolet, GLC300 4Matic Coupe, GLC43 AMG, GLC43 AMG Coupe, 2014 E350 Coupe, E350 4Matic Coupe, E350 Cabriolet, E400 Hybrid, 2015-2017 E400 Coupe, E400 4Matic Coupe, E400 Cabriolet, 2014-2017 E550 Coupe, E550 Cabriolet, B250e, 2014-2016 E250 BlueTec, E63 AMG 4Matic Wagon, 2012-2013 E350 BlueTec, 2012-2016 E350, E350 4Matic, 2015-2016 E400, E400 4Matic, 2012 E63 AMG, 2014-2015 E250 4Matic BlueTec, 2013-2016 E350 Wagon, 2017 GLC300d 4Matic, and 2018 GLC350e 4Matic. The driver's air bag may unexpectedly deploy due to insufficient grounding of the steering components if an electrostatic discharge occurs and the air bag clockspring is broken.

Consequence:

If the driver air bag inadvertently deploys, it can increase the risk of injury and a crash.

Remedy:

MBUSA will notify owners, and dealers will add sufficient grounding to the steering components, free of charge. The recall began in December 6, 2017. Owners may contact MBUSA customer service at 1-877-496-3691.

Manufacturer Recall Number: 2017110011 US NHTSA CAMPAIGN ID: 14V762000

Mfg's Report Date: NOV 30, 2014

Component: ENGINE AND ENGINE COOLING:ENGINE:DIESEL

Potential Number Of Units Affected: 4871

Summary:

Mercedes-Benz USA, LLC (Mercedes) is recalling certain model year 2014-2015 E250 BlueTec, E250 BlueTec 4Matic, GLK250 4Matic BlueTec, and 2015 ML250 4Matic BlueTec vehicles manufactured February 28, 2014, to November 10, 2014. In the affected vehicles, oil may leak from around the chain tensioner gasket area.

Consequence:

Leaking oil may drip onto a hot engine surface, increasing the risk of a fire. Additionally, the leaking oil may be a road hazard for other vehicles, increasing the risk of a crash.

Remedy:

Mercedes will notify owners, and dealers will replace the chain tensioner gasket, free of charge. The recall began on December 19, 2014. Owners may contact Mercedes customer service at 1-800-367-6372. Mercedes' number for this recall is 2014120002.

Dates of Manufacture: FEB 27, 2014 to NOV 09, 2014

Manufacturer Recall Number: 2014120002

WARRANTY

Basic: 4 Years/50,000 Miles

Drivetrain: 4 Years/50,000 Miles

Corrosion: 4 Years/50,000 Miles

Roadside Assistance: 4 Years/50,000 Miles

Technical Specifications

Brakes

- Brake ABS System (Second Line) N/A
- Brake ABS System 4-Wheel
- Brake Type 4-Wheel Disc
 Disc Front (Yes or) Yes
- Disc Front (Yes or) Yes
 Disc Rear (Yes or) Yes
- DISC Rear (Yes or) Y
 Drum Deer (Yes er)
- Drum Rear (Yes or)
- Front Brake Rotor Diam x Thickness 14.2in
- Rear Brake Rotor Diam x Thickness 12.6in
- Rear Drum Diam x Width in

Cargo Area Dimensions



Trunk Volume 15.9ftÅ³

Cooling System

Total Cooling System Capacity N/Aqts

Electrical

- Cold Cranking Amps @ 0° F (Primary) 850
- Maximum Alternator Capacity (amps) 180

Emissions

- EPA Greenhouse Gas Score N/A
- Tons/yr of CO2 Emissions @ 15K mi/year N/A

Engine

- Displacement 4.7 L/285
- Engine Order Code
- Engine Type Twin Turbo Premium Unleaded V-8
- Fuel System Gasoline Direct Injection
- SAE Net Horsepower @ RPM 402 @ 5000 .
- SAE Net Torque @ RPM 443 @ 1600

Exterior Dimensions

- Height, Overall 57.9in
- Length, Overall 192.1in
- Liftover Height N/Ain
- Min Ground Clearance N/Ain .
- Track Width, Front 63in Track Width, Rear 63.7in
- ٠
- Wheelbase 113.2in
- Width, Max w/o mirrors 73in

Fuel Tank

- Aux Fuel Tank Capacity, Approx N/Agal
- Fuel Tank Capacity, Approx 21.1gal

Interior Dimensions

- Front Head Room 37.9in
- Front Hip Room N/Ain
- Front Leg Room 41.3in •
- Front Shoulder Room 57.8in
- Passenger Capacity 5
- Passenger Volume N/AftÂ³
- Second Head Room 38.2in ٠
- Second Hip Room N/Ain .
- Second Leg Room 35.8in ٠
- Second Shoulder Room 56.9in

Mileage

- Battery Range N/Ami
- Cruising Range City N/Ami
- Cruising Range Hwy N/Ami .
- EPA Fuel Economy Est City N/AMPG ٠
- EPA Fuel Economy Est Hwy N/AMPG
- EPA MPG Equivalent City N/A •
- EPA MPG Equivalent Combined N/A
- EPA MPG Equivalent Hwy N/A • Fuel Economy Est Combined N/AMPG

Steering

- Lock to Lock Turns (Steering) N/A
- Steering Ratio (:1), Overall N/A .
- **Steering Type Rack-Pinion** •
- Turning Diameter Curb to Curb 36.9ft ٠
- Turning Diameter Wall to Wall N/Aft



Suspension

- Shock Absorber Diameter Front N/Amm ٠
- Shock Absorber Diameter Rear N/Amm .
- Stabilizer Bar Diameter Front N/Ain .
- Stabilizer Bar Diameter Rear N/Ain .
- Suspension Type Front (Cont.) Strut ٠
- ٠ Suspension Type - Front Strut
- Suspension Type Rear (Cont.) Multi-Link Suspension Type Rear Multi-Link ٠
- ٠

Tires

- Front Tire Order Code
- Front Tire Size P245/40HR18
- Rear Tire Order Code ٠
- Rear Tire Size P245/40HR18
- Spare Tire Order Code
- Spare Tire Size Compact

Trailering

- Dead Weight Hitch Max Tongue Wt. N/Albs
- Dead Weight Hitch Max Trailer Wt. N/Albs ٠
- Wt Distributing Hitch - Max Tongue Wt. N/Albs
- Wt Distributing Hitch Max Trailer Wt. N/Albs

Transmission

- Clutch Size N/Ain
- Drivetrain All Wheel Drive
- Fifth Gear Ratio (:1) 1.00 ٠
- Final Drive Axle Ratio (:1) 2.47 ٠
- First Gear Ratio (:1) 4.38
- Fourth Gear Ratio (:1) 1.37
- Reverse Ratio (:1) 3.42 •
- Second Gear Ratio (:1) 2.86
- Seventh Gear Ratio (:1) 0.73 .
- Sixth Gear Ratio (:1) 0.82
- Third Gear Ratio (:1) 1.92 •
- Trans Description Cont. Again ٠
- Trans Description Cont. Automatic w/OD ٠
- **Trans Order Code** ٠
- Trans Type 7

Vehicle

• EPA Classification Mid-Size Cars

Weight Information

• Base Curb Weight 4145lbs

Wheels

- Front Wheel Material Aluminum
- Front Wheel Size 18 X 8.5in
- **Rear Wheel Material Aluminum** .
- Rear Wheel Size 18 X 8.5in
- **Spare Wheel Material Steel** •
- Spare Wheel Size Compactin