



Vehicle Information

Date: September 28, 2018
Vehicle: 2015 Mercedes-Benz C Class Sedan 4D C300 AWD 2.0L I4 Turbo
VIN: 55SWF4KB6FU086339
Weight: 3,594

New Cars/Trucks Values

Powered by Chrome Data	Base	Options	Destination	Adjusted Value
Base MSRP	\$40,400	\$8,790	\$925	\$50,115

NADA New Vehicle Values

Low	N/A	N/A	N/A	N/A
Average	N/A	N/A	N/A	N/A
High	N/A	N/A	N/A	N/A

Optional Equipment

	Invoice	MSRP
BLIND SPOT ASSIST Code: 234	\$512.00	\$550.00
BURL WALNUT WOOD TRIM Code: 731-A	\$302.00	\$325.00
HEATED FRONT SEATS Code: 873	\$539.00	\$580.00
KEYLESS GO Code: 889	\$512.00	\$550.00
MULTIMEDIA PACKAGE -inc: COMAND Navigation & Voice Control, 8.4" high-resolution color screen, SiriusXM Traffic and Weather Services, Rear View Camera, Navigation Map Updates Included For 3 Years Code: 320	\$2502.00	\$2690.00
PANORAMA SUNROOF Code: 413	\$1376.00	\$1480.00
PREMIUM 1 PACKAGE -inc: KEYLESS GO, SiriusXM Satellite Radio, LED Headlamps, LED Taillights, Burmester Premium Sound Code: P01	\$1972.00	\$2120.00
REAR VIEW CAMERA Code: 218-A	\$428.00	\$460.00
SIRIUSXM SATELLITE RADIO Code: 536	\$428.00	\$460.00
LUXURY PACKAGE -inc: comfort suspension, Burl Walnut or Linden wood trim, 17" multi-spoke wheel, luxury grille w/"standing star" and dash w/MB-TEX and top-stitching Code: 167-0	\$302.00	\$325.00
STANDARD PAINT Code: -PAINT	\$0.00	\$0.00



	Invoice	MSRP
LUNAR BLUE METALLIC	\$670.00	\$720.00
Code: 890		
BEIGE/ESPRESSO, MB-TEX UPHOLSTERY	\$0.00	\$0.00
Code: 105-0		

Standard Equipment

ENTERTAINMENT

- 8 Speakers
- Audio Theft Deterrent
- Bluetooth Wireless Phone Connectivity
- Radio w/Clock and Steering Wheel Controls
- Radio: HD AM/FM Single Disc CD/MP3 -inc: Media Interface 7" Color Display Touchpad, USB connectivity, Bluetooth audio streaming, weatherband, sound system and auxiliary input
- Window Grid Antenna

EXTERIOR

- 7" Wheels w/Silver Accents
- Body-Colored Door Handles
- Body-Colored Front Bumper w/Chrome Bumper Insert
- Body-Colored Power Heated Side Mirrors w/Driver Auto Dimming, Power Folding and Turn Signal Indicator
- Body-Colored Rear Bumper w/Black Rub Strip/Fascia Accent and Chrome Bumper Insert
- Chrome Bodyside Moldings
- Chrome Grille
- Chrome Side Windows Trim and Black Front Windshield Trim
- Clearcoat Paint
- Fixed Rear Window w/Defroster
- Fully Automatic Projector Beam Halogen Daytime Running Headlamps w/Delay-Off
- Galvanized Steel/Aluminum Panels
- LED Brakelights
- Light Tinted Glass
- Perimeter/Approach Lights
- Rain Detecting Variable Intermittent Wipers w/Heated Jets And Reservoir
- Rear Fog Lamps
- Tires: 225/45R17 Fr & 245/40R17 Rr All-Season
- Trunk Rear Cargo Access
- Wheels: 17" Multi-Spoke

INTERIOR

- 2 12V DC Power Outlets
- 2 Seatback Storage Pockets
- 40-20-40 Folding Bench Front Facing Fold Forward Seatback Rear Seat
- Air Filtration
- Analog Display
- Ashtray
- Cargo Space Lights
- Carpet Floor Trim and Carpet Trunk Lid/Rear Cargo Door Trim
- Compass
- Cruise Control
- Day-Night Auto-Dimming Rearview Mirror
- Delayed Accessory Power
- Driver / Passenger And Rear Door Bins
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- Driver Foot Rest
- Driver Seat
- Dual Zone Front Automatic Air Conditioning
- Engine Immobilizer
- Fade-To-Off Interior Lighting
- FOB Controls -inc: Trunk/Hatch/Tailgate and Windows
- Front And Rear Map Lights
- Front Bucket Seats -inc: 8-way power front seats w/lumbar support
- Front Center Armrest and Rear Center Armrest w/Storage
- Front Cigar Lighter(s)
- Front Cupholder
- Full Carpet Floor Covering -inc: Carpet Front And Rear Floor Mats
- Full Cloth Headliner
- Full Floor Console w/Covered Storage, Mini Overhead Console and 2 12V DC Power Outlets
- Gauges -inc: Speedometer, Odometer, Engine Coolant Temp, Tachometer, Trip Odometer and Trip Computer
- Homelink Garage Door Transmitter
- HVAC -inc: Underseat Ducts and Console Ducts



- Illuminated Locking Glove Box
- Interior Trim -inc: Aluminum Instrument Panel Insert, Genuine Wood/Meta-look Door Panel Insert, Genuine Wood Console Insert, Meta-look Interior Accents and Mb-Tex Leatherette Upholstered Dashboard
- Leather Steering Wheel w/Auto Tilt-Away
- Mb-Tex Leatherette Door Trim Insert
- MB-Tex Upholstery
- Memory Settings -inc: Driver Seat, Door Mirrors, Steering Wheel and Head Restraints
- Outside Temp Gauge
- Passenger Seat
- Perimeter Alarm
- Power (driver Only) Anti-Whiplash Adjustable Front Head Restraints and Manual Adjustable Rear Head Restraints
- Power 1st Row Windows w/Front And Rear 1-Touch Up/Down
- Power Door Locks w/Autolock Feature
- Power Fuel Flap Locking Type
- Power Rear Windows
- Power Tilt/Telescoping Steering Column
- Proximity Key For Push Button Start Only
- Rear Cupholder
- Redundant Digital Speedometer
- Remote Keyless Entry w/Integrated Key Transmitter, 4 Door Curb/Courtesy, Illuminated Entry and Panic Button
- Remote Releases -inc: Power Cargo Access
- Seats w/Leatherette Back Material
- Send2Benz Selective Service Internet Access
- Smart Device Integration
- Systems Monitor
- Tracker System
- Trip Computer
- Urethane Gear Shift Knob
- Valet Function

MECHANICAL

- 150 Amp Alternator
- 18 Gal. Fuel Tank
- 3.07 Axle Ratio
- 4-Wheel Disc Brakes w/4-Wheel ABS, Front And Rear Vented Discs, Brake Assist, Hill Hold Control and Electric Parking Brake
- 74-Amp/Hr Maintenance-Free Battery
- Automatic w/Driver Control Ride Control Comfort Ride Suspension
- Dual Stainless Steel Exhaust w/Chrome Tailpipe Finisher
- Electric Power-Assist Speed-Sensing Steering
- Engine: 2.0L Turbo I4 Includes ECO stop/start technology. FFV option is not available in all states, please consult your retail dealer and/or MBUSA to determine availability in your state.
- Front And Rear Anti-Roll Bars
- Full-Time 4MATIC All-Wheel Drive
- Gas-Pressurized Shock Absorbers
- Multi-Link Rear Suspension w/Coil Springs
- Strut Front Suspension w/Coil Springs
- Transmission: 7-Speed Automatic 7G-TRONIC Plus

SAFETY

- ABS And Driveline Traction Control
- Airbag Occupancy Sensor
- BabySmart Childseat Sensor and Rear Child Safety Locks
- Collision Prevention Assist Plus
- Curtain 1st And 2nd Row Airbags
- Driver Knee Airbag, Driver And Passenger Pelvic Airbag
- Dual Stage Driver And Passenger Front Airbags
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Electronic Stability Control (ESC)
- First Aid Kit
- mbrace2 Emergency Sos
- Outboard Front Lap And Shoulder Safety Belts -inc: Rear Center 3 Point, Height Adjusters and Pretensioners
- Side Impact Beams
- Tire Specific Low Tire Pressure Warning

Vehicle Information

CRASH TEST RATING

US NHTSA CRASH TEST RESULTS:

Overall Rating: ****

Overall Frontal Barrier Crash Rating: ****



Overall Side Crash Rating: *****

Side Barrier Rating: *****

Combined Side Barrier and Pole Ratings:

Front Seat Rating: ***** Rear Seat Rating: *****

Overall Rollover Rating: *****

Dynamic Test Result: No Tip

Risk of Rollover: 11%

Note Regarding Driver Rating:

Male: Average sized adult male dummy in 35-MPH crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs. Female: Small-sized adult female dummy in 35-mph crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs.

Rollover Note: Dynamic (moving) test results (Tip or No Tip) and measured rollover-related properties determine vehicle's risk of rollover in single vehicle crash and its rollover rating. The Rollover Resistance Rating utilizes a "fishhook" maneuver which is a series of abrupt turns at varying speeds to see how "top-heavy" a vehicle is.

RECALL

US NHTSA CAMPAIGN ID:
17V627000

Mfg's Report Date:
OCT 05, 2017

Component:
AIR BAGS:FRONTAL

Potential Number Of Units Affected:
495290

Summary:

Mercedes-Benz USA, LLC. (MBUSA) is recalling these vehicles: 2014-2018 CLA250, CLA250 4Matic, CLA45 AMG 4Matic, 2015-2018 GLA250, GLA250 4Matic, GLA45 AMG 4Matic, C300 4Matic, C63S AMG, 2012-2014 C250, C350, C300 4Matic, E550 4Matic, 2013-2014 C63 AMG, 2012-2015 C250 Coupe, C350 Coupe, C63 AMG Coupe, 2013-2015 C350 4Matic Coupe, GLK250 4Matic BlueTec, GLK350, GLK350 4Matic, 2016-2017 C350e, C43 AMG, 2015 C400 4Matic, 2016-2018 C63 AMG, GLC300, GLC300 4Matic, 2017-2018 C300 Coupe, C300 4Matic Coupe, C43 AMG, C63 AMG Coupe, C63S AMG Coupe, C300 Cabriolet, C300 4Matic Cabriolet, C43 AMG Cabriolet, C63 AMG Cabriolet, C63S AMG Cabriolet, GLC300 4Matic Coupe, GLC43 AMG, GLC43 AMG Coupe, 2014 E350 Coupe, E350 4Matic Coupe, E350 Cabriolet, E400 Hybrid, 2015-2017 E400 Coupe, E400 4Matic Coupe, E400 Cabriolet, 2014-2017 E550 Coupe, E550 Cabriolet, B250e, 2014-2016 E250 BlueTec, E63 AMG 4Matic Wagon, 2012-2013 E350 BlueTec, 2012-2016 E350, E350 4Matic, 2015-2016 E400, E400 4Matic, 2012 E63 AMG, 2014-2015 E250 4Matic BlueTec, 2013-2016 E350 Wagon, 2017 GLC300d 4Matic, and 2018 GLC350e 4Matic. The driver's air bag may unexpectedly deploy due to insufficient grounding of the steering components if an electrostatic discharge occurs and the air bag clockspring is broken.

Consequence:

If the driver air bag inadvertently deploys, it can increase the risk of injury and a crash.

Remedy:

MBUSA will notify owners, and dealers will add sufficient grounding to the steering components, free of charge. The recall began in December 6, 2017. Owners may contact MBUSA customer service at 1-877-496-3691.

Manufacturer Recall Number:
2017110011
US NHTSA CAMPAIGN ID:
14V598000

Mfg's Report Date:
SEP 25, 2014

Component:
STEERING

Potential Number Of Units Affected:
10509

Summary:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2015 C300 4Matic and C400 4Matic vehicles manufactured March 28, 2014, to September 18, 2014. If the steering coupling interlock mechanism is not locked in place, the sliding shaft, which is part of the steering column, could become disengaged from the steering coupling socket due to vibrations, steering thrust, or load feedback from the road surface.


Consequence:

If the sliding shaft becomes disengaged from the steering coupling socket, the driver may experience noises, steering backlash, and in a worst case, loss of steering control, which may increase the risk of a crash.

Remedy:

MBUSA has notified owners, and dealers will inspect the steering coupling interlock mechanism to verify that it is in the locked position, free of charge. The recall began on October 1, 2014. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2014090008.

Dates of Manufacture:



MAR 27, 2014 to SEP 17, 2014

Manufacturer Recall Number:
2014090008
US NHTSA CAMPAIGN ID:
15V138000

Mfg's Report Date:
MAR 09, 2015

Component:
FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Potential Number Of Units Affected:
3039

Summary:
Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2015 C300 4matic and C400 4matic vehicles manufactured April 7, 2014, to July 25, 2014. In the affected vehicles, the fuel delivery module may be improperly secured to the fuel tank. Secondly, electrical wires that connect to the fuel delivery module might have been pinched between the flange of the fuel delivery module and the tank.

Consequence:
If the locking plate is not properly secured to the fuel delivery module it may become loose, and leak fuel, increasing the risk of a fire. If the electrical wires are pinched, the fuel pump may stop working, resulting in a stall, thereby increasing the risk of a crash.

Remedy:
MBUSA will notify owners, and dealers will inspect the vehicles for improperly secured locking plates and pinched wires, correcting the vehicles as necessary, free of charge. The recall began on April 24, 2015. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2015030004.

Dates of Manufacture:
APR 06, 2014 to JUL 24, 2014

Manufacturer Recall Number:
2015030004
US NHTSA CAMPAIGN ID:
15V845000

Mfg's Report Date:
DEC 15, 2015

Component:
STEERING:ELECTRIC POWER ASSIST SYSTEM

Potential Number Of Units Affected:
28452

Summary:
Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2015 C300 and C400 4matic sedans manufactured January 27, 2014, to December 1, 2014. Due to an error in the electric power steering control unit software, the affected vehicles may have a loss of electric power steering assist.

Consequence:
If the vehicle experiences a loss of power steering assist, extra steering effort will be required, especially at lower speeds, increasing the risk of a vehicle crash.

Remedy:
MBUSA will notify owners, and dealers will update the power steering software, free of charge. The recall began in January 15, 2016. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture:
JAN 26, 2014 to NOV 30, 2014

Manufacturer Recall Number:
2015120006
US NHTSA CAMPAIGN ID:
15V087000


Mfg's Report Date:
FEB 10, 2015

Component:
EXTERIOR LIGHTING:HEADLIGHTS

Potential Number Of Units Affected:
9137

Summary:
Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2015 C300 and C400 vehicles manufactured from June 18, 2014, through September 5, 2014, that fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment." The affected vehicles were assembled with horizontal adjustment mechanisms that allow the owner to change the horizontal adjustment used during the manufacturing process, instead of the proper sealing caps.

Consequence:



If the original horizontal adjustment is used to alter the low beam aim, the misaimed headlamp may not properly illuminate the road or cause increased glare to oncoming drivers, which increases the risk of a crash.

Remedy:
Mercedes-Benz will notify owners, and dealers will replace the horizontal adjustment mechanisms on the headlamps with sealing caps on the affected vehicles. The recall began May 23, 2016. Owners may contact Mercedes at 1-800-367-6372.

Dates of Manufacture:
JUN 17, 2014 to SEP 04, 2014

Manufacturer Recall Number:
2015020003
US NHTSA CAMPAIGN ID:
17V177000

Mfg's Report Date:
MAR 13, 2017

Component:
AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Potential Number Of Units Affected:
51

Summary:
Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2016 AMG GT-S, GLC300, CLA250 and GLE300d 4Matic vehicles, 2013 C250, E350 BlueTec and G63 AMG vehicles, 2008-2014 C300 vehicles, 2013-2014 C300 4Matic and ML350 4Matic vehicles, 2009 C350 vehicles, 2014 CLS550, E350 4Matic, E350 Coupe 4Matic, E350 Wagon 4Matic, GLK350 and SL550 vehicles, 2012 CLS550 4Matic vehicles, 2012-2016 E350 vehicles, 2016-2017 GL450 4Matic vehicles, 2012-2014 ML350 4Matic BlueTec vehicles, 2015 S550, S550 4Matic and C300 4Matic Sedan vehicles, 2015-2016 C300 Sedan vehicles, and 2017 SL63 AMG vehicles. Various control units on these vehicles may have been updated with incorrect software, potentially affecting the correct deployment of the air bags in the event of a crash.

Consequence:
If the air bags do not deploy as intended in the event of a crash, there would be an increased risk of injury in the event of a crash.

Remedy:
MBUSA will notify owners, and dealers will update software in the affected control units, free of charge. The recall began April 21, 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture:
DEC 31, 2007 to DEC 31, 2016
US NHTSA CAMPAIGN ID:
17V114000

Mfg's Report Date:
FEB 22, 2017

Component:
ENGINE AND ENGINE COOLING:ENGINE

Potential Number Of Units Affected:
307629

Summary:
Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2015-2017 C300 4Matic, C300, CLA250, CLA250 4Matic and CLA45 AMG vehicles, 2017 C300 4Matic Cabrio, C300 4Matic Coupe, C300 Cabrio, C300 Coupe, E300, E300 4Matic, E400 4Matic Wagon, E43 AMG 4Matic, GLA250, GLA250 4Matic and GLC300 4Matic Coupe vehicles and 2016 C350e and GLC300 vehicles and 2016-2017 C450 4Matic AMG Sport and GLC300 4Matic vehicles. In the event that the engine or transmission cannot turn over, the starting current limiter may overheat from the repeated attempts of the starter motor attempting to start the vehicle.

Consequence:
If the starting current limiter overheats, the surrounding components can melt, increasing the risk of a fire.

Remedy:
MBUSA will notify owners, and dealers will install an additional fuse in the electrical line to the starter, free of charge. Parts to remedy the vehicles are not currently available. Owners will be notified of the recall beginning in late March 2017. Owners will be mailed a follow up notice when remedy parts are available, currently expected to be in July 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture:
JAN 31, 2014 to JAN 31, 2017

Manufacturer Recall Number:
2017080002
US NHTSA CAMPAIGN ID:
17V654000

Mfg's Report Date:
OCT 15, 2017

Component:
POWER TRAIN:AXLE ASSEMBLY



Potential Number Of Units Affected:
2098

Summary:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2015-2016 C63 AMG, 2015-2017 C63S and 2017 C63S AMG Coupe and C63 AMG Cabrio vehicles. The rear axle differential mounting flange may fracture from repeated aggressive launches.

Consequence:

A fractured rear axle mounting flange can cause the rear differential to become misaligned, possibly resulting in failure of the driveshaft and a loss of propulsion, increasing the risk of a crash.

Remedy:

MBUSA will notify owners, and dealers will update the vehicle's stability system software and chassis control unit software, free of charge. The recall began on November 20, 2017. MBUSA's number for this recall is 2017110002. Owners may contact MBUSA customer service at 1-877-496-3691.

Dates of Manufacture:

NOV 03, 2014 to MAY 29, 2016

Manufacturer Recall Number:

2017110002

WARRANTY

Basic:

4 Years/50,000 Miles

Drivetrain:

4 Years/50,000 Miles

Corrosion:

4 Years/50,000 Miles

Roadside Assistance:

4 Years/50,000 Miles

Technical Specifications

Brakes

- Brake ABS System (Second Line) N/A
- Brake ABS System 4-Wheel
- Brake Type 4-Wheel Disc
- Disc - Front (Yes or) Yes
- Disc - Rear (Yes or) Yes
- Drum - Rear (Yes or)
- Front Brake Rotor Diam x Thickness 13in
- Rear Brake Rotor Diam x Thickness 11.8in
- Rear Drum Diam x Width in

Cargo Area Dimensions

- Trunk Volume 12.6ft³

Cooling System

- Total Cooling System Capacity N/Aqts

Electrical

- Cold Cranking Amps @ 0Â° F (Primary) N/A
- Maximum Alternator Capacity (amps) 150

Emissions

- EPA Greenhouse Gas Score 7.0 (Est)
- Tons/yr of CO₂ Emissions @ 15K mi/year N/A

Engine

- Displacement 2.0 L/121
- Engine Order Code
- Engine Type Intercooled Turbo Premium Unleaded I-4
- Fuel System Gasoline Direct Injection
- SAE Net Horsepower @ RPM 241 @ 5550



- SAE Net Torque @ RPM 273 @ 1300

Exterior Dimensions

- Height, Overall 56.8in
- Length, Overall 184.5in
- Liftover Height N/Ain
- Min Ground Clearance N/Ain
- Track Width, Front 61.6in
- Track Width, Rear 60.8in
- Wheelbase 111.8in
- Width, Max w/o mirrors 71.3in

Fuel Tank

- Aux Fuel Tank Capacity, Approx N/Agal
- Fuel Tank Capacity, Approx 18gal

Interior Dimensions

- Front Head Room 37.1in
- Front Hip Room N/Ain
- Front Leg Room 41.7in
- Front Shoulder Room N/Ain
- Passenger Capacity 5
- Passenger Volume N/Aft³
- Second Head Room 37.1in
- Second Hip Room N/Ain
- Second Leg Room 35.2in
- Second Shoulder Room N/Ain

Mileage

- Battery Range N/Ami
- Cruising Range - City N/Ami
- Cruising Range - Hwy N/Ami
- EPA Fuel Economy Est - City N/AMPG
- EPA Fuel Economy Est - Hwy N/AMPG
- EPA MPG Equivalent - City N/A
- EPA MPG Equivalent - Combined N/A
- EPA MPG Equivalent - Hwy N/A
- Fuel Economy Est-Combined N/AMPG

Steering

- Lock to Lock Turns (Steering) N/A
- Steering Ratio (:1), Overall N/A
- Steering Type Rack-Pinion
- Turning Diameter - Curb to Curb 36.8ft
- Turning Diameter - Wall to Wall N/Aft

Suspension

- Shock Absorber Diameter - Front N/Amm
- Shock Absorber Diameter - Rear N/Amm
- Stabilizer Bar Diameter - Front N/Ain
- Stabilizer Bar Diameter - Rear N/Ain
- Suspension Type - Front (Cont.) Strut
- Suspension Type - Front Strut
- Suspension Type - Rear (Cont.) Multi-Link
- Suspension Type - Rear Multi-Link

Tires

- Front Tire Order Code R02
- Front Tire Size P225/45HR17
- Rear Tire Order Code R02
- Rear Tire Size P245/40HR17
- Spare Tire Order Code
- Spare Tire Size

Trailer

- Dead Weight Hitch - Max Tongue Wt. N/Albs



- Dead Weight Hitch - Max Trailer Wt. N/A/lbs
- Wt Distributing Hitch - Max Tongue Wt. N/A/lbs
- Wt Distributing Hitch - Max Trailer Wt. N/A/lbs

Transmission

- Clutch Size N/A in
- Drivetrain All Wheel Drive
- Fifth Gear Ratio (:1) 1.00
- Final Drive Axle Ratio (:1) 3.07
- First Gear Ratio (:1) 4.38
- Fourth Gear Ratio (:1) 1.37
- Reverse Ratio (:1) 3.42
- Second Gear Ratio (:1) 2.86
- Seventh Gear Ratio (:1) 0.73
- Sixth Gear Ratio (:1) 0.82
- Third Gear Ratio (:1) 1.92
- Trans Description Cont. Again
- Trans Description Cont. Automatic w/OD
- Trans Order Code
- Trans Type 7

Vehicle

- EPA Classification Compact Cars

Weight Information

- Base Curb Weight 3594lbs

Wheels

- Front Wheel Material Aluminum
- Front Wheel Size 17in
- Rear Wheel Material Aluminum
- Rear Wheel Size 17in
- Spare Wheel Material
- Spare Wheel Size in