



Vehicle Information

Date: September 26, 2018
Vehicle: 2015 Hyundai Sonata Sedan 4D SE 2.4L I4
VIN: 5NPE24AFXFH180349
Weight: 3,252

New Cars/Trucks Values

Powered by Chrome Data	Base	Options	Destination	Adjusted Value
Base MSRP	\$21,150	\$1,245	\$825	\$23,220
NADA New Vehicle Values				
Low	N/A	N/A	N/A	N/A
Average	N/A	N/A	N/A	N/A
High	N/A	N/A	N/A	N/A

Optional Equipment

	Invoice	MSRP
FRONT BUCKET SEATS W/POWER DRIVER'S SEAT -inc: multi-adjustable bucket, seatback pockets and 8-way power driver's seat w/2-way power lumbar support, Code: -NONST	\$0.00	\$0.00
OPTION GROUP 09 -inc: Popular Equipment Package 09, leatherette interior door panel inserts, Automatic Headlight Control, Rearview Backup Camera, Front Bucket Seats w/Power Driver's Seat, multi-adjustable bucket, seatback pockets and 8-way power driver's seat w/2-way power lumbar support, Radio: AM/FM/SiriusXM/CD/MP3 w/Color Touchscreen, iPod/USB and auxiliary inputs, 6 speakers (2 front-door-mounted, 2 tweeters, and 2 rear) and 5-inch color touchscreen, Hyundai Blue Link Telematics System (GEN 1) Code: 09-0	\$1047.00	\$1150.00
RADIO: AM/FM/SIRIUSXM/CD/MP3 W/COLOR TOUCHSCREEN -inc: iPod/USB and auxiliary inputs, 6 speakers (2 front-door-mounted, 2 tweeters, and 2 rear) and 5-inch color touchscreen Code: -NONRD	\$0.00	\$0.00
OPTION GROUP 01 Code: 01-0	\$0.00	\$0.00
STANDARD PAINT Code: -PAINT	\$0.00	\$0.00
MUD GUARDS (PIO) Code: MG	\$76.00	\$95.00
QUARTZ WHITE PEARL Code: W8	\$0.00	\$0.00
GRAY, PREMIUM CLOTH SEATING SURFACES Code: GG-I	\$0.00	\$0.00

Standard Equipment

ENTERTAINMENT

- Bluetooth Wireless Phone Connectivity
- Radio w/Seek-Scan, Clock, Speed Compensated Volume Control, Steering Wheel Controls and Voice Activation



- Radio: AM/FM/SiriusXM/CD/MP3 Audio System -inc: iPod/USB and auxiliary inputs, and 6 speakers (2 front-door-mounted, 2 tweeters, and 2 rear)
- Window Grid And Roof Mount Antenna

EXTERIOR

- Auto Off Projector Beam Halogen Daytime Running Headlamps w/Delay-Off
- Body-Colored Door Handles
- Body-Colored Front Bumper
- Body-Colored Power w/Tilt Down Heated Side Mirrors w/Convex Spotter and Manual Folding
- Body-Colored Rear Bumper
- Chrome Side Windows Trim and Black Front Windshield Trim
- Clearcoat Paint
- Fixed Rear Window w/Defroster
- Front Windshield -inc: Sun Visor Strip
- Fully Galvanized Steel Panels
- Light Tinted Glass
- Lip Spoiler
- Metal-Look Grille
- Spare Tire Mobility Kit
- Speed Sensitive Variable Intermittent Wipers
- Tires: P205/65R16
- Trunk Rear Cargo Access
- Wheels: 16 x 6.5J Aluminum Alloy

INTERIOR

- 3 12V DC Power Outlets
- 60-40 Folding Bench Front Facing Fold Forward Seatback Rear Seat
- Air Filtration
- Analog Display
- Cargo Features -inc: Spare Tire Mobility Kit
- Cargo Space Lights
- Carpet Floor Trim and Carpet Trunk Lid/Rear Cargo Door Trim
- Cloth Door Trim Insert
- Cruise Control w/Steering Wheel Controls
- Day-Night Rearview Mirror
- Delayed Accessory Power
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- Driver Foot Rest
- Fade-To-Off Interior Lighting
- FOB Controls -inc: Trunk/Hatch/Tailgate
- Front And Rear Map Lights
- Front Bucket Seats -inc: multi-adjustable bucket, seatback pockets, impact reducing front seats and 6-way manual passenger seat (height adjustable)
- Front Center Armrest and Rear Center Armrest
- Front Cupholder
- Front Seats w/Manual Driver Lumbar
- Full Carpet Floor Covering
- Full Cloth Headliner
- Full Floor Console w/Covered Storage, Mini Overhead Console w/Storage and 3 12V DC Power Outlets
- Gauges -inc: Speedometer, Odometer, Engine Coolant Temp, Tachometer, Trip Odometer and Trip Computer
- HVAC -inc: Underseat Ducts
- Illuminated Locking Glove Box
- Instrument Panel Covered Bin, Driver / Passenger And Rear Door Bins
- Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert and Metal-Look Interior Accents
- Manual Air Conditioning
- Manual Anti-Whiplash Adjustable Front Head Restraints and Manual Adjustable Rear Head Restraints
- Manual Tilt/Telescoping Steering Column
- Outside Temp Gauge
- Perimeter Alarm
- Power 1st Row Windows w/Driver 1-Touch Up/Down
- Power Door Locks w/Autolock Feature
- Power Rear Windows
- Premium Cloth Seating Surfaces
- Rear Cupholder
- Redundant Digital Speedometer
- Remote Keyless Entry w/Integrated Key Transmitter, 2 Door Curb/Courtesy, Illuminated Entry, Illuminated Ignition Switch and Panic Button
- Remote Releases -inc: Power Cargo Access and Power Fuel
- Systems Monitor
- Trip Computer
- Urethane Gear Shift Knob
- Valet Function
- 4-Way Driver Seat -inc: Manual Lumbar Support
- 4-Way Passenger Seat

MECHANICAL

- 150 Amp Alternator



Licensed to J.D. Power

- 18.5 Gal. Fuel Tank
- 2.88 Axle Ratio
- 4497# Gvwr
- 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs, Brake Assist and Hill Hold Control
- 80-Amp/Hr 640CCA Maintenance-Free Battery w/Run Down Protection
- Electric Power-Assist Speed-Sensing Steering
- Engine: 2.4L GDI 4-Cylinder
- Front And Rear Anti-Roll Bars
- Front-Wheel Drive
- Gas-Pressurized Shock Absorbers
- Multi-Link Rear Suspension w/Coil Springs
- Single Stainless Steel Exhaust w/Chrome Tailpipe Finisher
- Strut Front Suspension w/Coil Springs
- Transmission w/Driver Selectable Mode
- Transmission: 6-Speed Automatic w/SHIFTRONIC-inc: OD lock-up torque converter, shift lock and SHIFTRONIC manual shift mode

SAFETY

- ABS And Driveline Traction Control
- Airbag Occupancy Sensor
- Curtain 1st And 2nd Row Airbags
- Driver Knee Airbag
- Dual Stage Driver And Passenger Front Airbags
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Electronic Stability Control (ESC)
- Outboard Front Lap And Shoulder Safety Belts-inc: Rear Center 3 Point, Height Adjusters and Pretensioners
- Rear Child Safety Locks
- Side Impact Beams
- Tire Specific Low Tire Pressure Warning

Vehicle Information

CRASH TEST RATING

US NHTSA CRASH TEST RESULTS:

Overall Rating: *****

Overall Frontal Barrier Crash Rating: *****

Overall Side Crash Rating: *****

Side Barrier Rating: *****

Combined Side Barrier and Pole Ratings:

Front Seat Rating: ***** Rear Seat Rating: *****

Overall Rollover Rating: *****

Dynamic Test Result: No Tip

Risk of Rollover: 10.5%

Note Regarding Driver Rating:

Male: Average sized adult male dummy in 35-MPH crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs. Female: Small-sized adult female dummy in 35-mph crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs.

Rollover Note: Dynamic (moving) test results (Tip or No Tip) and measured rollover-related properties determine vehicle's risk of rollover in single vehicle crash and its rollover rating. The Rollover Resistance Rating utilizes a "fishhook" maneuver which is a series of abrupt turns at varying speeds to see how "top-heavy" a vehicle is.

RECALL

US NHTSA CAMPAIGN ID:
14V368000

Mfg's Report Date:
JUN 23, 2014

Component:
SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:DISC:CALIPER

Potential Number Of Units Affected:
16900

Summary:

Hyundai Motor Company (Hyundai) is recalling certain model year 2015 Sonata vehicles manufactured April 25, 2014, through June 16, 2014. Due to a manufacturing error, one or both of the



front brake calipers may fracture.

Consequence:

If a brake caliper fractures, brake effectiveness would be reduced, lengthening to distance required to stop the vehicle, increasing the risk of a crash.

Remedy:

Hyundai contacted the affected owners on June 19, 2014 and instructed them not to drive their vehicles. Hyundai dealers will replace the affected brake calipers, free of charge. The recall began on September 12, 2014. Owners may contact Hyundai customer service at 1-800-633-5151. Hyundai's number for this recall is 120.

Dates of Manufacture:

APR 24, 2014 to JUN 15, 2014

Manufacturer Recall Number:

120

US NHTSA CAMPAIGN ID:

14V325000

Mfg's Report Date:

JUN 11, 2014

Component:

STEERING

Potential Number Of Units Affected:

2138

Summary:

Hyundai Motor Company (Hyundai) is recalling certain model year 2015 Sonata vehicles manufactured May 2, 2014, through May 23, 2014. A poor connection within the vehicle's wiring harness may result in a reduction of steering assist from the vehicle's motor driven power steering system or the inability to move the vehicle's shifter from the Park position.

Consequence:

The reduction of power steering assist can increase the steering effort needed, increasing the risk of a crash.

Remedy:

Hyundai notified dealers to suspend sales of affected Sonata vehicles and has published recall bulletin 14-01-024 providing a service procedure to repair the affected vehicles. On June 7, 2014 Hyundai began to contact the affected retail customers. Owners may contact Hyundai customer service at 1-800-633-5151. Hyundai's number for this recall is 119.

Dates of Manufacture:

MAY 01, 2014 to MAY 22, 2014

Manufacturer Recall Number:

119

US NHTSA CAMPAIGN ID:

14V784000

Mfg's Report Date:

DEC 08, 2014

Component:

POWER TRAIN:AXLE ASSEMBLY:AXLE SHAFT

Potential Number Of Units Affected:

208

Summary:

Hyundai Motor America (Hyundai) is recalling certain 1.6 liter model year 2015 Sonata vehicles manufactured August 29, 2014, to October 28, 2014. The affected vehicles may have been assembled with an incorrect left axle shaft which may result in the shaft separating from the transaxle differential.

Consequence:

If the left axle shaft separates from the transaxle, the vehicle may stop moving, increasing the risk of a crash. Additionally, a separated axle shaft may allow the vehicle to roll away as the driver and other occupants exit the vehicle or anytime thereafter. A vehicle rollaway increases the risk of injury to exiting occupants and bystanders.

Remedy:

Hyundai will notify owners, dealers will inspect and replace the axle shaft, as necessary, free of charge. Owners may contact Hyundai customer service at 1-800-633-5151. Hyundai's number for this recall is 126.

Dates of Manufacture:

AUG 28, 2014 to OCT 27, 2014

Manufacturer Recall Number:

126

US NHTSA CAMPAIGN ID:

15V414000

Mfg's Report Date:

JUN 29, 2015

Component:

SEAT BELTS:FRONT:BUCKLE ASSEMBLY



Potential Number Of Units Affected:
128804

Summary:

Hyundai Motor America (Hyundai) is recalling certain model year 2015 Sonata vehicles manufactured April 25, 2014, to December 4, 2014. The affected vehicles have a front passenger seat belt whose buckle latch assembly may prevent the front passenger from fastening the seat belt.

Consequence:

If the front passenger seat belt cannot be latched, an occupant sitting in the front passenger seat has an increased risk of injury in the event of a crash.

Remedy:

Hyundai will notify owners, and dealers will repair or replace the front passenger seat belt buckle, free of charge. The recall began on September 15, 2015. Owners may contact Hyundai customer service at 1-855-671-3059. Hyundai's number for this recall is 130.

Dates of Manufacture:

APR 24, 2014 to DEC 03, 2014

Manufacturer Recall Number:

130

US NHTSA CAMPAIGN ID:

15V678000

Mfg's Report Date:

OCT 19, 2015

Component:

ELECTRICAL SYSTEM: INSTRUMENT PANEL

Potential Number Of Units Affected:

64744

Summary:

Hyundai Motor America (Hyundai) is recalling certain model year 2015-2016 Sonata vehicles manufactured May 28, 2014, to August 21, 2015. The affected vehicles are equipped with an Antilock Braking System (ABS) warning light intended to warn the driver if there is an ABS malfunction. In the event of an ABS malfunction, the Brake System warning light will illuminate, but the ABS warning light will not illuminate. Since the vehicles have ABS malfunction lights that do not illuminate, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 135, "Light Vehicle Brake Systems."

Consequence:

If the driver is alerted there is a brake system malfunction, but not specifically with the ABS system, the driver may operate the vehicle unaware that the vehicle's brakes may lock up during hard braking, increasing the risk of a crash.

Remedy:

Hyundai will notify owners, and dealers will update the ABS control unit software, free of charge. The recall is expected began on November 30, 2015. Owners may contact Hyundai customer service at 1-855-671-3059. Hyundai's number for this recall is 134.

Dates of Manufacture:

MAY 27, 2014 to AUG 20, 2015

Manufacturer Recall Number:

134

US NHTSA CAMPAIGN ID:

16V232000

Mfg's Report Date:

APR 20, 2016

Component:

AIR BAGS:FRONTAL

Potential Number Of Units Affected:

33

Summary:

Hyundai Motor Company (Hyundai) is recalling certain model year 2015-2016 Sonata vehicles manufactured May 29, 2014 to February 11, 2016, 2017 Elantra vehicles manufactured January 12, 2016 to February 22, 2016, and one 2016 Sonata Hybrid vehicle manufactured October 15, 2015. In these vehicles, the driver's frontal air bag may be missing a chemical enhancer required for the second stage air bag deployment, resulting in the second stage not deploying in certain crashes. The primary stage will deploy as intended.

Consequence:

An air bag that does not inflate increases the risk of injury.

Remedy:

Hyundai will notify owners, and dealers will replace the driver's frontal air bag module, free of charge. The recall began on May 5, 2016. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 144.


Dates of Manufacture:

MAY 28, 2014 to FEB 10, 2016

Manufacturer Recall Number:

144

US NHTSA CAMPAIGN ID:



16V726000

Mfg's Report Date:
OCT 10, 2016

Component:
VISIBILITY:SUN ROOF ASSEMBLY

Potential Number Of Units Affected:
62811

Summary:
Hyundai Motor America (Hyundai) is recalling certain model year 2015-2016 Sonata Hybrid vehicles manufactured December 8, 2014, to August 18, 2015, and Hyundai Sonata vehicles manufactured May 28, 2014, to March 18, 2016, equipped with the panoramic sunroof option. Due to a bonding issue with the sunroof wind deflector, the sunroof panel on the affected vehicles may detach while driving.

Consequence:
If the sunroof detaches from the vehicle it could become a road hazard, increasing the risk of a crash.

Remedy:
Hyundai will notify owners, and dealers will repair the wind deflector anchor plate, free of charge. The recall began December 2016. Owners may contact Hyundai customer service at 1-800-633-5151. Hyundai's number for this recall is 152.

Dates of Manufacture:
MAY 27, 2014 to MAR 17, 2016

Manufacturer Recall Number:
152
US NHTSA CAMPAIGN ID:
17V359000

Mfg's Report Date:
JUN 04, 2017

Component:
PARKING BRAKE:INDICATOR LIGHT

Potential Number Of Units Affected:
161074

Summary:
Hyundai Motor America (Hyundai) is recalling certain 2015-2016 Sonata and Genesis vehicles. In the affected vehicles, the warning light to indicate that the parking brake is applied may intermittently not illuminate in the dash due to corrosion in the switch.

Consequence:
If the parking brake indicator is not illuminated when the parking brake is applied, the driver may operate the vehicle with the parking brake partially engaged, increasing the risk of a crash.

Remedy:
Hyundai will notify owners, and dealers will replace the parking brake switch, free of charge. The recall began on August 4, 2017. Owners may contact Hyundai customer service at 1-855-671-3059. Hyundai's number for this recall is 164.

Dates of Manufacture:
APR 24, 2014 to MAR 02, 2015

Manufacturer Recall Number:
164

WARRANTY

Basic:
5 Years/60,000 Miles

Drivetrain:
10 Years/100,000 Miles

Corrosion:
7 Years/Unlimited Miles

Roadside Assistance:
5 Years/Unlimited Miles

Technical Specifications

Brakes

- Brake ABS System (Second Line) N/A
- Brake ABS System 4-Wheel



Licensed to J.D. Power

- Brake Type N/A
- Disc - Front (Yes or) Yes
- Disc - Rear (Yes or) Yes
- Drum - Rear (Yes or)
- Front Brake Rotor Diam x Thickness 12in
- Rear Brake Rotor Diam x Thickness 11.2in
- Rear Drum Diam x Width in

Cargo Area Dimensions

- Trunk Volume 16.3ft³

Cooling System

- Total Cooling System Capacity N/Aqts

Electrical

- Cold Cranking Amps @ 0Å° F (Primary) 640
- Maximum Alternator Capacity (amps) 150

Emissions

- EPA Greenhouse Gas Score N/A
- Tons/yr of CO₂ Emissions @ 15K mi/year 6.1

Engine

- Displacement 2.4 L/144
- Engine Order Code
- Engine Type Regular Unleaded I-4
- Fuel System Gasoline Direct Injection
- SAE Net Horsepower @ RPM 185 @ 6000
- SAE Net Torque @ RPM 178 @ 4000

Exterior Dimensions

- Height, Overall 58.1in
- Length, Overall 191.1in
- Lifterover Height N/Ain
- Min Ground Clearance 5.3in
- Track Width, Front 63.5in
- Track Width, Rear 63.8in
- Wheelbase 110.4in
- Width, Max w/o mirrors 73.4in

Fuel Tank

- Aux Fuel Tank Capacity, Approx N/Agal
- Fuel Tank Capacity, Approx 18.5gal

Interior Dimensions

- Front Head Room 40.4in
- Front Hip Room 55.3in
- Front Leg Room 45.5in
- Front Shoulder Room 57.9in
- Passenger Capacity 5
- Passenger Volume 106.1ft³
- Second Head Room 38in
- Second Hip Room 56.1in
- Second Leg Room 35.6in
- Second Shoulder Room 56.5in

Mileage

- Battery Range N/Ami
- Cruising Range - City 462.50mi
- Cruising Range - Hwy 684.50mi
- EPA Fuel Economy Est - City 25MPG
- EPA Fuel Economy Est - Hwy 37MPG
- EPA MPG Equivalent - City N/A
- EPA MPG Equivalent - Combined N/A



Licensed to J.D. Power

- EPA MPG Equivalent - Hwy N/A
- Fuel Economy Est-Combined 29MPG

Steering

- Lock to Lock Turns (Steering) N/A
- Steering Ratio (:1), Overall N/A
- Steering Type Rack-Pinion
- Turning Diameter - Curb to Curb 35.8ft
- Turning Diameter - Wall to Wall N/Aft

Suspension

- Shock Absorber Diameter - Front N/Amm
- Shock Absorber Diameter - Rear N/Amm
- Stabilizer Bar Diameter - Front N/Ain
- Stabilizer Bar Diameter - Rear N/Ain
- Suspension Type - Front (Cont.) Strut
- Suspension Type - Front Strut
- Suspension Type - Rear (Cont.) Multi-Link
- Suspension Type - Rear Multi-Link

Tires

- Front Tire Order Code
- Front Tire Size P205/65HR16
- Rear Tire Order Code
- Rear Tire Size P205/65HR16
- Spare Tire Order Code
- Spare Tire Size

Trailer

- Dead Weight Hitch - Max Tongue Wt. N/Albs
- Dead Weight Hitch - Max Trailer Wt. N/Albs
- Wt Distributing Hitch - Max Tongue Wt. N/Albs
- Wt Distributing Hitch - Max Trailer Wt. N/Albs

Transmission

- Clutch Size N/Ain
- Drivetrain Front Wheel Drive
- Fifth Gear Ratio (:1) 1.00
- Final Drive Axle Ratio (:1) 2.88
- First Gear Ratio (:1) 4.21
- Fourth Gear Ratio (:1) 1.39
- Reverse Ratio (:1) 3.38
- Second Gear Ratio (:1) 2.64
- Sixth Gear Ratio (:1) 0.77
- Third Gear Ratio (:1) 1.80
- Trans Description Cont. Again
- Trans Description Cont. Automatic w/OD
- Trans Order Code
- Trans Type 6

Vehicle

- EPA Classification Large Cars

Weight Information

- Base Curb Weight 3252lbs

Wheels

- Front Wheel Material Aluminum
- Front Wheel Size 16 X 6.5in
- Rear Wheel Material Aluminum
- Rear Wheel Size 16 X 6.5in
- Spare Wheel Material
- Spare Wheel Size in