

Vehicle Information

Date: January 10, 2019
Vehicle: 2018 Volkswagen Tiguan Utility 4D SE AWD 2.0L I4 Turbo
VIN: 3VV2B7AX5JM106273
Weight: 3,858



New Cars/Trucks Values

Powered by Chrome Data	Base	Options	Destination	Adjusted Value
Base MSRP	\$28,050	N/A	\$995	\$29,045
NADA New Vehicle Values				
Low	\$23,952	N/A	\$995	\$24,947
Average	\$25,158	N/A	\$995	\$26,153
High	\$26,517	N/A	\$995	\$27,512

Optional Equipment

	Invoice	MSRP
STANDARD PAINT Code: -PAINT	\$0.00	\$0.00
PURE WHITE Code: 0Q0Q	\$0.00	\$0.00
STORM GRAY, PERFORATED V-TEX LEATHERETTE SEATING SURFACES Code: FV	\$0.00	\$0.00

Standard Equipment

ENTERTAINMENT

- 1 LCD Monitor In The Front
- Audio Theft Deterrent
- Radio w/Seek-Scan, MP3 Player, Clock, Speed Compensated Volume Control, Steering Wheel Controls, Voice Activation and Radio Data System
- Radio: AM/FM/HD/CD w/Dual USB & Aux-In-inc: Composition Media, 8" touchscreen, voice control, 6-speaker sound system, VW Car-Net App-Connect smartphone integration and interface (w/Apple CarPlay, Android Auto and MirrorLink), VW Car-Net Security and Service connected car service (limited subscription), Bluetooth connectivity and SiriusXM satellite radio (w/limited-time trial subscription)
- Streaming Audio
- Window Grid And Roof Mount Diversity Antenna

EXTERIOR

- Body-Colored Door Handles
- Body-Colored Front Bumper
- Body-Colored Power Heated Side Mirrors w/Manual Folding and Turn Signal Indicator
- Body-Colored Rear Bumper w/Black Rub Strip/Fascia Accent and Chrome Bumper Insert
- Chrome Bodyside Insert, Black Bodyside Cladding and Black Wheel Well Trim
- Chrome Grille
- Chrome Side Windows Trim and Black Front Windshield Trim
- Clearcoat Paint
- Compact Spare Tire Mounted Inside Under Cargo
- Deep Tinted Glass
- Fixed Rear Window w/Fixed Interval Wiper and Defroster



Licensed to J.D. Power

- Fully Automatic Aero-Composite Halogen Daytime Running Headlamps w/Delay-Off
- Fully Galvanized Steel Panels
- LED Brakelights
- Liftgate Rear Cargo Access
- Lip Spoiler
- Roof Rack Rails Only
- Steel Spare Wheel
- Tailgate/Rear Door Lock Included w/Power Door Locks
- Tires: 17" AS
- Variable Intermittent Wipers w/Heated Jets
- Wheels w/Silver Accents
- Wheels: 17" Tulsa Standard on SE when available-otherwise SE comes with 17" Montana wheel.

INTERIOR

- 2 Seatback Storage Pockets
- 3 12V DC Power Outlets
- 40-20-40 Folding Split-Bench Front Facing Manual Reclining Fold Forward Seatback Rear Seat w/Manual Fore/Aft
- 6-Way Passenger Seat
- 8-Way Driver Seat
- Air Filtration
- Analog Display
- Cargo Area Concealed Storage
- Cargo Space Lights
- Carpet Floor Trim
- Compass
- Cruise Control w/Steering Wheel Controls
- Day-Night Rearview Mirror
- Delayed Accessory Power
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination, Driver And Passenger Auxiliary Mirror
- Driver Foot Rest
- Dual Zone Front Automatic Air Conditioning
- Fade-To-Off Interior Lighting
- FOB Controls -inc: Trunk/Hatch/Tailgate
- Front And Rear Map Lights
- Front Center Armrest and Rear Center Armrest
- Front Cupholder
- Full Carpet Floor Covering -inc: Carpet Front And Rear Floor Mats
- Full Cloth Headliner
- Full Floor Console w/Covered Storage, Mini Overhead Console w/Storage and 3 12V DC Power Outlets
- Gauges -inc: Speedometer, Odometer, Engine Coolant Temp, Tachometer, Oil Temperature, Trip Odometer and Trip Computer
- Heated Front Bucket Seats -inc: 10-way power driver's seat w/power lumbar support and 6-way manual front passenger seat w/height adjustment
- HVAC -inc: Underseat Ducts and Console Ducts
- Illuminated Glove Box
- Instrument Panel Covered Bin, Dashboard Storage, Driver / Passenger And Rear Door Bins
- Interior Trim -inc: Metal-Look Instrument Panel Insert, Metal-Look Door Panel Insert and Metal-Look Interior Accents
- Leather/Metal-Look Gear Shift Knob
- Leather/Piano Black Steering Wheel
- Leatherette Door Trim Insert
- Manual Adjustable Front Head Restraints and Manual Adjustable Rear Head Restraints
- Manual Tilt/Telescoping Steering Column
- Outside Temp Gauge
- Perforated V-TEX Leatherette Seating Surfaces
- Power 1st Row Windows w/Front And Rear 1-Touch Up/Down
- Power Door Locks w/Autolock Feature
- Power Fuel Flap Locking Type
- Power Rear Windows and Fixed 3rd Row Windows
- Proximity Key For Doors And Push Button Start
- Rear Cupholder
- Redundant Digital Speedometer
- Remote Keyless Entry w/Integrated Key Transmitter, Illuminated Entry and Panic Button
- Seats w/Leatherette Back Material
- Systems Monitor
- Tracker System
- Trip Computer
- Vw Car-Net Selective Service Internet Access

MECHANICAL

- 15.9 Gal. Fuel Tank
- 3.33 Axle Ratio
- 4-Wheel Disc Brakes w/4-Wheel ABS, Front Vented Discs, Brake Assist, Hill Descent Control, Hill Hold Control and Electric Parking Brake
- 69-Amp/Hr 360CCA Maintenance-Free Battery w/Run Down Protection
- 970# Maximum Payload
- Electric Power-Assist Speed-Sensing Steering
- Engine Auto Stop-Start Feature
- Engine Oil Cooler
- Engine: 2.0L TSI DOHC Turbocharged 4-Cylinder -inc: 16-valve, direct injection



- Front And Rear Anti-Roll Bars
- Full-Time All-Wheel Drive
- Gas-Pressurized Shock Absorbers
- GVWR: 5,093 lbs (2,310 kgs)
- Multi-Link Rear Suspension w/Coil Springs
- Permanent Locking Hubs
- Quasi-Dual Stainless Steel Exhaust
- Strut Front Suspension w/Coil Springs
- Towing Equipment -inc: Trailer Sway Control
- Transmission: 8-Speed Automatic w/Tiptronic -inc: sport mode

SAFETY

- ABS And Driveline Traction Control
- Airbag Occupancy Sensor
- Back-Up Camera
- Blind Spot Monitor Blind Spot Sensor
- Dual Stage Driver And Passenger Front Airbags
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Electronic Stability Control (ESC)
- Front Assist w/Autonomous Emergency Braking
- Low Tire Pressure Warning
- Outboard Front Lap And Shoulder Safety Belts -inc: Rear Center 3 Point, Height Adjusters and Pretensioners
- Rear Child Safety Locks
- Side Curtain Protection Curtain 1st, 2nd And 3rd Row Airbags
- Side Impact Beams
- Vw Car-Net Emergency Socs

Vehicle Information

CRASH TEST RATING

US NHTSA CRASH TEST RESULTS:

Overall Rating: Not Rated

Overall Frontal Barrier Crash Rating: Not Rated

Frontal Crash Test Note: During two frontal crash tests of this vehicle, the driver's seat belt tore apart where it loops through the seat belt latch tongue. NHTSA is expanding its ongoing investigation to determine potential causes of this separation. For additional information, please click on the "Investigations" tab in the "Recalls & Safety Issues" section below.

Overall Side Crash Rating: Not Rated

Overall Rollover Rating: Not Rated

Risk of Rollover: Not Rated

Note Regarding Driver Rating:

Male: Average sized adult male dummy in 35-MPH crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs. Female: Small-sized adult female dummy in 35-mph crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs.

RECALL

US NHTSA CAMPAIGN ID:
18V159000

Mfg's Report Date:
MAR 07, 2018

Component:
ENGINE

Potential Number Of Units Affected:
4

Summary:
Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Tiguan long wheel base (LWB) vehicles. The engine support bolts on these vehicles may not have been properly tightened.

Consequence:
If the engine support bolts were not properly tightened, an unexpected engine breakdown or loss of engine power may occur, increasing the risk of a crash.

Remedy:
Volkswagen will notify owners, and dealers will replace engine support bolts, free of charge. The recall began March 26, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 10F7.



Dates of Manufacture:
MAY 07, 2017 to MAY 23, 2017

Manufacturer Recall Number:
10F7
US NHTSA CAMPAIGN ID:
17V662000

Mfg's Report Date:
OCT 17, 2017

Component:
EXTERIOR LIGHTING:TAIL LIGHTS

Potential Number Of Units Affected:
5509

Summary:
Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen Tiguan long wheel base (LWB) vehicles. The back-up lights in the taillight assemblies may not be bright enough. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence:
If the back-up lights are not bright enough, other drivers may not see the vehicle reversing, or the driver may back into an obstacle, increasing the risk of a crash.

Remedy:
Volkswagen will notify owners, and dealers will replace the affected inner taillight assemblies, free of charge. The recall began December 15, 2017. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 94J9.

Dates of Manufacture:
JUL 03, 2017 to AUG 18, 2017

Manufacturer Recall Number:
94J9
US NHTSA CAMPAIGN ID:
18V102000

Mfg's Report Date:
FEB 08, 2018

Component:
AIR BAGS:FRONTAL

Potential Number Of Units Affected:
3768

Summary:
Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2017-2018 Tiguan Limited vehicles. The front driver air bag installed on these vehicles may not be intended for use in vehicles sold in the United States. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

Consequence:
In the event of a crash, the incorrect air bags may not protect the driver as intended, increasing the risk of injury.

Remedy:
Volkswagen will notify owners, and dealers will replace the steering wheel and front driver air bag module, free of charge. The recall began May 30, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 69V2.

Dates of Manufacture:
MAY 23, 2017 to JAN 15, 2018

Manufacturer Recall Number:
69V2
US NHTSA CAMPAIGN ID:
18V324000

Mfg's Report Date:
MAY 15, 2018

Component:
SUSPENSION:FRONT:CONTROL ARM:LOWER BALL JOINT

Potential Number Of Units Affected:
2464

Summary:
Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen Tiguan and Tiguan long wheel base (LWB) vehicles. The nut that holds the lower ball joint of the front wheel on each side of the vehicle may be loose or improperly tightened.

Consequence:
A loose or improperly tightened ball joint nut can result in the separation of the lower ball joint causing steering, traction or other stability issues, increasing the risk of a crash.



Remedy:
Volkswagen has notified owners, and dealers will replace the nut on the lower ball joint and, as necessary, clean the thread in the ball joint, free of charge. The recall began May 30, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 40N4. Note: owners are advised not to drive their vehicle until the recall repair has been performed.

Dates of Manufacture:
JUL 30, 2017 to APR 02, 2018

Manufacturer Recall Number:
40N4/40N5
US NHTSA CAMPAIGN ID:
18V375000

Mfg's Report Date:
JUN 05, 2018

Component:
AIR BAGS:PASSENGER SIDE FRONTAL

Potential Number Of Units Affected:
821

Summary:
Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen Atlas and Tiguan vehicles. In the event of a crash, the passenger frontal air bag may tear or not properly unfold during deployment.

Consequence:
If the air bag were to tear or unfold incorrectly during deployment, it can increase the risk of injury.

Remedy:
Volkswagen will notify owners, and dealers will replace the passenger frontal air bag, free of charge. The recall began July 19, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's numbers for this recall are 69W8, and 69W9.

Dates of Manufacture:
MAR 09, 2018 to MAY 18, 2018

Manufacturer Recall Number:
69W8 69W9
US NHTSA CAMPAIGN ID:
18V262000

Mfg's Report Date:
APR 24, 2018

Component:
SUSPENSION:REAR:SHOCK ABSORBER

Potential Number Of Units Affected:
7430

Summary:
Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen Tiguan long wheelbase (LWB) vehicles. A lower loop of a rear shock absorber may separate from its base due to an incorrect welding process.

Consequence:
If the lower loop of the rear shock absorber detaches, there may be a loss of vehicle control, increasing the risk of a crash.

Remedy:
Volkswagen will notify owners, and dealers will inspect the rear shock absorbers, replacing them as necessary, free of charge. The recall began May 30, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 42I7.

Dates of Manufacture:
JAN 14, 2018 to MAR 09, 2018


Manufacturer Recall Number:
42I7
US NHTSA CAMPAIGN ID:
18V467000

Mfg's Report Date:
JUL 12, 2018

Component:
VISIBILITY:SUN ROOF ASSEMBLY

Potential Number Of Units Affected:
45457

Summary:



Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen Tiguan vehicles. The LED module for the panoramic sunroof ambient light bar may short circuit.

Consequence:

A short-circuit can increase the risk of a fire.

Remedy:

Volkswagen will notify owners, and dealers will disconnect the power supply for the panoramic sunroof LED module, free of charge, until a future service action can safely reactivate the feature. The recall began July 24, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall 60D1.

Dates of Manufacture:

DEC 07, 2016 to JUL 06, 2018

Manufacturer Recall Number:

60D1

WARRANTY

Basic:

6 Years/72,000 Miles

Drivetrain:

6 Years/72,000 Miles

Corrosion:

7 Years/100,000 Miles

Roadside Assistance:

3 Years/36,000 Miles

Technical Specifications

Brakes

- Brake ABS System (Second Line) N/A
- Brake ABS System 4-Wheel
- Brake Type 4-Wheel Disc
- Disc - Front (Yes or) Yes
- Disc - Rear (Yes or) Yes
- Drum - Rear (Yes or)
- Front Brake Rotor Diam x Thickness 13.4in
- Rear Brake Rotor Diam x Thickness 11.8in
- Rear Drum Diam x Width in

Cargo Area Dimensions

- Cargo Area Length @ Floor to Seat 1 N/Ain
- Cargo Area Length @ Floor to Seat 2 N/Ain
- Cargo Area Length @ Floor to Seat 3 N/Ain
- Cargo Area Width @ Beltline N/Ain
- Cargo Box (Area) Height N/Ain
- Cargo Box Width @ Wheelhousings N/Ain
- Cargo Volume to Seat 1 73.5ft³
- Cargo Volume to Seat 2 37.6ft³
- Cargo Volume to Seat 3 37.6ft³

Cooling System

- Total Cooling System Capacity N/Aqts

Electrical


- Cold Cranking Amps @ 0Å° F (Primary) 360
- Maximum Alternator Capacity (amps) N/A

Emissions

- EPA Greenhouse Gas Score N/A
- Tons/yr of CO2 Emissions @ 15K mi/year 7.7

Engine

- Displacement 2.0 L/121
- Engine Order Code



- Engine Type Intercooled Turbo Regular Unleaded I4
- Fuel System Gasoline Direct Injection
- SAE Net Horsepower @ RPM 184 @ 4400
- SAE Net Torque @ RPM 221 @ 1600

Exterior Dimensions

- Height, Overall 66.3in
- Length, Overall N/Ain
- Lifterover Height N/Ain
- Min Ground Clearance 7.9in
- Rear Door Opening Height N/Ain
- Rear Door Opening Width N/Ain
- Track Width, Front 62.2in
- Track Width, Rear 61.8in
- Wheelbase 109.8in
- Width, Max w/o mirrors 72.4in

Fuel Tank

- Aux Fuel Tank Capacity, Approx N/Agal
- Fuel Tank Capacity, Approx 15.9gal

Interior Dimensions

- Front Head Room 39.6in
- Front Hip Room N/Ain
- Front Leg Room 40.2in
- Front Shoulder Room 57in
- Passenger Capacity 5
- Passenger Volume 101.1ft³
- Second Head Room 38.9in
- Second Hip Room N/Ain
- Second Leg Room 38.7in
- Second Shoulder Room 55.8in
- Third Head Room in
- Third Hip Room N/Ain
- Third Leg Room in
- Third Shoulder Room in

Mileage

- Cruising Range - City 333.90mi
- Cruising Range - Hwy 429.30mi
- EPA Fuel Economy Est - City 21MPG
- EPA Fuel Economy Est - Hwy 27MPG
- EPA MPG Equivalent - City N/A
- EPA MPG Equivalent - Combined N/A
- EPA MPG Equivalent - Hwy N/A
- Fuel Economy Est-Combined 23MPG

Steering

- Lock to Lock Turns (Steering) N/A
- Steering Ratio (:1), Overall N/A
- Steering Type Rack-Pinion
- Turning Diameter - Curb to Curb 37.7ft
- Turning Diameter - Wall to Wall N/Aft

Suspension

- Shock Absorber Diameter - Front N/Amm
- Shock Absorber Diameter - Rear N/Amm
- Stabilizer Bar Diameter - Front N/Ain
- Stabilizer Bar Diameter - Rear N/Ain
- Suspension Type - Front (Cont.) Strut
- Suspension Type - Front Strut
- Suspension Type - Rear (Cont.) Multi-Link
- Suspension Type - Rear Multi-Link

Tires

- Front Tire Order Code
- Front Tire Size P215/65HR17



Licensed to J.D. Power

- Rear Tire Order Code
- Rear Tire Size P215/65HR17
- Spare Tire Order Code
- Spare Tire Size Compact

Trailer

- Dead Weight Hitch - Max Tongue Wt. lbs
- Dead Weight Hitch - Max Trailer Wt. lbs
- Maximum Trailering Capacity lbs
- Wt Distributing Hitch - Max Tongue Wt. lbs
- Wt Distributing Hitch - Max Trailer Wt. lbs

Transmission

- Clutch Size N/Ain
- Drivetrain All Wheel Drive
- Eighth Gear Ratio (:1) 0.67
- Fifth Gear Ratio (:1) 1.21
- Final Drive Axle Ratio (:1) 3.33
- First Gear Ratio (:1) 5.59
- Fourth Gear Ratio (:1) 1.43
- Reverse Ratio (:1) 3.99
- Second Gear Ratio (:1) 3.14
- Seventh Gear Ratio (:1) 0.81
- Sixth Gear Ratio (:1) 1.00
- Third Gear Ratio (:1) 1.95
- Trans Description Cont. Again
- Trans Description Cont. Automatic w/OD
- Trans Order Code
- Trans Type 8
- Transfer Case Gear Ratio (:1), High N/A
- Transfer Case Gear Ratio (:1), Low N/A

Vehicle

- EPA Classification Small Sport Utility Vehicles 4WD

Weight Information

- Base Curb Weight 3858lbs
- Curb Weight - Front N/Albs
- Curb Weight - Rear N/Albs
- Curb Weight N/Albs
- Maximum Payload Capacity N/Albs
- Total Option Weight 0.00lbs

Wheels

- Front Wheel Material Aluminum
- Front Wheel Size 17 X 7in
- Rear Wheel Material Aluminum
- Rear Wheel Size 17 X 7in
- Spare Wheel Material Steel
- Spare Wheel Size Compactin