

csievers@poquetauto.com

Vehicle Information

Date: January 23, 2019

Vehicle: 2016 Mercedes-Benz C Class Sedan 4D C300 AWD 2.0L 14

Tui

VIN: 55SWF4KB5GU100345

Weight: 3,594



New Cars/Trucks Values

Powered by Chrome Data	Base	Options	Destination	Adjusted Value
Base MSRP	\$40,950	\$4,695	\$925	\$46,570
NADA New Vehicle Values				
Low	N/A	N/A	N/A	N/A
Average	N/A	N/A	N/A	N/A
High	N/A	N/A	N/A	N/A
Optional Equipment				
			Invoice	MSRP
BLIND SPOT ASSIST			\$512.00	\$550.00
Code: 234			\$500.00	Ф ГОО ОО
HEATED FRONT SEATS			\$539.00	\$580.00
Code: 873 KEYLESS GO			\$512.00	\$550.00
Code: 889			ψ512.00	ψ550.00
PANORAMA SUNROOF			\$1376.00	\$1480.00
Code: 413			Ψ1010.00	φ1 100.00
PREMIUM 1 PACKAGE			\$651.00	\$700.00
-inc: KEYLESS GO, Surround Light Mirro Code: P01	or Mounted Entry Lamps,	SiriusXM Satellite Radio	·	·
REAR VIEW CAMERA			\$428.00	\$460.00
Code: 218-A				
SD-CARD FOR GARMIN MAP PILOT	NAVIGATION		\$558.00	\$600.00
Code: 03A				•
SIRIUSXM SATELLITE RADIO			\$428.00	\$460.00
Code: 536			ተ ດ ດດ	
STANDARD PAINT			\$0.00	\$0.00
Code: -PAINT BLACK			\$0.00	\$0.00
BLACK			ψ0.00	ψ0.00
Code: 040				
OPEN-PORE BLACK ASH TRIM			\$302.00	\$325.00
-inc: analog clock in dash Code: 736			#0.00	#0.00
BLACK, MB-TEX UPHOLSTERY			\$0.00	\$0.00



NADA New Cars/Trucks

Licensed to J.D. Power		
	Invoice	MSRP
Code: 101-0		
TIRES: 225/50R17 ALL-SEASON	\$0.00	\$0.00
(STD) Code: R02		
WHEELS: 17" SPLIT 5-SPOKE	\$0.00	\$0.00
(STD) Code: R48		

Standard Equipment

ENTERTAINMENT

- 8 Speakers
- **Audio Theft Deterrent**
- Bluetooth Wireless Phone Connectivity
- Radio w/Clock and Steering Wheel Controls
- Radio: HD AM/FM Single Disc CD/MP3 -inc: Media Interface 7" Color Display, Touchpad, USB connectivity, Bluetooth audio streaming, weatherband, sound system and auxiliary input
- Window Grid Antenna

EXTERIOR

- Black Grille w/Chrome Accents
- **Body-Colored Door Handles**
- Body-Colored Front Bumper w/Chrome Bumper Insert
- Body-Colored Power Heated Side Mirrors w/Driver Auto Dimming, Power Folding and Turn Signal Indicator
- Body-Colored Rear Bumper w/Black Rub Strip/Fascia Accent and Chrome Bumper Insert
- **Chrome Bodyside Moldings**
- Chrome Side Windows Trim and Black Front Windshield Trim
- **Clearcoat Paint**
- Fixed Rear Window w/Defroster
- Fully Automatic Projector Beam Halogen Daytime Running Headlamps w/Delay-Off
- **Galvanized Steel/Aluminum Panels**
- **LED Brakelights**
- **Light Tinted Glass**
- Rain Detecting Variable Intermittent Wipers w/Heated Jets And Reservoir
- **Rear Fog Lamps**
- Tires: 225/50R17 All-Season
- **Trunk Rear Cargo Access**
- Wheels: 17" Split 5-Spoke

INTERIOR

- 2 12V DC Power Outlets
- 2 Seatback Storage Pockets
- 40-20-40 Folding Bench Front Facing Fold Forward Seatback Rear Seat
- Air Filtration
- **Analog Display**
- **Ashtray**
- Cargo Space Lights
- Carpet Floor Trim and Carpet Trunk Lid/Rear Cargo Door Trim
- Compass
- Day-Night Auto-Dimming Rearview Mirror
- **Delayed Accessory Power**
- Driver / Passenger And Rear Door Bins
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- **Driver Foot Rest**
- Driver Seat
- **Dual Zone Front Automatic Air Conditioning**
- Engine Immobilizer
- Fade-To-Off Interior Lighting
- FOB Controls inc: Trunk/Hatch/Tailgate and Windows
- Front And Rear Map Lights
- Front Bucket Seats -inc: 8-way power front seats w/lumbar support
- Front Center Armrest and Rear Center Armrest w/Storage
- Front Cigar Lighter(s)
- Front Cupholder
- Full Carpet Floor Covering inc: Carpet Front And Rear Floor Mats
- Full Floor Console w/Covered Storage, Mini Overhead Console and 2 12V DC Power Outlets
- Gauges -inc: Speedometer, Odometer, Engine Coolant Temp, Tachometer, Trip Odometer and Trip Computer
- **Homelink Garage Door Transmitter**
- **HVAC** -inc: Underseat Ducts and Console Ducts
- Illuminated Locking Glove Box



- Licensed to J.D. P
- Interior Trim -inc: Metal-Look Interior Accents
- Leather/Metal-Look Steering Wheel w/Auto Tilt-Away
- MB Apps Selective Service Internet Access
- Mb-Tex Leatherette Door Trim Insert
- MB-Tex Upholstery
- Memory Settings -inc: Driver Seat, Door Mirrors, Steering Wheel and Head Restraints
- Outside Temp Gauge
- Passenger Seat
- Perimeter Alarm
- Power (driver Only) Anti-Whiplash Adjustable Front Head Restraints and Manual Adjustable Rear Head Restraints
- Power 1st Row Windows w/Front And Rear 1-Touch Up/Down
- Power Door Locks w/Autolock Feature
- Power Fuel Flap Locking Type
- Power Rear Windows
- Power Tilt/Telescoping Steering Column
- Proximity Key For Push Button Start Only
- Rear Cupholder
- Redundant Digital Speedometer
- Remote Keyless Entry w/Integrated Key Transmitter, 4 Door Curb/Courtesy, Illuminated Entry and Panic Button
- Remote Releases -Inc: Power Cargo Access
- Seats w/Leatherette Back Material
- Smart Device Integration
- Systems Monitor
- Tracker System
- Trip Computer
- Urethane Gear Shift Knob
- Valet Function

MECHANICAL

- 150 Amp Alternator
- 17.4 Gal. Fuel Tank
- 3.07 Axle Ratio
- 4-Wheel Disc Brakes w/4-Wheel ABS, Front And Rear Vented Discs, Brake Assist, Hill Hold Control and Electric Parking Brake
- 74-Amp/Hr Maintenance-Free Battery
- Automatic Ride Control Suspension
- Dual Stainless Steel Exhaust w/Chrome Tailpipe Finisher
- Electric Power-Assist Speed-Sensing Steering
- Engine: 2.0L Turbo I4 Includes ECO stop/start technology. FFV option is not available in all states, please consult your retail dealer and/or MBUSA to determine availability in your state
- Front And Rear Anti-Roll Bars
- Full-Time 4MATIC All-Wheel Drive
- Gas-Pressurized Shock Absorbers
- Multi-Link Rear Suspension w/Coil Springs
- Strut Front Suspension w/Coil Springs
- Transmission: 7-Speed Automatic 7G-TRONIC Plus

SAFETY

- ABS And Driveline Traction Control
- Airbag Occupancy Sensor
- BabySmart Childseat Sensor and Rear Child Safety Locks
- Collision Prevention Assist Plus
- Curtain 1st And 2nd Row Airbags
- Driver Knee Airbag, Driver And Passenger Pelvic Airbag
- Dual Stage Driver And Passenger Front Airbags
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Electronic Stability Control (ESC)
- First Aid Kit
- mbrace2 Emergency Sos
- Outboard Front Lap And Shoulder Safety Belts -inc: Rear Center 3 Point, Height Adjusters and Pretensioners
- Side Impact Beams
- Tire Specific Low Tire Pressure Warning

Vehicle Information

CRASH TEST RATING

US NHTSA CRASH TEST RESULTS:

Overall Rating: ****

Overall Frontal Barrier Crash Rating: ****

Overall Side Crash Rating: * * * * *

NADA Used Car Guide assumes no responsibility or liability for any errors or omissions or any revisions or additions made by anyone on this report. NADA Used Car Guide and its logo are registered trademarks of National Automobile Dealers Association, used under license by J.D. Power. ©2019 J.D.Power



Side Barrier Rating: * * * * *

Combined Side Barrier and Pole Ratings: Front Seat Rating: ***** Rear Seat Rating: *****

Overall Rollover Rating: * * * *
Dynamic Test Result: No Tip
Risk of Rollover: 11%

Note Regarding Driver Rating:

Male: Average sized adult male dummy in 35-MPH crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs. Female: Small-sized adult female dummy in 35-mph crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs.

Rollover Note: Dynamic (moving) test results (Tip or No Tip) and measured rollover-related properties determine vehicle's risk of rollover in single vehicle crash and its rollover rating. The Rollover Resistance Rating utilizes a "fishhook" maneuver which is a series of abrupt turns at varying speeds to see how "top-heavy" a vehicle is.

RECALL

US NHTSA CAMPAIGN ID: 16V087000

Mfg's Report Date: FEB 15, 2016

Component:

VISIBILITY:SUN ROOF ASSEMBLY

Potential Number Of Units Affected: 53

Summary:

Mercedes Benz USA, LLC (MBUSA) is recalling certain model year 2016 C300 vehicles manufactured December 11, 2015, to December 23, 2015, C300 4Matic vehicles manufactured December 12, 2015, to December 29, 2015, and C450 AMG 4Matic vehicles manufactured December 12, 2015, to December 22, 2015. The affected vehicles may be equipped with a panoramic sunroof that may not be properly bonded, allowing the glass to detach and fall from the vehicle during operation.

Consequence:

If the panoramic glass detaches during vehicle operation, it can increase the risk of injury or crash.

Remedy

MBUSÁ will notify owners, and dealers will inspect the bonding of the rear sunroof glass panel, replacing it as necessary, free of charge. The recall began on April 12, 2016. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture: DEC 10, 2015 to DEC 22, 2015 US NHTSA CAMPAIGN ID: 16V438000

Mfg's Report Date: JUN 14, 2016

Component

STEERING: ELECTRIC POWER ASSIST SYSTEM

Potential Number Of Units Affected:

17

Summary:

Mercedes Benz USA, LLC (MBUSA) is recalling certain model year 2016 C300 4Matic vehicles manufactured November 4, 2015, to March 1, 2016. In the affected vehicles, the electric power steering assist system may shutdown due to a software error.

Consequence:

If the vehicle experiences a loss of power steering assist, extra steering effort will be required at lower speeds, increasing the risk of a vehicle crash.

Remedy

MBUSA will notify owners, and dealers will update the software for the electric power steering control unit, free of charge. The recall began January 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture: NOV 03, 2015 to FEB 29, 2016 US NHTSA CAMPAIGN ID: 17V177000

Mfg's Report Date: MAR 13, 2017

Component:

AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE



Potential Number Of Units Affected:

51

Summary:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2016 AMG GT-S, GLC300, CLA250 and GLE300d 4Matic vehicles, 2013 C250, E350 BlueTec and G63 AMG vehicles, 2008-2014 C300 vehicles, 2013-2014 C300 4Matic and ML350 4Matic vehicles, 2009 C350 vehicles, 2014 CLS550, E350 4Matic, E350 Coupe 4Matic, E350 Wagon 4Matic, GLK350 and SL550 vehicles, 2012 CLS550 4Matic vehicles, 2012-2016 E350 vehicles, 2016-2017 GL450 4Matic vehicles, 2012-2014 ML350 4Matic BlueTec vehicles, 2015 S550, S550 4Matic and C300 4Matic Sedan vehicles, 2015-2016 C300 Sedan vehicles, and 2017 SL63 AMG vehicles. Various control units on these vehicles may have been updated with incorrect software, potentially affecting the correct deployment of the air bags in the event of a crash.

Consequence:

If the air bags do not deploy as intended in the event of a crash, there would be an increased risk of injury in the event of a crash.

Remedy:

MBUSA will notify owners, and dealers will update software in the affected control units, free of charge. The recall began April 21, 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture: DEC 31, 2007 to DEC 31, 2016 US NHTSA CAMPAIGN ID: 17V243000

Mfg's Report Date: APR 10, 2017

Component:

STEERING: ELECTRIC POWER ASSIST SYSTEM

Potential Number Of Units Affected:

3

Summary:

Mercedes Benz USA, LLC. (MBUSA) is recalling certain 2016-2017 C300 vehicles. The electrical contacts for the power steering electric motor may not have been properly welded, possibly resulting in a loss of electrical contact.

Consequence:

A loss of electrical contact will cause the electric power steering assist to deactivate, increasing the risk of a crash.

Remedy

MBUSA will notify owners, and dealers will replace the electric power steering rack, free of charge. The recall began June 2017. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture: JUL 10, 2016 to NOV 02, 2016 US NHTSA CAMPAIGN ID: 17V114000

Mfg's Report Date: FEB 22, 2017

Component:

ENGINE AND ENGINE COOLING:ENGINE

Potential Number Of Units Affected: 307629

007020

Summary:

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2015-2017 C300 4Matic, C300, CLA250, CLA250 4Matic and CLA45 AMG vehicles, 2017 C300 4Matic Cabrio, C300 4Matic Coupe, C300 Cabrio, C300 Coupe, E300, E300 4Matic, E400 4Matic Wagon, E43 AMG 4Matic, GLA250, GLA250 4Matic and GLC300 4Matic Coupe vehicles and 2016 C350e and GLC300 vehicles and 2016-2017 C450 4Matic AMG Sport and GLC300 4Matic vehicles. In the event that the engine or transmission cannot turn over, the starting current limiter may overheat from the repeated attempts of the starter motor attempting to start the vehicle.

Consequence

If the starting current limiter overheats, the surrounding components can melt, increasing the risk of a fire.

Remedy

MBUSA will notify owners, and dealers will install an additional fuse in the electrical line to the starter, free of charge. The recall began August 31, 2017. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2017080002.

Dates of Manufacture: JAN 31, 2014 to JAN 31, 2017

Manufacturer Recall Number: 2017080002 US NHTSA CAMPAIGN ID: 16V603000

Mfg's Report Date: AUG 15, 2016



Component:

ELECTRONIC STABILITY CONTROL

Potential Number Of Units Affected:

62

Summary:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2016 GLC 300 SUV, GLC 300 4Matic SUV, C300 Sedan and C300 4Matic vehicles manufactured February 8, 2016, to May 18, 2016. The affected vehicles may be equipped with an Electronic Stability Program (ESP) control unit that may have been damaged before being installed.

Consequence:

A damaged ESP control unit may inadvertently activate the stability control altering the vehicle's path. Additionally, the electronic parking brake may not function. Either condition may increase the risk of a crash

Remedy:

MBUSA will notify owners, and dealers will replace the ESP Hydraulic control units, free of charge. The recall is expected to begin in October 2016. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture:

FEB 07, 2016 to MAY 17, 2016

Manufacturer Recall Number: 2016090002 US NHTSA CAMPAIGN ID: 17V627000

Mfg's Report Date: OCT 05, 2017

Component: AIR BAGS:FRONTAL

Potential Number Of Units Affected:

495290

Summary:

Mercedes-Benz USA, LLC. (MBUSA) is recalling these vehicles: 2014-2018 CLA250, CLA250 4Matic, CLA45 AMG 4Matic, 2015-2018 GLA250, GLA250 4Matic, GLA45 AMG 4Matic, C300 4Matic, C63S AMG, 2012-2014 C250, C350, C300 4Matic, E550 4Matic, 2013-2014 C63 AMG, 2012-2015 C250 Coupe, C350 Coupe, C63 AMG Coupe, 2013-2015 C350 4Matic Coupe, GLK250 4Matic BlueTec, GLK350, GLK350 4Matic, 2016-2017 C350e, C43 AMG, 2015 C400 4Matic, 2016-2018 C63 AMG, GLC300, GLC300, GLC300 4Matic, 2017-2018 C300 Coupe, C300 4Matic Coupe, C300 4Matic Coupe, C43 AMG Coupe, C300 AMG Coupe, C300 Cabriolet, C300 4Matic Coupe, C43 AMG Cabriolet, C63 AMG Cabriolet, GLC300 4Matic Coupe, GLC43 AMG, GLC43 AMG Coupe, 2014 E350 Coupe, E350 4Matic Coupe, E350 Cabriolet, E400 Hybrid, 2015-2017 E400 Coupe, E400 4Matic Coupe, E400 Cabriolet, 2014-2017 E550 Coupe, E550 Cabriolet, B250e, 2014-2016 E250 BlueTec, E63 AMG 4Matic Wagon, 2012-2013 E350 BlueTec, 2012-2016 E350, E350 4Matic, 2015-2016 E400, E400 4Matic, 2012 E63 AMG, 2014-2015 E250 4Matic BlueTec, 2013-2016 E350 Wagon, 2017 GLC300d 4Matic, and 2018 GLC350e 4Matic. The driver's air bag may unexpectedly deploy due to insufficient grounding of the steering components if an electrostatic discharge occurs and the air bag clockspring is broken.

Consequence

If the driver air bag inadvertently deploys, it can increase the risk of injury and a crash.

Remedy:

MBUSA will notify owners, and dealers will add sufficient grounding to the steering components, free of charge. The recall began in December 6, 2017. Owners may contact MBUSA customer service at 1-877-496-3691.

Manufacturer Recall Number: 2017110011 US NHTSA CAMPAIGN ID: 18V850000

Mfg's Report Date: NOV 28, 2018

Component:

STEERING: RACK AND PINION: RACK

Potential Number Of Units Affected:

6162

Summary:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2015-2016 Mercedes Benz C300, 2017-2019 C300 Cabrio, C300 Coupe, C63 Cabrio, 2015 C63S AMG, 2018-2019 C300, C350e, C63 AMG, C63S AMG Cabrio, 2018 C63 AMG Cabrio, C63 AMG Coupe, C63S AMG, C63S AMG Coupe, E300, E400 Cabrio, E400 Coupe, 2019 CLS450, E450 Cabrio, and E450 Coupe rear-wheel drive vehicles. A locknut in the steering rack may break under high load, possibly causing the steering to become stuck in one position.

Consequence

A car that cannot be properly steered has an increased risk of a crash.

Remedy

MBUSA will notify owners, and dealers will replace the steering rack, free of charge. The recall is expected to begin January 25, 2019. Owners may contact MBUSA customer service at 1-800-367-6372.

Dates of Manufacture:



JAN 01, 2018 to OCT 04, 2018

WARRANTY

Basic:

4 Years/50,000 Miles

Drivetrain:

4 Years/50,000 Miles

Corrosion:

4 Years/50,000 Miles

Roadside Assistance: 4 Years/50,000 Miles

Technical Specifications

Brakes

- Brake ABS System (Second Line) N/A
- Brake ABS System 4-Wheel
- Brake Type 4-Wheel Disc
- Disc Front (Yes or) Yes
- Disc Rear (Yes or) Yes
- Drum Rear (Yes or)
- Front Brake Rotor Diam x Thickness 13in
- Rear Brake Rotor Diam x Thickness 11.8in
- Rear Drum Diam x Width in

Cargo Area Dimensions

Trunk Volume 12.6ft³

Cooling System

• Total Cooling System Capacity N/Aqts

Electrical

- Cold Cranking Amps @ O° F (Primary) N/A
- Maximum Alternator Capacity (amps) 150

Emissions

- EPA Greenhouse Gas Score 6.0
- Tons/yr of CO2 Emissions @ 15K mi/year 6.5

Engine

- Displacement 2.0 L/121
- Engine Order Code
- Engine Type Intercooled Turbo Premium Unleaded I4
- Fuel System Gasoline Direct Injection
- SAE Net Horsepower @ RPM 241 @ 5550
- SAE Net Torque @ RPM 273 @ 1300

Exterior Dimensions

- Height, Overall 56.8in
- Length, Overall 184.5in
- Liftover Height N/Ain
- Min Ground Clearance N/Ain
- Track Width, Front 61.5in
- Track Width, Rear 60.9in
- Wheelbase 111.8in
- Width, Max w/o mirrors 71.3in

Fuel Tank

Aux Fuel Tank Capacity, Approx N/Agal



• Fuel Tank Capacity, Approx 17.4gal

Interior Dimensions

- Front Head Room 37.1in
- Front Hip Room N/Ain
- Front Leg Room 41.7in
- Front Shoulder Room N/Ain
- Passenger Capacity 5
- Passenger Volume N/Aft³
- Second Head Room 37.1in
- Second Hip Room N/Ain
- Second Leg Room 35.2in
- Second Shoulder Room N/Ain

Mileage

- Battery Range N/Ami
- Cruising Range City 417.60mi
- Cruising Range Hwy 539.40mi
- EPA Fuel Economy Est City 24MPG
- EPA Fuel Economy Est Hwy 31MPG
- EPA MPG Equivalent City N/A
- EPA MPG Equivalent Combined N/A
- EPA MPG Equivalent Hwy N/A
- Fuel Economy Est-Combined 27MPG

Steering

- Lock to Lock Turns (Steering) N/A
- Steering Ratio (:1), Overall N/A
- Steering Type Rack-Pinion
- Turning Diameter Curb to Curb 36.8ft
- Turning Diameter Wall to Wall N/Aft

Suspension

- Shock Absorber Diameter Front N/Amm
- Shock Absorber Diameter Rear N/Amm
- Stabilizer Bar Diameter Front N/Ain
- Stabilizer Bar Diameter Rear N/Ain
- Suspension Type Front (Cont.) Strut
- Suspension Type Front Strut
- Suspension Type Rear (Cont.) Multi-Link
- Suspension Type Rear Multi-Link

Tires

- Front Tire Order Code RO2
- Front Tire Size P225/50HR17
- Rear Tire Order Code RO2
- Rear Tire Size P225/50HR17
- Spare Tire Order Code
- Spare Tire Size

Trailering

- Dead Weight Hitch Max Tongue Wt. N/Albs
- Dead Weight Hitch Max Trailer Wt. N/Albs
- Wt Distributing Hitch Max Tongue Wt. N/Albs
- Wt Distributing Hitch Max Trailer Wt. N/Albs

Transmission

- Clutch Size N/Ain
- Drivetrain All Wheel Drive
- Fifth Gear Ratio (:1) 1.00
- Final Drive Axle Ratio (:1) 3.07
- First Gear Ratio (:1) 4.38Fourth Gear Ratio (:1) 1.37
- Reverse Ratio (:1) 3.42
- Second Gear Ratio (:1) 2.86
- Second Gear Ratio (:1) 2.86
 Seventh Gear Ratio (:1) 0.73
- Sixth Gear Ratio (:1) 0.82



- Third Gear Ratio (:1) 1.92
- Trans Description Cont. Again
- Trans Description Cont. Automatic w/OD
- Trans Order Code
- Trans Type 7

Vehicle

• EPA Classification Compact Cars

Weight Information

• Base Curb Weight 3594lbs

Wheels

- Front Wheel Material AluminumFront Wheel Size 17 X 7in
- Rear Wheel Material Aluminum
- Rear Wheel Size 17 X 7in
- Spare Wheel Material
- Spare Wheel Size in