

SAFE-TEST POINT™ FEATURES

- Safe-Test Point™ is a Permanent Electrical Safety Device (PESD) that allows workers to safely perform an absence of voltage test from outside the electrical cabinet with a portable test instrument.
- Provides a safer and more productive method of performing Lockout/Tagout (LOTO), while enhancing compliance with NFPA 70E and the OSHA energy isolation principle.
- The **Safe-Test Point™** contains test point jacks that are hardwired directly to energy sources and allows measurement of up to 1,000 VAC/VDC by inserting the insulated meter probes into any two test point jacks to take a voltage reading. (See inside chart for Operational Ranges of each product)
- The 4-Wire option comes complete with a tool-entry dust cap that also includes a label and the 5-Wire option is featured in a pad-lockable housing that also includes tool-entry.





OPERATION

NEW R-3MT-1K-KIT-*





The **Safe-Test Point™** provides voltage test point jacks to allow measurement of up to 1,000 VAC/VDC (see below chart for Operational Ranges) either phase-to-phase, phase-to-ground, phase-to-neutral, or neutral-to-ground. Following facility safety procedures, insert insulated meter probes with .080" tips into any two test point jacks to take a voltage reading with properly rated test equipment (see Test Instrument Requirements). By following proper safety procedures, the risk of arc flash or shock hazard is mitigated.

In addition to the 4-Wire testing option, the Safe-Test Point is the first voltage portal from our line of GracePESDs® to feature an optional 5-Wire configuration for use on wye power systems with a neutral terminal. Mounting options will vary between the 4-Wire and 5-Wire configurations (refer to the installation guide(s) for more details). To customize your 5-Wire configuration see your sales representative.

SAFE-TEST POINT™ TECHNICAL SPECIFICATIONS

	CAT III & CAT IV, 1000V CAT III & CAT IV, 600V				
	CRACE WASHINGTON TO AND THE PROPERTY OF THE PR	WARNING WAR	R-5MT		
SERIES	NEW 1K 4-WIRE SAFE-TEST POINT™	4-WIRE SAFE-TEST POINT™	5-WIRE SAFE-TEST POINT™		
Product Number	R-3MT-1K-KIT-H* R-3MT-1K-KIT-F*	R-3MT-KIT-H* R-3MT-KIT-F*	R-5MT R-5MT-4X R-5MT-12		
Descriptions	4-Wire Safe-Test Point™ with label and dust cap	4-Wire Safe-Test Point™ with label and dust cap	5-Wire Safe-Test Point™		
Operating & Storage Temperature	Operate: -20°C to +55°C Storage: -45°C to +85°C				
UL Operational Range AC Single or 3-Phase	0 to 1000VAC phase to phase and/or phase to ground 50/60/400Hz	0 to 600VAC phase to phase and/or phase to ground 50/60/400Hz			
UL Operational Range DC or Stored Energy	0 to 1000VDC, any (2) wires line-to-line or line-to-ground 0 to 600VDC, any (2) wires line-to-line or line-to-ground				
Internal Resistance	164 kΩ in series with each input (L1, L2, L3, GND) wire to respective output jack	102 kΩ in series with each input (L1, L2, L3, GND) wire to respective output jack	102 kΩ in series with each input (L1, L2, L3, N, GND) wire to respective output jack		
Correction Factor	3.3% (Voltage measured value reads 3.3% less than the actual value due to the impedance protection inside the device)	2% (Voltage measured value reads 2% less than the actual value due to the impedance protection inside the device)			
Wire Specifications	8ft UL Listed 14AWG PVC Insulated	8ft UL Listed 18AWG PVC Insulated			
Components	3 Red jacks (L1, L2, L3), 1 Green jack (GND), .080" DIA pin sockets, 30mm push button hole, minimum probe insertion length .480"		3 Red jacks (L1, L2, L3), 1 Black jack (Neutral), 1 Green jack (GND), .080" DIA pin sockets, minimum probe insertion length .480"		
Certifications**	UL Type 4, 4X, 12 & 13 File #: E311256; CE	UL Type 12 & 13 File #: E311256; CE**	Port: UL Type 4, 4X, 12 File #: E311256, E207344; CE		

^{*}Part numbers ending in H are horizontal mount units and labels. Part numbers ending in F are flange mount units and labels.


^{**}Dust cap and label are not UL or CE certified.

R-3W SERIES VOLTAGE INDICATOR AND SAFE-TEST POINT™ COMBO TECHNICAL SPECIFICATIONS

All R-3W combos supplied	CAT III & IV RATED				
	600 VAC/VDC Type 12 & 13 Applications			1000 VDC or 600 VAC Type 4 & 4X Applications	
	R-3WMT-LMH	Tables of the state of the stat	R-3WSMT-LMH		
with R-3MT or R-3MT-1K, label and dust cap.		R-3W2MT-LMF		R-3WMT1K-LMF	
Product Number	R-3WMT-LMH* R-3WMT-LMF*	R-3W2MT-LMH* R-3W2MT-LMF*	R-3WSMT-LMH* R-3WSMT-LMF*	R-3WMT1K-LMH* R-3WMT1K-LMF*	
Voltage Indicator	R-3W (Flashing red LEDs)	R-3W2 (Flashing red LEDs)	R-3W-SR (Non-flashing red LEDs)	R-3W (Flashing red LEDs)	
Safe-Test Point™	R-3MT			R-3MT-1K	
Label Dimensions	Horizontal - 4.323"H x 6.50"W Flange - 10.058"H x 1.90"W				
Operating & Storage Temperature	Operate: -20°C to +55°C Storage: -45°C to +85°C				
UL Operational Range AC Single or 3-Phase	40-600VAC 50/60/400Hz	40-600VAC 50/60/400Hz	40-600VAC 50/60/400Hz	Voltage Indicator: 40-600VAC 50/60/400Hz Safe-Test Point™: 0-1000VAC 50/60/400Hz	
UL Operational Range DC or Stored Energy	Voltage Indicators: 30 to 1000VDC Safe-Test Point™: 0 to 600VDC			Voltage Indicator: 30 to 1000VDC Safe-Test Point™: 0 to 1000VDC	
Wire Specifications	PVC insulated with nylon jacket, 8ft, 18AWG Wire, 90°C @ 1000V, UL 1452, pre-stripped and tinned			Voltage Indicator: PVC insulated with nylon jacket, 8ft, 18AWG Wire, 90°C @ 1000V, UL 1452, pre-stripped and tinned Safe-Test Point™: 8ft, UL Listed, 14AWG, PVC Insulated	
Certifications**	Voltage Indicators: UL Type 4, 4X, 12 & 13, CE** Safe-Test Point™: UL 12 & 13, CE**			Both Voltage Indicator and Safe-Test Point™ UL Type 4, 4X, 12 & 13, CE	

Special configurations and custom labels available upon request. Contact your sales representative for more information.

R-3MT-1K-KIT TERMINATIONS



R-3MT & R-5MT TERMINATIONS

Note: R-3MT-1K Test Point Assembly with 164 k Ω impedance on L1, L2, L3, and GND affects voltage readings - 3.3%. R-3MT & R-5MT Test Point Assemblies with 102 k Ω impedance on L1, L2, L3, and GND affects voltage readings - 2%.

FOR MORE INFORMATION VISIT PESD.COM OR CALL 1.800.280.9517

Warning: Verify an electrical conductor has been de-energized using an adequately rated test instrument before working on it. Follow appropriate Energy Control (Lockout/Tagout) procedures as per OSHA Subpart S.

© Grace Technologies All rights reserved. Specifications are subject to change with/without notice.

PORTABLE TEST INSTRUMENT REQUIREMENTS

Voltage test instrument with 1000V AC/DC rated input minimum, a typical $10M\Omega$ input impedance and CAT III & IV. A pair of insulated test probes with .080" DIA. points with minimum probe insertion length of .480".





^{*}Part numbers ending in H are horizontal mount units and labels. Part numbers ending in F are flange mount units and labels.

^{**}Dust cap and label are not UL or CE certified.

TECHNICAL SPECIFICATIONS For more details on each product please refer to the installation guide(s).

R-3MT and R-3MT-1K





R-5MT

FREQUENTLY ASKED QUESTIONS

#1 Phillips

Head Screw

Regular head captive

screw tighten up to 3in LBF (0.3 NM)

Q: What is the difference between the R-3MT and R-3MT-1K Safe-Test Points?

A: The difference between these two versions of the Safe-Test Point™ is that the R-3MT-1K is designed for use on higher voltage systems in CAT IV systems (up to 1000VAC/VDC). Furthermore, the R-3MT-1K has additional UL certifications for Type 4, 4X, 12, & 13 while the standard R-3MT is rated for UL Type 12 & 13 only.

Q: Where do I install the Safe-Test Point™ on equipment?

A: Safe-Test Point™ can be directly wired to either the load side or line side of the LOTO voltage source point. It can also be directly wired onto the bus below the fuses to measure a blown fuse or a tripped circuit breaker.

Q: What is the shock hazard when using this device?


A: This high impedance device limits the max. available fault current to 2.94mA at 600V and 2.35mA at 480V when any two test point jacks are shorted together. According to OSHA document 3075 (2002) page 7, "any shock hazard under 6mA is considered a slight shock; uncomfortable, but not painful."

Q: What would a typical Lockout/Tagout (LOTO) procedure include with this device?

A: Follow NFPA 70E Article 120.5, Process for establishing and verifying an electrically safe work condition. The Safe-Test Point™ allows voltage measurements from phase to phase and phase to ground to test for absence of voltage safely from outside the enclosure.

Q: How do I perform a "live-dead-live" test with the R-3MT?

A: Always follow lockout/tagout procedures as per Article 120.4 and "live-dead-live" test procedure as per Article 120.5(7) of NFPA 70E (2021)--with a properly rated test instrument, verify the test instrument to a known source, then insert the test probes into the R-3MT test point assembly to verify the presence of voltage. Next, open the isolator and proceed to test for absence of voltage on the R-3MT assembly by measuring the voltage on L1-L2, L1-L3, L2-L3, L1-G, L2-G and L3-G. Once you have tested for absence of voltage, re-verify the test instrument to any known source.





For a complete listing of Frequently Asked Questions please scan the QR Code to the left to go to our Knowledge Base.

Warning: Verify an electrical conductor has been de-energized using an adequately rated test instrument before working on it. Follow appropriate Energy Control (Lockout/Tagout) procedures as per OSHA Subpart S.

