

**TRIP**  
Extreme UNIVERSAL



**HEAT:** 500 °C  
**SPEED:** 40%

**T3**  
Extreme



**HEAT:** 430 °C  
**SPEED:** 5


**T300**  
Extreme



**Hot Air Welding**  
**HEAT:** 500 °C  
**SPEED:** 8 M/MIN

**Hot Wedge Welding**  
**HEAT:** 450 °C  
**SPEED:** 7 M/MIN


**T600**  
Extreme



**Hot Air Welding**  
**HEAT:** 500 °C  
**SPEED:** 8 M/MIN

**Hot Wedge Welding**  
**HEAT:** 450 °C  
**SPEED:** 7 M/MIN

**112**  
Extreme



**HEAT:** 730 °C  
**SPEED:** 15 M/MIN

\*\*\*All published weld settings are estimate ranges. The settings of your machine may vary.  
The testing of all seams and all fabrics is the exclusive responsibility of the operator.

ARCHITENT