

TRAD
Extreme UNIVERSAL



HEAT: 500 °C
SPEED: 40%

T3
Extreme



HEAT: 430 °C
SPEED: 4

T300
Extreme



Hot Air Welding
HEAT: 500 °C
SPEED: 4 M/MIN

Hot Wedge Welding
HEAT: 450 °C
SPEED: 5 M/MIN


T600
Extreme



Hot Air Welding
HEAT: 500 °C
SPEED: 4 M/MIN

Hot Wedge Welding
HEAT: 450 °C
SPEED: 5 M/MIN

112
Extreme



HEAT: 730 °C
SPEED: 10 M/MIN

***All published weld settings are estimate ranges. The settings of your machine may vary.
The testing of all seams and all fabrics is the exclusive responsibility of the operator.

RIVIERA MARINE

MILLER WELDMASTER®
The First Choice Globally

4220 Alabama Ave
Navarre | Ohio | 44662 USA
Phone. 330 - 833 - 6739 | Fax. 330 - 837 - 2828
www.weldmaster.com | sales@weldmaster.com