

Profile



©2010 National Coatings Corporation.
All Rights Reserved.

NESTLE

Size: 60,000 Square Feet

Location: Boise, Idaho

Challenge *Aged PVC Roof*

- Weathered and checking PVC.
- Severe weathering in waterways, around drains, and around HVAC platforms.
- Loss of integrity and advanced deterioration at seams.
- Concern regarding the loss of plasticizers.

Solution *AcryShield® Restoration System*

- No more UV degradation.
- Restored existing roof and provided superior waterproofing.
- Seamless and fully adhered roofing system.
- Minimized loss of plasticizers from PVC membrane.

Nestle was able to restore a relatively young PVC roof that was showing typical signs of deterioration. Their new Cool Roof System adds an extra layer of waterproofing, will help to lower energy bills and life-cycle costs, and can be maintained for years to come.

**NATIONAL
COATINGS**

**COOL
ROOF
SYSTEMS®**

**NATIONAL
COATINGS**

1201 Calle Suerte, Camarillo, CA 93012
(800) 423-9557, Fax (800) 294-3866

www.nationalcoatings.com, info@nationalcoatings.com