

Pilot + Aircraft Safety Survey

Trip summary: Van Nuys, CA, US (KVNY) — Teterboro, NJ, US (KTEB)

Trip departure date: 11-Jul-2008

Safety standard: The Wyvern Standard

Operator

Certificate holder name: RR Investments dba Million Air Dallas

Certificate: GQVA433E

Address: 4300 WESTGROVE DR., Attn: Charter, ADDISON, TX 75001 United States

Wyvern audited: Yes – Audited on 10-Apr-2007

Aircraft

Aircraft registration: N123AB

Type: Type: HS-125-800XP (Hawker 800XP)

Serial number: 98765

Seats: 8

Year: 2001

Insurance amount: \$150 Million



Pilot in Command (PIC)

Name: David Henderson

Certificate type: ATP

Applicable type rating: HS125

Medical: First class

Last medical date: 28-Apr-2008

Total time: 6156 hrs

Total PIC time: 4231 hrs

Total time in type: 1289 hrs

Record last updated: 06-Jul-2008

Second in Command (SIC)

Name: Steven Clark

Certificate type: Commercial ME/INST

Applicable type rating: HS125

Medical type: First class

Last medical date: 30-Mar-2008

Total time: 5972 hrs

Total time as PIC: 2641 hrs

Time in type as PIC: 327 hrs

Record last updated: 02-Jul-2008

Disclaimer

The data used in compiling and contained in this report has been obtained from the air charter operators named above, the National Transportation Safety Board, the Federal Aviation Administration and other publicly available information sources. All information contained in this report is of an advisory nature only and should not be deemed a recommendation, certification or warranty. Wyvern makes no claim as to the veracity of the information contained in this report. Any conclusions drawn from the data contained in this report are the reader's alone. Neither Wyvern nor any employee, officer, or affiliate makes any warranty, expressed or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information contained in this report. Wyvern will not be held liable for any damages whatsoever arising out of or in connection with the use of the information contained in this report.