



Le présent bulletin détaille les types d'injecteurs Common Rail qu'il est possible de tester avec le kit HK900 (sur banc AVM2) ou avec les bancs d'essai CRI-PC et IFT-200, ainsi que les différents accessoires nécessaires.

**REMARQUE:** La version Excel de ce bulletin (disponible en téléchargement à [www.hartridge.com](http://www.hartridge.com)) comprend également des détails d'accessoires pour les machines IFR-50 et IFT-70 machines, ainsi qu'une page 'Recherche' pour trouver les pièces nécessaires pour un injecteur spécifique.

Le dessin illustre un dispositif typique; les fournitures supplémentaires sont les suivantes :

1. Adaptateur d'embout et joints
  2. Adaptateur pour retour de fuite (non représenté)
  3. Bloc de serrage
  4. Tube HP (entre rampe et injecteur) (non représenté)
  5. Câble électrique (non représenté)
  6. Chemise d'alimentation (voir ci-dessous)
  7. \* Entretoise (seulement AVM2 / CRI)
- \* L'entretoise 9 kN est fournie avec le kit HK900/CRI-PC

Pour AVM2 / CRI, et de manière générale, le bloc de serrage, le tube HP et la chemise d'alimentation sont particuliers à une référence donnée (ou à un groupe de références identiques dans leurs dimensions). Les autres accessoires sont communs à une gamme de références. Consultez les tableaux des applications au verso, pour déterminer les pièces nécessaires à chaque application.

#### À noter concernant les tableaux des applications

Les kits références HK9xx contiennent les fournitures pour 4 injecteurs. Avec un banc CRI-PC simple ligne, les références des kits à utiliser sont les mêmes, mais complétées d'un suffixe "/C", comme dans HK9xx/C par exemple ; ces kits "/C" comportent les fournitures nécessaires à un seul injecteur.

L'IFR-50 ne nécessite aucun adaptateur d'embout et bloc de serrage. Pour le IFR-50, on peut utiliser les mêmes numéros de kit de câble, mais sans y ajouter "/R", par ex. HK9xx/R. Ces kits "/R" contiendront des versions plus courtes des câbles standards, adaptées à l'utilisation de l'IFR-50.

x = non pertinent

AM = Toutes Marques (All Makes)

OE = La Solution Officielle

#### Flexibles haute pression

Les références ci-dessous correspondent à des flexibles haute pression destinés aux solutions d'essai des injecteurs CR toutes marques. Ils sont vendus à l'unité ; un flexible par circuit d'injection :

AHP5065	Flexible HP – 400 x 14 x 12
AHP5066	Flexible HP – 400 x 14 x 14
AHP5129	Flexible HP – 350 x 14 x 12, Coude à 90°
AHP5130	Flexible HP – 400 x 14 x 14, Coude à 90°
AHP5140	Flexible HP – 600 x 14 x 12
AHP5141	Flexible HP – 600 x 14 x 14
AHP5142	Flexible HP – 600 x 14 x 12, Coude à 90°
AHP5143	Flexible HP – 600 x 14 x 14, Coude à 90°

#### Installation (solidaire) du flexible HP recommandée, à savoir HK917

1. L'extrémité taraudée du collier du flexible doit être ajustée sur l'orifice de la rampe.
2. Approcher cette extrémité de la rampe et régler la position du collier de la manière appropriée : il est nécessaire de laisser un espace d'environ 1 mm entre le siège de la rampe et le collier HP pour garantir que le flexible vienne en contact hermétique avec le côté du cône (et non le collier lui-même).
3. Serrer l'écrou à la main pour positionner le flexible puis serrer au couple à 35 Nm.

Pour les adaptateurs pour essais d'étanchéité HK952 Delphi, HK953 et HK954 Bosch, voir TB195/16.

#### Applications Poids-Lourds

Pour les applications lourdes, il peut ne pas être possible de tester 4 injecteurs à la fois en raison de contraintes soit de la pompe d'alimentation haute pression utilisés soit du système de mesure de la machine. Pour ces applications, les injecteurs doivent être testés individuellement ou par paires.

D'autres applications sont en cours de développement ; merci de prendre contact avec Hartridge™ pour toute information complémentaire sur les nouvelles applications.

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC											IFT-200						
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
									Nosepiece Adaptor	Nozzle Leak Adaptor	BackLeak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	BackLeak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
AZPI (CRI-PC ONLY)	A-04-011-01	Coil	No			YaZDA (Engine Manuf.)			HK1147-T		HK1150	CRI: HK1146	x	AHP5130	x	x	HK963	x	x	9kN	HK1147-T	HK1150	A220K121	AHP5143	A220P121	x
Bosch	0445 110 002	Coil	No		CR/IPS19/ZEREK10S	Fiat Lancia Alfa Romeo		1.9 JTD/2.4 JTD	HK907	HK952	HK909	HK918	x	AHP5129	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5142	A220P115	x
Bosch	0445 110 008	Coil	No		CR/IPS17/ZEREW10S				HK907	HK952	HK909	HK914	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 009	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 010	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 011	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 012	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 021	Coil	No		CR/IPS19/ZEREK10S	Renault		1.9 DCI	HK907	HK952	HK909	HK969	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 024	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 025	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 028	Coil	No		CR/IPS17/ZEREK10S	BMW MG/ Rover			HK907	HK952	HK909	HK941	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 029	Coil	No		CR/IPS17/ZEREK10S	BMW MG/ Rover			HK907	HK952	HK909	HK941	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 030	Coil	No		CR/IPS17/ZEREK10S	BMW MG/ Rover			HK907	HK952	HK909	HK941	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 034	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 035	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 036	Coil	No		CR/IPS17/ZEREW10S	Citroen Peugeot		2.2 HDi	HK907	HK952	HK909	HK937	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 038	Coil	No		CR/IPS17/ZEREK10S	Renault Opel			HK907	HK952	HK909	HK971	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 044	Coil	No		CR/IPS17/ZEREK10S	Chevrolet Citroen Peugeot Fiat Lancia			HK907	HK952	HK909	HK914	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 047	Coil	No		CR/IPS17/ZEREK10S	BMW MG/ Rover			HK907	HK952	HK909	HK941	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 048	Coil	No		CR/IPS17/ZEREK10S	BMW MG/ Rover			HK907	HK952	HK909	HK941	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 049	Coil	No		CR/IPS17/ZEREK10S	BMW MG/ Rover			HK907	HK952	HK909	HK941	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 055	Coil	No		CR/IPS19/ZEREK20S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 057	Coil	No		CR/IPS17/ZEREW10S	Citroen Peugeot		2.2 HDi	HK907	HK952	HK909	HK937	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 059	Coil	No		CR/IPS19/ZEREK10S	Chrysler	Voyager	2.5ltr	HK907	HK952	HK909	HK986	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 062	Coil	No		CR/IPS17/ZEREK10S	Chevrolet Citroen Peugeot Fiat Lancia			HK907	HK952	HK909	HK914	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 063	Coil	No		CR/IPS17/ZEREK10S	Renault Opel			HK907	HK952	HK909	HK971	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 064	Coil	No		CR/IPS17/ZEREK10S	Hyundai Kia			HK907	HK952	HK909	HK939	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 068	Coil	No		CR/IPS19/ZEREK10S	Fiat Lancia Alfa Romeo			HK907	HK952	HK909	HK918	x	AHP5129	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5142	A220P115	x
Bosch	0445 110 069	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 070	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 071	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 072	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 073	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 074	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 075	Coil	No		CR/IPS20/ZEREAK20S	Citroen Peugeot Chevrolet		1.4 HDi	HK907	HK952	HK909	HK947	x	AHP5129	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5142	A220P115	x
Bosch	0445 110 076	Coil	No		CR/IPS17/ZEREK10S	Chevrolet Citroen Peugeot Fiat Lancia			HK907	HK952	HK909	HK914	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 077	Coil	No		CR/IPS19/ZEREK20S	Volvo			HK907	HK952	HK909	HK978	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 078	Coil	No		CR/IPS19/ZEREK20S	Volvo			HK907	HK952	HK909	HK978	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC												IFT-200					
									1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ054)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Bosch	0445 110 080	Coil	No		CR/IFL17/ZEREAK20S	BMW			HK907	HK952	HK909	HK988	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 083	Coil	No		CR/IFL17/ZEREK10S	Fiat Lancia Opel			HK907	HK952	HK909	HK980	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 084	Coil	No		CR/IFL19/ZEREK10S	Renault Opel			HK907	HK952	HK909	HK971	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 085	Coil	No		CR/IPS17/ZEREK20S	Toyota			HK907	HK952	HK909	HK982	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 086	Coil	No		CR/IPS19/ZEREK10S	Kia Hyundai		2.5CRDi	HK907	HK952	HK909	HK942	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 087	Coil	No		CR/IFS19/ZEREK10S	Renault Opel			HK907	HK952	HK909	HK971	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 092	Coil	No		CR/IFL19/ZEREK10S	Kia Hyundai		2.5CRDi	HK907	HK952	HK909	HK942	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 094	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 095	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 096	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 099	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 100	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 101	Coil	No		CR/IFL17/ZEREK10S	Hyundai Kia			HK907	HK952	HK909	HK939	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 102	Coil	No		CR/IFS19/ZEREK10S	Renault Opel			HK907	HK952	HK909	HK971	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 104	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 105	Coil	No		CR/IFL19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 106	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 107	Coil	No		CR/IFL19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 108	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 110	Coil	No		CR/IPS19/ZEREK10S	Renault		1.9 DCI	HK907	HK952	HK909	HK969	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 116	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 118	Coil	No		CR/IFL17/ZEREK20S	GM/ Opel		1.7 CDTi	HK907	HK952	HK909	AVM2: HK943 CRI: HK1018	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 119	Coil	No		CR/IPS19/ZEREK10S	Fiat Lancia Alfa Romeo			HK907	HK952	HK909	HK918	x	AHP5129	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5142	A220P115	x
Bosch	0445 110 121	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 126	Coil	No		CR/IFL17/ZEREK10S	Hyundai Kia			HK907	HK952	HK909	HK939	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 129	Coil	No		CR/IPS19/ZEREAK20S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 130	Coil	No		CR/IFS17/ZEREK10S	BMW MG/ Rover			HK907	HK952	HK909	HK941	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 131	Coil	No		CR/IFL17/ZEREAK20S	BMW			HK907	HK952	HK909	HK988	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 135	Coil	No		CR/IFL20/ZEREAK20S	Citroen Peugeot		1.4 Hd	HK907	HK952	HK909	HK947	x	AHP5129	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5142	A220P115	x
Bosch	0445 110 141	Coil	No		CR/IPS17/ZEREK10S	Renault Opel			HK907	HK952	HK909	HK971	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 146	Coil	No		CR/IPS19/ZEREAK10S	Renault		1.9 DCI	HK907	HK952	HK909	HK969	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 156	Coil	No		CR/IPS19/ZEREAK20S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 159	Coil	No		CR/IFL17/ZEREK20S	Vauxhall Opel SAAB		1.9 CDTi	HK907	HK952	HK909	HK990	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 162	Coil	No			Mercedes	Sprinter	OM647	HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 174	Coil	No		CR/IFL17/ZEREK20S	GM/ Opel		1.7 CDTi	HK907	HK952	HK909	AVM2: HK943 CRI: HK1018	x	AHP5129	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5142	A220P115	x
Bosch	0445 110 181	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 182	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 183	Coil	No		CR/IFL17/ZEREK20S	Fiat Lancia Opel			HK907	HK952	HK909	HK980	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 185	Coil	No		CR/IFL19/ZEREK10S	Kia Hyundai		2.5CRDi	HK907	HK952	HK909	HK942	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 110 186	Coil	No		CR/IFL19/ZEREK10S	Kia Hyundai		2.5CRDi	HK907	HK952	HK909	HK942	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC											IFT-200						
									1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fueling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Bosch	0445 110 188	Coil	No		CR/IFL17/ZEREK20S	Citroen Ford Peugeot Volvo	C4, C5, 1.6HDI, Xsara, Picasso Focus, C-Max, Focus 2 206, 307, 407 C30, S40, V50		HK907	HK952	HK909	HK1010	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 189	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 190	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 206	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 215	Coil	No		CR/IPS17/ZEREK20S	Toyota			HK907	HK952	HK909	HK982	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 217	Coil	No			Dodge Jeep	Liberty		HK907	HK952	HK909	HK1089	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 237	Coil	No		CR/IPS19/ZEREAK10S	Mercedes Benz			HK907	HK952	HK909	HK912	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 258	Coil	No			Hyundai Kia	330, Sonata, Tucson Carenis, Cee'd, Lotoe, Magentis, Sportage	2.0 CRDi	HK907	HK952	HK909	HK1181 HK1182	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 259	Coil	No			Ford	DV6		HK907	HK952	HK909	HK1010	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 273	Coil	No		CR/IFL19/ZEREK20S	Fiat IVECO		2.3i	HK908	HK953	HK909	HK973	x	AHP5065	x	x	HK902	x	x	9kN	HK908	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 110 315	Coil	No			Valmett Tractor			HK907	HK952	HK909	HK1157	x	AHP5065	x	x	HK905	x	x	9kN	HK907	HK909	A220K120	AHP5140	A220P117	x
Bosch	0445 110 683	Coil	No		CR/IFS17/ZEREW10S				HK907	HK952	HK909	HK937	x	AHP5065	x	x	HK902	x	x	9kN	HK907	HK909	A220K121	AHP5140	A220P115	x
Bosch	0445 115 007	Piezo	No			Vauxhall/Opel Renault Nissan	Vivaro Laguna, Megane Vel Satis, Espace, Koleos, Traffic Primastar	M9R 780-782 2.0 CDTi 2.0 Dci	HK907	HK952	HK1130 HK1131	HK1158	x	AHP5066	x	x	x	HK1145	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P128	x
Bosch	0445 115 022	Piezo	No			Nissan	Primastar, Quashepi, X-Trail	2.0ltr dCi	HK907	HK952	HK1130 HK1131	HK1158	x	AHP5066	x	x	x	HK1145	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P128	x
Bosch	0445 115 026	Piezo	No		CR/IPS19/ZEREAK50S				HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 027	Piezo	No		CR/IPS19/ZEREAK50S				HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 053	Piezo	No		CR/IFL19/ZEREAK50S 59130Z77AJ	Audi	A4 A6	2.7L	HK907	HK952	HK1130 HK1131	HK1068	HK1057	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 054	Piezo	No		CR/IFL19/ZEREAK50S 59130Z77AJ	Audi	A4 A6	2.7L	HK907	HK952	HK1130 HK1131	HK1068	HK1057	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 059	Piezo	No		CR/IFL19/ZEREAK50S				HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 060	Piezo	No		CR/IFL19/ZEREAK50S				HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 063	Piezo	No		CR/IFL19/ZEREAK50S	Mercedes		OM642	HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 064	Piezo	No		CR/IFL19/ZEREAK50S	Mercedes		OM642	HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 069	Piezo	No	A 646 070 1487		MB	Sprinter		HK907	HK952	HK1130 HK1131	HK1060	HK1149	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P125	x
Bosch	0445 115 077	Piezo	No		VIN WBAPN7C54AA778455	BMW	3 series	335d	HK907	HK952	HK1130 HK1131	HK1183	x	AHP5066	x	x	x	HK1124	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5066	A220P125	x
Bosch	0445 117 008	Piezo	No			Chevrolet / GMC	Duramax	6.8ltr 2011on	HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1145	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P128	x
Bosch	0445 117 010	Piezo	No			Chevrolet / GMC	Duramax	6.8ltr 2011on	HK907	HK952	HK1130 HK1131	HK1060	x	AHP5066	x	x	x	HK1145	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P128	x
Bosch	0445 117 023	Piezo	No			Ford	6.7L powerstroke		HK907	HK952	HK1130 HK1131	HK1085	HK933	AHP5066	x	x	x	HK1145	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P128	x
Bosch	0445 117 024	Piezo	No			Ford	6.7L powerstroke		HK907	HK952	HK1130 HK1131	HK1085	HK933	AHP5066	x	x	x	HK1145	x	9kN	HK907	HK1130 HK1131	A220K120	AHP5141	A220P128	x
Bosch	0445 120 002	Coil	No		CR/IPS21/ZEREK10S	Fiat IVECO Renault			HK908	HK953	HK909	HK922	x	AHP5065	x	x	HK902	x	x	9kN	HK908	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 120 003	Coil	No		CR/IFL32/ZIRIS10S	Renault		11.1ltr	HK921-T	HK954	x	HK934	x	AHP5130	x	x	HK903	x	HK936	9kN	HK921-T	x	A220K121	AHP5143	A220P118	HK936
Bosch	0445 120 004	Coil	No		CR/IFL32/ZIRIS10S	Renault		11.1ltr	HK921-T	HK954	x	HK934	x	AHP5130	x	x	HK903	x	HK936	9kN	HK921-T	x	A220K121	AHP5143	A220P118	HK936
Bosch	0445 120 006	Coil	No		CR/IFL21/ZERIS10S	MAN			HK921-T	HK954	x	HK1019	x	AHP5130	x	x	HK903	x	HK1020	9kN	HK921-T	x	A220K121	AHP5143	A220P118	HK1020
Bosch	0445 120 007	Coil	No		CR/IFS26/ZIRIS10S	Cummins			HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9kN	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 008	Coil	No		CR/IPS21/ZERES10S	GM Chevrolet	LB7 2001 - 2004.5	Duramax 2500 HD Duramax 3500	HK921-T	HK954	HK910	HK924	x	AHP5066	x	x	HK903	x	x	9kN	HK921-T	HK910	A220K121	AHP5141	A220P118	x
Bosch	0445 120 011	Coil	No		CR/IPS19/ZEREK10S	Fiat IVECO			HK908	HK953	HK909	HK973	x	AHP5065	x	x	HK902	x	x	9kN	HK908	HK909	A220K120	AHP5140	A220P115	x
Bosch	0445 120 012	Coil	No		CR/IFL21/ZERES10S	Renault			HK998		x	HK975 HK976	x	AHP5066	x	x	HK903	x	x	9kN	HK998	x	A220K120	AHP5141	A220P118	x
Bosch	0445 120 013	Coil	No		CR/IFL21/ZERES10S	Renault			HK998		x	HK975 HK976	x	AHP5066	x	x	HK903	x	x	9kN	HK998	x	A220K120	AHP5141	A220P118	x
Bosch	0445 120 018	Coil	No		CR/IFS26/ZIRIS10S	Dodge Cummins		5.9ltr	HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9kN	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 019	Coil	No		CR/IFL32/ZIRIS10S	Renault		11.1ltr	HK921-T	HK954	x	HK934	x	AHP5130	x	x	HK903	x	HK936	9kN	HK921-T	x	A220K121	AHP5143	A220P118	HK936

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC												IFT-200					
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
									Nosepiece Adaptor	Nozzle Leak Adaptor	BackLeak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	BackLeak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Bosch	0445 120 020	Coil	No		CR/IFL32/ZIRIS10S	Renault		11. ltr	HK921-T	HK954	x	HK934	x	AHP5130	x	x	HK903	x	HK936	9N	HK921-T	x	A220K121	AHP5143	A220P118	HK936
Bosch	0445 120 027	Coil	No			Chevrolet GMC	Duramax 6.6Ltr LLY 2004.5 - 2005	2500, 3500	HK907	HK952	HK909	HK1024	x	AHP5066	x	x	HK902	x	x	9N	HK907	HK909	A220K121	AHP5141	A220P115	x
Bosch	0445 120 028	Coil	No		CR/IFS26/ZIRIS10S	Cummins			HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 029	Coil	No			Komatsu			HK907	HK952	x	HK1040	x	AHP5130	x	x	HK903	x	HK1041	9N	HK907	x	A220K121	AHP5143	A220P118	HK1041
Bosch	0445 120 030	Coil	No		CR/IFL26/ZIRIS20S	MAN		7.5 ltr	HK907	HK952	x	HK991	x	AHP5130	x	x	HK903	x	HK992	9N	HK907	x	A220K121	AHP5143	A220P118	HK992
Bosch	0445 120 032	Coil	No			Dodge Cummins		5.9ltr	HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 035	Coil	No			Cummins	4940439 4940170		HK907	HK952	x	HK1040	x	AHP5130	x	x	HK903	x	HK1041	9N	HK907	x	A220K121	AHP5143	A220P118	HK1041
Bosch	0445 120 041	Coil	No		CR/IFL26/ZIRIS20S	MAN			HK907	HK952	x	HK1052	x	AHP5130	x	x	HK903	x	HK992	9N	HK907	x	A220K121	AHP5143	A220P118	HK992
Bosch	0445 120 042	Coil	No			Chevrolet GMC	Duramax 6.6Ltr LBZ 2006.5 - 2007.5	2500, 3500	HK907	HK952	HK909	HK1024	x	AHP5066	x	x	HK902	x	x	9N	HK907	HK909	A220K121	AHP5141	A220P115	x
Bosch	0445 120 044	Coil	No			MAN			HK907	HK952	x	HK1012	x	AHP5130	x	x	HK903	x	HK1016	9N	HK907	x	A220K121	AHP5143	A220P118	HK1016
Bosch	0445 120 045	Coil	No		CR/IFL26/ZIRIS10S	MAN			HK907	HK952	x	HK1012	x	AHP5130	x	x	HK903	x	HK1013	9N	HK907	x	A220K121	AHP5143	A220P118	HK1013
Bosch	0445 120 050	Coil	No	Cummins 4940095	CR/IFS26/ZIRIS30S	Dodge Cummins		6.7ltr	HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 059	Coil	No		CR/IFS26/ZIRIS10S	Cummins			HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 063	Coil	No			Sisu, Fendt		8.4ltr	HK907	HK952	x	HK1153	x	AHP5130	x	x	HK903	x	HK1154	9N	HK907	x	A220K121	AHP5143	A220P118	HK1154
Bosch	0445 120 064	Coil	No		CR/IFL26/ZIRIS20S	Deutz Renault Volvo			HK907	HK952	x	HK1044	x	AHP5066	x	x	HK903	x	HK1045	9N	HK907	x	A220K121	AHP5141	A220P118	HK1045
Bosch	0445 120 065	Coil	No		CR/IFL26/ZIRIS20S	Deutz			HK907	HK952	HK1047	HK1046	x	AHP5066	x	x	HK903	x	x	9N	HK907	HK1047	A220K120	AHP5141	A220P118	x
Bosch	0445 120 066	Coil	No		CR/IFL21/ZIRIS20S	Deutz			HK907	HK952	HK1047	HK1046	x	AHP5066	x	x	HK903	x	x	9N	HK907	HK1047	A220K120	AHP5141	A220P118	x
Bosch	0445 120 067	Coil	No		CR/IFL21/ZIRIS20S	Deutz			HK907	HK952	HK1047	HK1046	x	AHP5066	x	x	HK903	x	x	9N	HK907	HK1047	A220K120	AHP5141	A220P118	x
Bosch	0445 120 071	Coil	No	Cummins 4940096	CR/IFL26/ZIRIS10S	Dodge Cummins		6.7ltr	HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 082	Coil	No			Chevrolet GMC	Duramax 6.6Ltr LMV 2007.5 - 2010	2500, 3500	HK907	HK952	HK909	HK1024	x	AHP5066	x	x	HK902	x	x	9N	HK907	HK909	A220K121	AHP5141	A220P115	x
Bosch	0445 120 090	Coil	No			Mitsubishi			HK907	HK952	HK909	HK1162 HK1163	x	AHP5066	x	x	HK902	x	x	9N	HK907	HK909	A220K121	AHP5141	A220P115	x
Bosch	0445 120 092	Coil	No			Iveco, Case IH, New Holland	Cursor 9, CR9060	9.0ltr	HK908	HK953	HK1155	HK1156	x	AHP5066	x	x	HK903	x	x	9N	HK908	HK1155	A220K121	AHP5141	A220P118	x
Bosch	0445 120 093	Coil	No			Mitsubishi			HK907	HK952	HK909	HK1163 HK1164	x	AHP5066	x	x	HK902	x	x	9N	HK907	HK909	A220K121	AHP5141	A220P115	x
Bosch	0445 120 098	Coil	No		CR/IFL26/ZIRIS10S	MAN			HK907	HK952	x	HK1012	x	AHP5130	x	x	HK903	x	HK1013	9N	HK907	x	A220K121	AHP5143	A220P118	HK1013
Bosch	0445 120 100	Coil	No			MAN	D2676 engine	12.4ltr	HK907	HK952	x	HK991	x	AHP5130	x	x	HK903	x	HK992	9N	HK907	x	A220K121	AHP5143	A220P118	HK992
Bosch	0445 120 103	Coil	No			Dodge Cummins		5.9ltr	HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 112	Coil	No			Cummins	4940439 4940170		HK907	HK952	x	HK1040	x	AHP5130	x	x	HK903	x	HK1041	9N	HK907	x	A220K121	AHP5143	A220P118	HK1041
Bosch	0445 120 114	Coil	No			Dodge Cummins		5.9ltr	HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 125	Coil	No			Cummins	4940439 4940170		HK907	HK952	x	HK1040	x	AHP5130	x	x	HK903	x	HK1041	9N	HK907	x	A220K121	AHP5143	A220P118	HK1041
Bosch	0445 120 136	Coil	No			Deutz Renault Volvo			HK907	HK952	x	HK1044	x	AHP5066	x	x	HK903	x	HK1045	9N	HK907	x	A220K121	AHP5141	A220P118	HK1045
Bosch	0445 120 137	Coil	No			Deutz Renault Volvo			HK907	HK952	x	HK1044	x	AHP5066	x	x	HK903	x	HK1045	9N	HK907	x	A220K121	AHP5141	A220P118	HK1045
Bosch	0445 120 161	Coil	No		CR/IFL26/ZIRIS10S	Cummins			HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 184	Coil	No	Cummins 4981077	CR/IFL26/ZIRIS10S	Dodge Cummins		6.7ltr	HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 185	Coil	No	Cummins 4981076	CR/IFL26/ZIRIS10S	Dodge Cummins		6.7ltr	HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 193	Coil	No	Cummins 5253220	CR/IFL26/ZIRIS10S	Dodge Cummins		6.7ltr	HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 202	Coil	No	MAN 51.10100-6121		MAN		D2676 12.4ltr	HK907	HK952	x	HK991	x	AHP5130	x	x	HK903	x	HK992	9N	HK907	x	A220K121	AHP5143	A220P118	HK992
Bosch	0445 120 204	Coil	No	Cummins 5253221	CR/IFL26/ZIRIS10S	Dodge Cummins		6.7ltr	HK907	HK952	x	HK1014	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 208	Coil	No			Dodge Cummins		5.9ltr	HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 210	Coil	No			Dodge Cummins		5.9ltr	HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 255	Coil	No			Dodge Cummins		5.9ltr	HK907	HK952	x	HK926	x	AHP5130	x	x	HK903	x	HK928	9N	HK907	x	A220K121	AHP5143	A220P118	HK928
Bosch	0445 120 281	Coil	No	MAN 51.10100-6121		MAN		D2676 12.4ltr	HK907	HK952	x	HK991	x	AHP5130	x	x	HK903	x	HK992	9N	HK907	x	A220K121	AHP5143	A220P118	HK992

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC												IFT-200					
									1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Bosch	0445 120 311	Coil	No	MAN 51.10100-6121		MAN		D2676 12.4ltr	HK907	HK952	x	HK991	x	AHP5130	x	x	HK903	x	HK992	9kN	HK907	x	A220K121	AHP5143	A220P118	HK992
Bosch	0445 120 340	Coil	No			Sisu, Fendt		8.4ltr	HK907	HK952	x	HK1153	x	AHP5130	x	x	HK903	x	HK1154	9kN	HK907	x	A220K121	AHP5143	A220P118	HK1154
CAT / Perkins	250012401325	Coil	No		2645A718	Perkins/ CAT			HK907	HK952	x	HK1042	x	AHP5066	x	x	HK963	x	HK1043	9kN	HK907	x	A220K120	AHP5141	A220P121	HK1043
CAT / Perkins	2500398517FC	Coil	No		2645A734	CAT/ Perkins	C6.6	6.6L	HK907	HK952	x	HK1042	x	AHP5066	x	x	HK963	x	HK1043	9kN	HK907	x	A220K120	AHP5141	A220P121	HK1043
CAT / Perkins	2500491407FB	Coil	No		2645A749	Perkins/ CAT		100VK, NH1, NJ1, 1104D John Deere 4.4 ltr	HK907	HK952	x	HK1042	x	AHP5066	x	x	HK963	x	HK1043	9kN	HK907	x	A220K120	AHP5141	A220P121	HK1043
Continental	77550	Piezo	Yes			Ford	Ranger	3 litre	HK907	HK952	HK909	HK1096	HK1057	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	5WS40000-Z	Piezo	Yes			PSA		DW10TD 2.0ltr	HK907	HK952	HK909	HK945	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40057	Piezo	Yes	AZC59511315		Ford Jaguar PSA		2.7i Litre Euro 3/4	HK907	HK952	HK909	HK989	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40086	Piezo	Yes	AZC59511610		Ford		Lyrix	HK907	HK952	HK909	HK1025	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	5WS40087	Piezo	Yes	AZC59511606		Renault Nissan			HK907	HK952	HK909	HK1048	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	5WS40103	Piezo	Yes	AZC59511316		Ford Jaguar PSA	Unknown	Unknown	HK907	HK952	HK909	HK989	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40148-Z	Piezo	Yes			Ford PSA	Unknown	1.4 Litre Euro 3	HK907	HK952	HK909	HK947	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	5WS40149-Z	Piezo	Yes			Ford PSA	Unknown	1.4 Litre Euro 4	HK907	HK952	HK909	HK947	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	5WS40156-4Z	Piezo	Yes			Ford PSA Volvo		DW10B Class 4	HK907	HK952	HK909	HK949	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40156-6	Piezo	Yes	AZC59511601		Ford Volvo	Unknown	Unknown	HK907	HK952	HK909	HK949	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40156-Z	Piezo	Yes			Ford PSA Volvo	Unknown	DW10B Class 5	HK907	HK952	HK909	HK949	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40200	Piezo	Yes	AZC59511602		PSA			HK907	HK952	HK909	HK949	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40249	Piezo	Yes	AZC59511364		Ford Land Rover	Unknown	Unknown	HK907	HK952	HK909	HK989	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40250	Piezo	Yes	AZC59511611		Ford			HK907	HK952	HK909	HK1025	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	5WS40441	Piezo	Yes	AZC59511603		PSA			HK907	HK952	HK909	HK949	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	5WS40516	Piezo	Yes	AZC59511612		PSA			HK907	HK952	HK909	HK947	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	5WS40539	Piezo	Yes	AZC59513554	03L130277B	VW			HK907	HK952	HK909	HK1054	HK1011	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	AZC59513484	Piezo	Yes			Renault	K9K Euro 5		HK907	HK952	HK909	HK1048	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K120	AHP5140	A220P127	x
Continental	AZC59513552	Piezo	Yes			PSA			HK907	HK952	HK909	HK949	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	AZC59513553	Piezo	Yes			Ford	Lion V6 upgrade		HK907	HK952	HK909	HK989	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	AZC59513556	Piezo	Yes			PSA Ford Mazda Volvo	DV6C TED4	1.6ltr	HK907	HK952	HK1172	HK1171	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK1172	A220K120	AHP5140	A220P127	x
Continental	AZC59513596	Piezo	Yes			Ford	Lion V8		HK907	HK952	HK909	HK989	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	AZC59513597	Piezo	Yes			Ford	Lion V8		HK907	HK952	HK909	HK989	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK909	A220K121	AHP5140	A220P127	x
Continental	AZC59517051	Piezo	No	BK2Q-9K546-AG		Ford Mazda PSA	Ranger, Transit, Turneo BT-50 Jumper, Boxer	2.2, 3.2ltr	HK907	HK952	HK909	HK1179 HK1180	x	AHP5065	x	x	HK906	HK1122	x	9kN	HK907	HK952	A220K120	AHP5140	A220P127	x
Cummins	4954927	Coil	No	1T07142-0617	71700144	ISC		8.9ltr	HK907	HK952	x	HK1087 HK1088	x	AHP5066	x	x	HK903	x	HK1086	9kN	HK907	x	HK1174	AHP5141	A220P118	HK1086
Cummins	2872068PX	Coil	No	1T07142-0617	71700144	ISC		8.9ltr	HK907	HK952	x	HK1087 HK1088	x	AHP5066	x	x	HK903	x	HK1086	9kN	HK907	x	HK1174	AHP5141	A220P118	HK1086
Cummins	2872127PX	Coil	No	1T07142-0617	71700144	ISC		8.9ltr	HK907	HK952	x	HK1087 HK1088	x	AHP5066	x	x	HK903	x	HK1086	9kN	HK907	x	HK1174	AHP5141	A220P118	HK1086
Cummins	2882076KX	Coil	No	1T07142-0617	71700144	ISC		8.9ltr	HK907	HK952	x	HK1087 HK1088	x	AHP5066	x	x	HK903	x	HK1086	9kN	HK907	x	HK1174	AHP5141	A220P118	HK1086
Delphi	28229873	Coil	Yes			HMC A Engine (WGT)			HK907	HK952	x	HK1098 HK1110	HK1105	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K121	AHP5143	A220P119	x
Delphi	28229876	Coil	Yes			JCB			HK907	HK952	HK1120	HK1114	x	AHP5130	CR: HK917 AVM: HK1148	x	HK904	x	x	9kN	HK907	HK1120	A220K120	AHP5143	A220P116	x
Delphi	28230891	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28231014	Coil	Yes			GreatWall 4D20			HK907	HK952	x	HK1115	HK931	AHP5066	HK917	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5141	A220P119	x
Delphi	28231462	Coil	Yes			VW			HK907	HK952	HK1120	HK1098 HK1106	HK1107	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5143	A220P119	x
Delphi	28234058	Coil	Yes			Doosan			HK907	HK952	x	HK1098 HK1099	x	AHP5130	HK1112 HK1128	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5143	A220P116	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC											IFT-200						
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
									Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Delphi	28235143	Coil	Yes			Kia HMC			HK907	HK952	x	HK1098 HK1102	HK1103	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5141	A220P119	x
Delphi	28236381	Coil	Yes			HMC A Engine (VGT)			HK907	HK952	x	HK1098 HK1110	HK1105	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K121	AHP5143	A220P119	x
Delphi	28239766	Coil	Yes			GMDAT Z22D			HK907	HK952	x	HK1098 HK1104	HK1105	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5141	A220P119	x
Delphi	28239769	Coil	Yes			GMDAT Z20D			HK907	HK952	x	HK1098 HK1104	HK1105	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5141	A220P119	x
Delphi	28241030	Coil	Yes			COOPER	NA 1.2L 3Cyl		HK907	HK952	HK911	HK916	HK1005	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	28241031	Coil	Yes			COOPER	TC/Tci		HK907	HK952	HK911	HK916	HK1005	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	28247584	Coil	Yes			Yuchai	4W		HK907	HK952	HK911	HK1161	HK1004	AHP5066	HK1148	x	HK904	x	x	9kN	HK907	HK911		AHP5141	A220P116	x
Delphi	28253155	Coil	Yes			MAHINDRA	BOLERO	UPCR 2.5L 4Cyl	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	28264951	Coil	Yes			GMDAT Z22D			HK907	HK952	x	HK1098 HK1104	HK1105	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5143	A220P119	x
Delphi	28264952	Coil	Yes			GMDAT Z20D			HK907	HK952	x	HK1098 HK1104	HK1105	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5141	A220P119	x
Delphi	28269978	Coil	Yes			Daedong			HK907	HK952	x	HK1116	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	28270450	Coil	Yes			JCB	Tier4 DF12.5 128kW		HK907	HK952	HK1120	HK1114	x	AHP5130	HK1148	x	HK904	x	x	9kN	HK907	HK1120	A220K120	AHP5143	A220P116	x
Delphi	28271551	Coil	Yes			Daimler Chrysler	OM651 D22 / OM651 D	OM651	HK907	HK952	HK1120	HK1098 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28272472	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1098 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28288930	Coil	Yes			Ashok Leyland	P15	1.5L 3Cyl	HK907	HK952	x	HK916	HK1149	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	28292089	Coil	Yes			JCB	DF12.5 55kW	108kW	HK907	HK952	HK1120	HK1114	x	AHP5130	HK1148	x	HK904	x	x	9kN	HK907	HK1120	A220K120	AHP5143	A220P116	x
Delphi	28307309	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1098 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28308779	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1098 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28317158	Coil	Yes			JCB	DF12.5 55kW		HK907	HK952	HK1120	HK1114	x	AHP5130	CRI: HK917 AVM: HK1148	x	HK904	x	x	9kN	HK907	HK1120	A220K120	AHP5143	A220P116	x
Delphi	28319895	Coil	Yes			PSA			HK907	HK952	HK1135	HK1132 HK1133	HK1057	AHP5066	HK1128 HK1134	x	HK1093	x	x	9kN	HK907	HK1135	A220K120	AHP5141	A220P119	x
Delphi	28320083	Coil	Yes			TATA		3L 4SP	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	28320633	Coil	Yes			TATA		1.05L	HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	28320793	Coil	Yes			Daedong			HK907	HK952	x	HK1116	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	28332705	Coil	Yes			Kia	U2 1.1L Euro6		HK907	HK952	x	HK1098 HK1102	HK1103	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5143	A220P119	x
Delphi	28334532	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1098 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28337917	Coil	Yes			Doosan	DF12.5	2.4L TCI 3.4L TCI	HK907	HK952	x	HK1098 HK1099	x	AHP5130	HK1112 HK1128	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5143	A220P116	x
Delphi	28342997	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1098 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28347042	Coil	Yes			Doosan	DF12.5	2.4L TCI 3.4L TCI	HK907	HK952	x	HK1098 HK1099	x	AHP5130	HK1112 HK1128	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5143	A220P116	x
Delphi	28348371	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1098 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	28361287	Coil	Yes			JCB	Tier3 6Cyl DF12.5		HK907	HK952	HK1120	HK1114	x	AHP5130	HK1148	x	HK904	x	x	9kN	HK907	HK1120	A220K120	AHP5143	A220P116	x
Delphi	28368960	Coil	Yes			PSA			HK907	HK952	HK1135	HK1132 HK1133	HK1057	AHP5066	HK1134	x	HK1093	x	x	9kN	HK907	HK1135	A220K120	AHP5141	A220P119	x
Delphi	28424049	Coil	Yes			VW		1.4 ltr	HK907	HK952	HK1178	HK1098 HK1177	HK1004	AHP5066	HK1176	x	HK1175	x	x	9kN	HK907	HK1178	A220K120	AHP5141	A220P122	x
Delphi	EJBR00801Z	Coil	Yes			Ford		1.8 TDCi	HK907	HK952	x	HK916	HK930	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR00901Z	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01001A	Coil	Yes			Suzuki Citroen			HK907	HK952	HK911	HK916	HK933	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJBR01001Z	Coil	Yes			Suzuki Citroen			HK907	HK952	HK911	HK916	HK933	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJBR01101Z	Coil	Yes			Ford		1.8TDCi	HK907	HK952	x	HK916	HK930	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01201Z	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01301Z	Coil	Yes			Ford		1.8 TDCi	HK907	HK952	x	HK916	HK930	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01302Z	Coil	Yes			Ford		1.8 TDCi	HK907	HK952	x	HK916	HK930	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01401Z	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC											IFT-200						
									1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Delphi	EJBR01501Z	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01601Z	Coil	Yes			Ford		1.8TDCi	HK907	HK952	x	HK916	HK930	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01701Z	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01801A	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01801Z	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR01901Z	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02001Z	Coil	Yes			Ford		1.8TDCi	HK907	HK952	x	HK916	HK930	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02101Z	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02201Z	Coil	Yes			Ford		1.8TDCi	HK907	HK952	x	HK916	HK930	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02301Z	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02401Z	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02501Z	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02601Z	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02701Z	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02801D	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR02901D	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03001D	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03101D	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03201D	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03301D	Coil	Yes			JMC TATA			HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03401Z	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03501D	Coil	Yes			JMC TATA			HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03601D	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03701D	Coil	Yes			Kia		2.9 HPDi	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03801D	Coil	Yes			PSA			HK907	HK952	HK911	HK1001	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJBR03901D	Coil	Yes			Hyundai Kia		2.9L	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR03902D	Coil	Yes			Hyundai Kia		2.9L	HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04001D	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04101D	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04201D	Coil	Yes			Daimler Chrysler			HK907	HK952	HK911	HK916	HK1004	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJBR04301D	Coil	Yes			TATA			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04401D	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04401Z	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04501D	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04501Z	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04601Z	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04701Z	Coil	Yes			SsangYong			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR04901D	Coil	Yes			TATA			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR05001D	Coil	Yes			JCB		4.4L	HK907	HK952	HK911	HK987	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC											IFT-200						
									1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Delphi	EJBR05101D	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR05102D	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR05201D	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR05301D	Coil	Yes			YUCHAI			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR05501D	Coil	Yes			Hyundai Kia	2.9L		HK907	HK952	x	HK916	HK931	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR05601D	Coil	Yes			Renault Nissan Suzuki			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR05701D	Coil	Yes			TATA			HK907	HK952	x	HK916	HK932	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR06001D	Coil	Yes			PSA			HK907	HK952	HK911	HK1001	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJBR06101D	Coil	Yes			YUCHAI			HK907	HK952	x	HK916	x	AHP5066	HK917	x	HK904	x	x	9kN	HK907	x	A220K120	AHP5141	A220P116	x
Delphi	EJBR06201D	Coil	Yes						HK907	HK952	HK911	HK916	HK1005	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00001Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00002Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00101Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00201Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00202Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00301Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00401Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00402Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00403Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00501Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00502Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00503Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00504Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00601Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00701D	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00801D	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR00801Z	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	HK929	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR01001D	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EJDR01101D	Coil	Yes			Ford	2.0 TDCi		HK907	HK952	HK911	HK920	x	AHP5066	HK917	x	HK904	x	x	14kN	HK907	HK911	A220K120	AHP5141	A220P116	x
Delphi	EMBR00001D	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1008 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	EMBR00002D	Coil	Yes			Daimler Chrysler		OM651	HK907	HK952	HK1120	HK1008 HK1100	HK1101	AHP5066	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P119	x
Delphi	EMBR00101D	Coil	Yes			PSA			HK907	HK952	HK1120	HK1091	HK1004	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P116	x
Delphi	EMBR00101DP	Coil	Yes			PSA			HK907	HK952	HK1120	HK1091	HK1004	AHP5066	HK917	x	HK904	x	x	9kN	HK907	HK1120	A220K120	AHP5141	A220P116	x
Delphi	EMBR00201D	Coil	Yes	2		Kia HMC			HK907	HK952	x	HK1098 HK1102	HK1103	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5143	A220P119	x
Delphi	EMBR00202D	Coil	Yes			Kia HMC			HK907	HK952	x	HK1098 HK1102	HK1103	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5143	A220P119	x
Delphi	EMBR00203D	Coil	Yes			Kia HMC			HK907	HK952	x	HK1098 HK1102	HK1103	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5143	A220P119	x
Delphi	EMBR00301D	Coil	Yes			SsangYong			HK907	HK952	x	HK1098 HK1108	HK1103	AHP5130	HK1112 HK1128	x	HK1093	x	x	9kN	HK907	x	A220K120	AHP5143	A220P119	x
Denso	095000-014x	Coil	No			Isuzu		6HK1	HK921-T	HK954	HK1007	HK1008	x	AHP5066	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K120	AHP5141	A220P121	x
Denso	095000-023x	Coil	No						HK984-T		HK994	HK1027	x	AHP5066	x	x	HK963	x	x	9kN	HK984-T	HK994	A220K121	AHP5141	A220P121	x
Denso	095000-042x (-057x)	Coil	No		23670-27030	Toyota	Avenis Avenis Verso Prius RAV4		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC										IFT-200							
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
									Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Denso	095000-043x (-064x)	Coil	No		23670-29025	Toyota	Corolla		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-051x	Coil	No		16600-8H80x	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail		HK907	HK952	HK910	HK996	x	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-052x (-074x)	Coil	No		23670-39015	Toyota	Land-Cruiser		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK959	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P120	x
Denso	095000-053x (-075x)	Coil	No		23670-39025	Toyota	Land-Cruiser		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-054x	Coil	No	PKW2 R9 B2		John Deere			HK907	HK952	HK910	HK1065	x	AHP5130	x	x	HK963	x	HK1066, HK1185	9kN	HK907	HK910	A220K121	AHP5143	A220P121	HK1066, HK1185
Denso	095000-056x	Coil	No		62181-13100 62181-13101	Komatsu			HK921-T	HK954	HK962	HK964	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK962	A220K121	AHP5143	A220P121	x
Denso	095000-058x	Coil	No			Hino			HK984-T		HK910	HK993	x	AHP5066	x	x	HK963	x	x	9kN	HK984-T	HK910	A220K121	AHP5141	A220P121	x
Denso	095000-063x (-095x)	Coil	No		23670-39045	Toyota	Dyna		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK959	x	x	9kN	HK907	HK910	A220K121	AHP5140	A220P120	x
Denso	095000-072x	Coil	No						HK1191		HK1192	HK1190	x	AHP5130	x	x	HK963	x	x	9kN	HK1191	HK1192	A220K121	AHP5143	A220P121	x
Denso	095000-076x	Coil	No		10F0225	Isuzu		6SD1	HK907	HK952	HK1007	HK1061	x	AHP5066	x	x	HK905	x	x	9kN	HK907	HK1007	A220K121	AHP5141	A220P117	x
Denso	095000-077x (-094x)	Coil	No		23670-39035	Toyota	4Runner Dyna Place HiLux Tiger 2.5i		HK907	HK952	HK910	HK997 HK956	HK932	HK958	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-080x	Coil	No		61561-13100	Komatsu			HK921-T	HK954	HK962	HK960	x	AHP5066	x	x	HK963	x	x	9kN	HK921-T	HK962	A220K121	AHP5141	A220P121	x
Denso	095000-088x	Coil	No		16600-AU600	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail		HK907	HK952	HK910	HK996	x	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-121x	Coil	No		05H0217	Komatsu / Perkins			HK984-T		HK962	HK1055	x	AHP5066	x	x	HK963	x	x	9kN	HK984-T	HK962	A220K121	AHP5141	A220P121	x
Denso	095000-500x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x
Denso	095000-501x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x
Denso	095000-503x	Coil	No			Mazda	MPV6		HK907	HK952	HK1006	HK1023 HK1117	x	AHP5130	x	x	HK963	x	x	9kN	HK907	HK1006	HK1174	AHP5143	A220P121	x
Denso	095000-505x	Coil	Yes	RE507860 RE520240		John Deere			HK907	HK952	AM: x OE: HK910	HK966	x	AHP5130	x	x	HK963	x	AM: HK968 OE: HK1185, HK1185	AM: 9kN OE: 7kN	HK907	x	A220K120	AHP5143	A220P121	AM: HK968
Denso	095000-508x	Coil	Yes		97313861	Vauxhall/ Opel			HK907	HK952	HK1006	HK1007	x	AHP5129	x	AHP4004	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	A220K120	AHP5142	A220P117	x
Denso	095000-512x (-542x)	Coil	No		23670-0G010, 23670-09030	Toyota	Avenis Avenis Verso Corolla Corolla Verso		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	A220K120	AHP5140	A220P117	x
Denso	095000-513x	Coil	No		16600-AW40x	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail		HK907	HK952	HK910	HK996	x	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-515x	Coil	No			John Deere			HK907	HK952	HK910	HK1065	x	AHP5130	x	x	HK963	x	HK1066 HK1185	9kN	HK907	HK910	A220K121	AHP5143	A220P121	HK1066 HK1185
Denso	095000-516x	Coil	Yes			John Deere			HK907	HK952	HK910	HK1065	x	AHP5130	x	AHP4024	HK963	x	HK1066 HK1185	OE: 7kN AM: 9kN	HK907	HK910	A220K121	AHP5143	A220P121	HK1066 HK1185
Denso	095000-518x	Coil	No		16600-8N80x	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail	YD22	HK907	HK952	HK910	HK996	x	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-519x	Coil	Yes			John Deere			HK907	HK952	HK910	HK1065	x	AHP5130	x	AHP4024	HK963	x	HK1066 HK1185	OE: 7kN AM: 9kN	HK907	HK910	A220K121	AHP5143	A220P121	HK1066 HK1185
Denso	095000-520x	Coil	Yes			John Deere			HK907	HK952	HK910	HK1065	x	AHP5130	x	AHP4024	HK963	x	HK1066 HK1185	OE: 7kN AM: 9kN	HK907	HK910	A220K121	AHP5143	A220P121	HK1066 HK1185
Denso	095000-521x	Coil	Yes			Hino			HK984-T		HK994	HK1027	x	AHP5066	x	AHP4015	HK963	x	x	OE: 7kN AM: 9kN	HK984-T	HK994	A220K121	AHP5141	A220P121	x
Denso	095000-522x	Coil	Yes			Hino			HK921-T	HK954	HK994	HK1073	x	AHP5066	x	AHP4020	HK963	x	x	OE: 7kN AM: 9kN	HK921-T	HK994	A220K121	AHP5141	A220P121	x
Denso	095000-523x	Coil	Yes			John Deere			HK907	HK952	HK910	HK1065	x	AHP5130	x	AHP4024	HK963	x	HK1066 HK1185	OE: 7kN AM: 9kN	HK907	HK910	A220K121	AHP5143	A220P121	HK1066 HK1185
Denso	095000-526x (-558x)	Coil	No		23670-027050 (23670-29045)	Toyota	Avenis Corolla		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	A220K120	AHP5140	A220P117	x
Denso	095000-528x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK910	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7kN AM: 9kN	HK984-T	HK910	A220K121	AHP5143	A220P121	x
Denso	095000-532x	Coil	Yes			Hino			HK907	HK952	HK910	HK1165	x	AHP5130	x	AHP4025	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	A220K120	AHP5143	A220P117	x
Denso	095000-534x	Coil	Yes			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	AHP4003	HK963	x	x	OE: 7kN AM: 9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x
Denso	095000-535x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC												IFT-200					
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
									Nosepiece Adaptor	Nozzle Leak Adaptor	BackLeak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	BackLeak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Denso	095000-536x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x
Denso	095000-539x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK910	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7kN AM: 9kN	HK984-T	HK910	A220K121	AHP5143	A220P121	x
Denso	095000-544x (-592x)	Coil	Yes			Toyota	Hiace		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-545x	Coil	No						HK1191		HK1192	HK1190	x	AHP5130	x	x	HK963	x	x	9kN	HK1191	HK1192	A220K121	AHP5143	A220P121	x
Denso	095000-547x	Coil	Yes			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	AHP4003	HK963	x	x	OE: 7kN AM: 9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x
Denso	095000-548x	Coil	Yes			John Deere			HK907	HK952	AM: x OE: HK910	HK966	x	AHP5130	x	x	HK963	x	AM: HK968 OE: HK1189, HK1185	AM: 9kN OE: 7kN	HK907	x	A220K120	AHP5143	A220P121	AM: HK968
Denso	095000-551x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1056	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K121	AHP5143	A220P121	x
Denso	095000-552x (-593x)	Coil	Yes		23670-0L010 (23670-09060)	Toyota	Hiace		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-555x	Coil	Yes			Hyundai			HK907	HK952	HK1006	HK1139	x	AHP5066	x	AHP4017	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	A220K120	AHP5141	A220P117	x
Denso	095000-560x	Coil	Yes		1465A041	Mitsubishi	L200	4D56 2.5i	HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-561x (-611x)	Coil	Yes		23670-09130	Toyota	Avenis		HK907	HK952	HK910	HK997 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-565x	Coil	Yes		16600-EB300	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail		HK907	HK952	HK910	HK996	x	AHP5065	x	AHP4006	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-566x	Coil	Yes			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-574x (-589x)	Coil	Yes		23670-30080 (23670-39135)	Toyota	Land-Cruiser		HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-576x	Coil	Yes		1465A054	Mitsubishi		4M41 3.2i	HK907	HK952	HK910	HK997 HK956	HK1000	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-578x	Coil	Yes			MAZDA			HK907	HK952	HK910	HK1144	HK1011	AHP5130	x	AHP4016	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5143	A220P117	x
Denso	095000-580x	Coil	Yes		6C1Q-9K546-AC	Citroen Fiat Ford Land Rover Peugeot	Jumpier 2.2ltr Ducato 2.2ltr Transit 2.2 & 2.4ltr Defender 2.4ltr Boxer 2.2 & 2.4ltr		HK907	HK952	HK1006	HK997 HK956	HK1009	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	HK1173	AHP5140	A220P117	x
Denso	095000-581x	Coil	Yes		6C1Q-9K546-8B	Citroen Fiat Ford Land Rover Peugeot	Jumpier 2.2ltr Ducato 2.2ltr Transit 2.2 & 2.4ltr Defender 2.4ltr Boxer 2.2 & 2.4ltr		HK907	HK952	HK1006	HK997 HK956	HK1009	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	HK1173	AHP5140	A220P117	x
Denso	095000-583x	Coil	Yes	9-97353080-0		Opel, Renault, Saab	Signum, Vectra, Espace/Vel satia, 9-5	3.0tr V6	HK907	HK952	HK1007	HK1167	x	AHP5065	x	AHP4028	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1007	HK1173	AHP5140	A220P117	x
Denso	095000-588x	Coil	No		23670-30050	Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-599x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK910	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7kN AM: 9kN	HK984-T	HK910	A220K121	AHP5143	A220P121	x
Denso	095000-602x	Coil	Yes		16600-ES60x	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail		HK907	HK952	HK910	HK996	x	AHP5065	x	AHP4006	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-603x	Coil	Yes			Hyundai			HK907	HK952	HK1006	HK1139	x	AHP5066	x	AHP4017	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	A220K120	AHP5141	A220P117	x
Denso	095000-604x (-623x)	Coil	Yes		23670-09140	Toyota	Corolla Verso RAV4		HK907	HK952	HK910	HK997 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-613x	Coil	Yes			Isuzu/Opel			HK907	HK952	HK1006	HK1097	x	AHP5065	x	AHP4009	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	A220K120	AHP5140	A220P117	x
Denso	095000-624x	Coil	Yes		16600-MB40#	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail		HK907	HK952	HK910	HK996	x	AHP5065	x	AHP4006	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-625x	Coil	Yes		16600-EC00#	Nissan	Almera Cabstar Pathfinder Primera Navara X-Trail		HK907	HK952	HK910	HK996	x	AHP5065	x	AHP4006	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-627x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1056	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K121	AHP5143	A220P121	x
Denso	095000-630x	Coil	No			Isuzu Perkins			HK921-T	HK954	HK1007	HK1056	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K121	AHP5143	A220P121	x
Denso	095000-631x	Coil	Yes			John Deere			HK907	HK952	HK994	HK1166	x	AHP5065	x	AHP4027	HK963	x	x	OE: 7kN AM: 9kN	HK907	HK994	A220K120	AHP5140	A220P121	x
Denso	095000-635x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK910	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7kN AM: 9kN	HK984-T	HK910	A220K121	AHP5143	A220P121	x
Denso	095000-636x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x
Denso	095000-638x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	x	HK963	x	x	9kN	HK921-T	HK1007	A220K120	AHP5143	A220P121	x

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC											IFT-200							
									1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6	
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	Nosepiece Adaptor	Nozzle Leak Adaptor	BackLeak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	BackLeak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve	
Denso	095000-639x	Coil	No			Isuzu			HK921-T	HK954	HK1007	HK1008	x	AHP5130	x	x	HK963	x	x	9N	HK921-T	HK1007	A220K120	AHP5143	A220P121	x	
Denso	095000-649x	Coil	Yes			John Deere			HK907	HK952	AM: x OE: HK910	HK966	x	AHP5130	x	x	HK963	x	AM: HK968 OE: HK1189, HK1185	AM: 9N OE: 7N	HK907	x	A220K120	AHP5143	A220P121	AM: HK968	
Denso	095000-650x	Coil	Yes			John Deere			HK907	HK952	AM: x OE: HK910	HK966	x	AHP5130	x	x	HK963	x	AM: HK968 OE: HK1189, HK1185	AM: 9N OE: 7N	HK907	x	A220K120	AHP5143	A220P121	AM: HK968	
Denso	095000-651x	Coil	Yes			Hino			HK907	HK952	HK910	HK1165	x	AHP5129	x	AHP4026	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	A220K120	AHP5142	A220P117	x	
Denso	095000-652x	Coil	Yes			Hino			HK907	HK952	HK910	HK1165	x	AHP5129	x	AHP4026	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	A220K120	AHP5142	A220P117	x	
Denso	095000-659x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK994	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7N AM: 9N	HK984-T	HK994	A220K121	AHP5143	A220P121	x	
Denso	095000-660x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK994	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7N AM: 9N	HK984-T	HK994	A220K121	AHP5143	A220P121	x	
Denso	095000-662x	Coil	Yes			Citroen Fiat Ford Land Rover Peugeot	Jumpier 2.2ltr Ducato 2.2ltr Transit 2.2 & 2.4ltr Defender 2.4ltr Boxer 2.2 & 2.4ltr		HK907	HK952	HK1006	HK907 HK956	HK1009	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK1006	HK1173	AHP5140	A220P117	x	
Denso	095000-670x	Coil	Yes			Zyu-Gata Kisha			HK921-T	HK954	HK1007	HK1008	HK1057	AHP5066	x	AHP4007	HK963	x	x	OE: 7N AM: 9N	HK921-T	HK1007	A220K120	AHP5141	A220P121	x	
Denso	095000-675x	Coil	No			Hino	Unknown	Unknown	HK984-T		HK910	HK993	x	AHP5130	x	x	HK963	x	x	9N	HK984-T	HK910	A220K121	AHP5143	A220P121	x	
Denso	095000-676x (-703x)	Coil	Yes		23670-30140 (23670-39185)	Toyota	Hilux		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-679x	Coil	Yes			Shanghai Diesel			HK907	HK952	HK910	HK1058	x	AHP5066	x	AHP4008	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	A220K120	AHP5141	A220P117	x	
Denso	095000-681x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK994	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7N AM: 9N	HK984-T	HK994	A220K121	AHP5143	A220P121	x	
Denso	095000-692x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK910	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7N AM: 9N	HK984-T	HK910	A220K121	AHP5143	A220P121	x	
Denso	095000-698x	Coil	Yes		98011604	Isuzu	Unknown		HK907	HK952	HK1006	HK1002 HK1003	x	AHP5066	x	AHP4012	HK905	x	x	OE: 7N AM: 9N	HK907	HK1006	HK1173	AHP5141	A220P117	x	
Denso	095000-699x	Coil	Yes		98011605	Isuzu		3.0 ltr	HK907	HK952	HK1006	HK1002 HK1003	x	AHP5066	x	AHP4012	HK905	x	x	OE: 7N AM: 9N	HK907	HK1006	HK1173	AHP5141	A220P117	x	
Denso	095000-705x	Coil	Yes			Shanghai Diesel			HK907	HK952	HK910	HK1186	HK1187	x	AHP5130	x	AHP4022	HK963	x	HK1188 HK1185	OE: 7N AM: 9N	HK907	HK910	A220K121	AHP5143	A220P121	HK1188 HK1185
Denso	095000-706x	Coil	Yes		6c1Q-9K546-BC	Citroen Fiat Ford Land Rover Peugeot	Jumpier 2.2ltr Ducato 2.2ltr Transit 2.2 & 2.4ltr Defender 2.4ltr Boxer 2.2 & 2.4ltr		HK907	HK952	HK1006	HK907 HK956	HK1009	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK1006	HK1173	AHP5140	A220P117	x	
Denso	095000-714x	Coil	Yes		33800-5200#	Hyundai		Mighty, Mega Truck, County	HK907	HK952	HK1170	HK1169	x	AHP5130	x	AHP4013	HK963	x	x	OE: 7N AM: 9N	HK907	HK1170	A220K120	AHP5143	A220P121	x	
Denso	095000-716x	Coil	Yes			MAZDA			HK907	HK952	HK910	HK1144	HK1011	AHP5130	x	AHP4016	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5143	A220P117	x	
Denso	095000-721x (-722x)	Coil	Yes			Toyota	Avenis		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-738x (-739x)	Coil	Yes			Toyota	Hiace		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-749x	Coil	Yes			Mitsubishi			HK907	HK952	HK910	HK907 HK956	HK1000	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	A220K121	AHP5140	A220P117	x	
Denso	095000-750x	Coil	Yes			Mitsubishi			HK907	HK952	HK910	HK907 HK956	HK1000	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	A220K121	AHP5140	A220P117	x	
Denso	095000-754x (-778x)	Coil	Yes			Toyota	Hiace		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-755x (-758x)	Coil	Yes			Toyota	Avenis		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-756x	Coil	Yes			John Deere			HK907	HK952	HK910	HK1065	x	AHP5130	x	AHP4024	HK963	x	HK1066 HK1185	OE: 7N AM: 9N	HK907	HK910	A220K121	AHP5143	A220P121	HK1066 HK1185	
Denso	095000-760x (-761x)	Coil	Yes			Toyota	Avenis		HK907	HK952	HK910	HK907 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-763x (-764x)	Coil	Yes			Toyota	RAV4		HK907	HK952	HK910	HK907 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-766x (-767x)	Coil	Yes			Toyota	Avenis		HK907	HK952	HK910	HK907 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-768x (-769x)	Coil	Yes			Toyota	Avenis		HK907	HK952	HK910	HK907 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-770x (-771x)	Coil	Yes			Toyota	Land Cruiser		HK907	HK952	HK910	HK907 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-772x (-773x)	Coil	Yes			Toyota	Land-Cruiser		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-775x (-776x)	Coil	Yes			Toyota	Hiace		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-779x (-780x)	Coil	Yes			Toyota	Hiace		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	x	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-781x (-782x)	Coil	Yes			Toyota	Dyna		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-783x (-784x)	Coil	Yes			Toyota	Dyna		HK907	HK952	HK910	HK907 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5140	A220P117	x	
Denso	095000-786x	Coil	Yes			MAZDA			HK907	HK952	HK910	HK1144	HK1011	AHP5130	x	AHP4016	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	HK1173	AHP5143	A220P117	x	
Denso	095000-789x	Coil	Yes			Subaru			HK907	HK952	HK910	HK1141 HK1142	x	AHP5065	x	AHP4018	HK905	x	x	OE: 7N AM: 9N	HK907	HK910	A220K121	AHP5140	A220P117	x	

CR INJECTOR APPLICATION									AVM2-PC, CRI-PC											IFT-200						
OE Manufacturer	Injector P/N	Elec Type: Coil / Piezo	OE-Approved Test	X ref	Type Code (Bosch) Carmaker Code (Denso)	VM	VM Range	VM Model	1a	1b	2	3a	3b	4a	4b	4c	5a	5b	6	7	1a	2	3	4	5	6
									Nosepiece Adaptor	Nozzle Leak Adaptor	Backleak Adaptor	Clamp Block & Adaptor	Clamp Spacer	HP (Flexible) Pipes (ALL MAKES)	HP (Rigid) Pipes - 19cc (Delphi OE only)	HP (Rigid) Pipes - 400cc (Denso OE only)	Cable (AVM2, standard CRI-PC)	Cable (CRI-PC with HJ064)	Fuelling Sleeve	Clamp Load Spacer	Nosepiece Adaptor	Backleak Adaptor	Clamp Plate / Disc	HP (Flexible) Pipes	Cable	Fuel Sleeve
Denso	095000-793x		Yes			Ford			HK907	HK952	HK1006	HK997 HK956	HK1009	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	HK1173	AHP5140	A220P117	x
Denso	095000-801x	Coil	Yes			Zyu-Gata Kisha			HK921-T	HK954	HK1007	HK1008	HK1057	AHP5066	x	AHP4007	HK963	x	x	OE: 7kN AM: 9kN	HK921-T	HK1007	A220K120	AHP5141	A220P121	x
Denso	095000-805x (-806x)	Coil	Yes			Toyota	Avenis		HK907	HK952	HK910	HK997 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-809x	Coil	Yes			Hino	Unknown	Unknown	HK984-T		HK994	HK993	x	AHP5130	x	AHP4005	HK963	x	x	OE: 7kN AM: 9kN	HK984-T	HK994	A220K121	AHP5143	A220P121	x
Denso	095000-810x	Coil	Yes			Zyu-Gata Kisha			HK921-T	HK954	HK994	HK1059	x	AHP5066	x	AHP4010	HK905	x	x	OE: 7kN AM: 9kN	HK921-T	HK994	A220K121	AHP5141	A220P117	x
Denso	095000-811x	Coil	Yes			Mitsubishi			HK907	HK952	HK910	HK997 HK956	HK1000	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	A220K121	AHP5140	A220P117	x
Denso	095000-816x	Coil	No			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-822x (-829x)	Coil	Yes			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-838x	Coil	Yes			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-839x	Coil	Yes			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-849x	Coil	No			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	x	HK905	x	x	9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-850x	Coil	Yes			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-856x	Coil	Yes			Toyota			HK907	HK952	HK910	HK997 HK956	HK932	AHP5065	x	AHP4001	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	095000-882x	Coil	Yes			John Deere			HK907	HK952	HK994	HK1166	x	AHP5065	x	AHP4027	HK963	x	x	OE: 7kN AM: 9kN	HK907	HK994	A220K120	AHP5140	A220P121	x
Denso	095000-973 (-978x)	Coil	Yes			Toyota			HK907	HK952	HK910	HK997 HK956	HK957	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	295050-001x	Coil	Yes			MAZDA			HK907	HK952	HK1006	HK1151	x	AHP5065	x	AHP4019	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	A220K120	AHP5140	A220P117	x
Denso	295050-012x	Coil	Yes			Mitsubishi			HK907	HK952	HK1006	HK1152	x	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	A220K120	AHP5140	A220P117	x
Denso	295050-025x	Coil	Yes			Subaru			HK907	HK952	HK910	HK1141 HK1142	x	AHP5065	x	AHP4018	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	A220K121	AHP5140	A220P117	x
Denso	295050-030x	Coil	Yes	16600-5X00#		Nissan	Pathfinder, Murano, Navara	2.5ltr	HK907	HK952	HK910	HK1168	HK932	AHP5065	x	AHP4006	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	295050-032x	Coil	Yes			Isuzu			HK921-T	HK954	HK1007	HK1193	x	AHP5066	x	AHP4029	HK963	x	x	OE: 7kN AM: 9kN	HK921-T	HK1007	A220K120	AHP5066	A220P121	x
Denso	295050-034x	Coil	Yes			Mitsubishi			HK907	HK952	HK1006	HK1152	x	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK1006	A220K120	AHP5140	A220P117	x
Denso	295050-056x	Coil	Yes	1465A351		Mitsubishi	Pajero Montero		HK907	HK952	HK910	HK997 HK956	HK1000	AHP5065	x	AHP4002	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	A220K121	AHP5140	A220P117	x
Denso	295050-064x	Coil	Yes			Hyundai			HK907	HK952	HK1170	HK1169	x	AHP5130	x	AHP4013	HK963	x	x	OE: 7kN AM: 9kN	HK907	HK1170	A220K120	AHP5143	A220P121	x
Denso	295050-105x	Coil	Yes	16600-5X00#		Nissan	Pathfinder, Murano, Navara	2.5ltr	HK907	HK952	HK910	HK1168	HK932	AHP5065	x	AHP4006	HK905	x	x	OE: 7kN AM: 9kN	HK907	HK910	HK1173	AHP5140	A220P117	x
Denso	295900-001x (-002x)	Piezo	No		23670-26011	Lexus Toyota	LS220 Avenis, Auris, Corolla, RAV4														HK907	HK910	HK1173	AHP5140	A220P126	x
Denso	295900-003x	Piezo	No		23670-0R040	Lexus Toyota	LS220 Avenis, Auris, Corolla, RAV4														HK907	HK910	HK1173	AHP5140	A220P126	x
Denso	295900-010x (-011x)	Piezo	No		23670-26020	Lexus Toyota	LS220 Avenis, Auris, Corolla, RAV4														HK907	HK910	HK1173	AHP5140	A220P126	x
PurePower Technologies	1875072C91	Piezo	No			Ford	Unknown	Powerstroke 6.4L	HK1053-T		HK1017	HK1015	x	AHP5130	x	x	HK1026	HK1184	x	9kN	HK1053-T	HK1017	A220K120	AHP5143	A220P129	x