

Profile



©2010 National Coatings Corporation.
All Rights Reserved.

NATIONAL PRINTING PLATE

Size: 18,350 Square Feet

Location: Indianapolis, Indiana

Challenge *Aged EPDM Roof*

- Numerous Leaks.
- Failing Seams.
- Excessive Membrane Surface Temperatures.

Solution *AcryShield® Restoration System*

- Reinforced Seams.
- Improved Coating Adhesion Technology.
- Cooling Energy Savings.
- HVAC Maintenance Easier on Cooler Roof.

National Printing Plate chose the latest in innovative RubberPrep™/AcryShield® technology to prolong the leak-free life of their 10-year old EPDM roof.



**NATIONAL
COATINGS**

1201 Calle Suerte, Camarillo, CA 93012
(800) 423-9557, Fax (800) 294-3866

www.nationalcoatings.com, info@nationalcoatings.com