

CONTENTS

▲ A-optimal designs Accelerated life tests Acceptance control charts Acceptance sampling Adjusted R-squared Adjusted residuals Agglomeration distance plot Agreement plot Akaike's information criterion Algorithmic cusum chart Alias matrix All-possible regressions Alpha plot Alpha and beta risks Analysis of covariance Analysis of deviance Analysis of means Analysis of variance Oneway & multifactor, GLM Repeated measures designs

Variance components Anderson-Darling test Andrews plot Annual subseries plot AOQ curve AOQL Plans Appraiser variation

AQL ARIMA control chart ARIMA models Arrhenius plot ASN function ATI curve Autocorrelations Automatic forecasting Autoregressive models Average run length

R Barcharts Bartlett's equal variance test Bartlett's sphericity test Bernoulli distribution Beta distribution

Bias analysis and correction BIB designs

Bicubic splines Binomial distribution

Birnbaum-Saunders distribution Bivariate capability analysis Bonferroni intervals

Bivariate density Bivariate normal distribution Blocked designs

Bootstrap intervals Box-and-whisker plots

Bollinger bands

Box-Behnken designs Box-Cox transformations

Box-Pierce test

Brushing Bubble chart Buy-sell indicators

C C charts Capability analysis Capability indices CCpk, Cp, Cpk, Cpm DPM, CM, CK, K Non-normal indices

Sigma quality level Within and between 7-scores

Calibration models Canonical correlations Candlestick plot Canonical variables plot

Capability ellipse

Casement plot Cauchy distribution Cause-and-effect diagram Censored data analysis

Central composite designs Chernoff faces

Chi-square decomposition Chi-square distribution

Chi-squared test City-block distance

Classification functions

Classification plot Cluster analysis

Furthest and nearest neighbor

Ward's method k-means

Cochrane-Orcutt transformation Coded scatterplot

Coefficient of variation

Collapse design

Comparison of regression slopes Completely randomized designs

Component line chart

Communality .

Compare proportions and rates Comparison of correlation coefficients

Comparison of means and medians Comparison of standard deviations

Component deviation plot Component effects plot Component extraction

Component loadings Components of variance

Computer-generated experiments Conditional gamma

Conditional sums of squares Confounding pattern

Consumer and producer risk

Confidence bounds & intervals
Contingency coefficient

Contingency tables

Contour plot Contrasts

Control chart design

Control ellipse

Control to standard Cook's distance

Correlations

Correspondence analysis

Correspondence map

Corrgram

Cost of quality trend analysis Covariances

Covariates

Cox proportional hazards

Cox-Snell residuals

Cramer's V

Cramer-Von Mises statistic

Cross-correlations Crosstabulation

Cumulative distributions

Cumulative event plot

Critical values Cronbach's alpha

Cross-validation

Cube plot

Cubic spline Cumulative failures plot Cumulative hazard function

Cumulative Pareto chart Cumulative score charts Cumulative survival function

Curve fitting Cuscore charts

CuSum charts

D-efficiency D-optimal designs Data tapers

Death density function

Deleted residuals

Demographics map Dendrograms

Density function

Density trace

Design of experiments

Analysis

Augmentation

Computer generated designs

Creation

Design resolution

Desirability functions

Multiple-variable optimization

Diagnostic plots

Discrete uniform distribution

Discriminant analysis

Discriminant functions plot

Dispersion dashboard

Dispersion index test

Distance graphs

Distribution fitting

Censored or uncensored data Distribution-free tolerance limits

Dixon's outlier test

Dot diagram

Draftsman's plot

Draper-Lin designs Duncan's test

Dunnett's procedure

Durbin-Watson statistic

EDF tests

Eigenvalues

Equimax rotation

Erlang distribution

Euclidian distance

Event plot

Event rate estimation EWMA charts

EWMA decomposition

Expected mean squares
Exponential distribution

Exponential models Exponential power distribution

Exponential smoothing

Brown's, Holt's, Winters' seasonal

Extrapolation

Extreme value distribution

Extreme value plot

Extreme vertices designs

F distribution

F test

Factor analysis

Factor means plot

Factor plots

Factorability tests

Factorial designs

Failure rate statistics

False alarm rate

Financial plots Fishbone diagram

Fisher's exact test for 2x2 tables

Fisher's LSD intervals

Fixed and random factors

Folded normal distribution Folded Plackett-Burman designs

Forecasting

Fraction of design space plot

Fractal

Fractional factorial designs

Freedman-Diaconis rule Frequency histogram and table

Frequency polygon Frequency tabulation

Friedman test

G G chart

G-optimal designs

Gage accuracy and linearity

Gage performance plot Gage studies

Games-Howell method

Gamma distribution

Gauss-Newton method

General linear models

Generalized gamma distribution

Generalized logistic distribution Generalized variance chart

Geometric distribution Geometric mean

Geospatial data analysis

Glyphs

Goodness-of-fit tests

Gradient map

Graeco-Latin squares

Graphical ANOVA

Greenhouse-Geisser correction

Growth curve

Grubbs' outlier test

H-K chart Half-normal distribution

Half-normal plots Hannan-Quinn criterion

Hanning

Hartley's test

Hazard functions

Henderson's moving average

Hierarchical designs

High-low-close plot

Histograms

Homogeneous groups

Homogeneous Poisson process

Hotelling-Lawley trace House of quality

Huynh-Feldt correction

Hyper-Graeco-Latin squares

Hypergeometric distribution Hypothesis tests

I-optimal designs

lcicle plots Individuals control charts

Inertia

Inflation adjustment

Influential points

Inner and outer arrays

Integrated periodogram Interaction analysis and plot

Interevent time distributions

Interpolation Interquartile range

Interrater comparisons Intersextile range

Inverse cumulative distributions

Inverse Gaussian distribution Inverse prediction Irregular fractions Item reliability

Jackknife Jittering

Kaiser-Meyer-Olkin measure Kaplan-Meier estimates Kendall rank correlations

Kendall's tau B and C

Kolmogorov-Smirnov tests Kriging Kruskal-Wallis test

Kuiper's V

Kurtosis

Life tables Lack-of-fit test Lambda Laney chart Laplace centroid test Laplace distribution Largest extreme value distribution Latin squares Levene's test Least squares means Leverage Life data regression Likelihood ratio test Linear trend test Linearity plot Log probit model Log survival functions Log-cumulative hazard plot Logarithmic models Logistic distribution Logistic regression Logit transformation Loglogistic distribution Lognormal distribution Lower and upper quartiles LOWESS smoothing LSD intervals LTPD plans

MAD regression Mahalanobis distance Main effects plot Mallows' Cp Mann-Whitney test MAPE, MAE and MSE Marquardt method Martingale residuals Matrix plot Mauchley's test Maximum likelihood estimation Maxwell distribution Mean rank plots Mean square PRESS Mean time between failures (MTBF) Mean, median & mode Means and median plot Measurement variation Median chart Median polish Membership table MIL-STD-105E, 1916 and 414 Mixed level fractions Mixed models

Mixture designs

Mosaic plot

Monte Carlo simulation

Moving average charts

Multifactor categorical designs

Multilevel factorial designs

Moving range charts

Multi-vari charts

Multifactor ANOVA

Mood's median test

Mode

Multiple comparisons Multiple correspondence analysis Multiple dot diagram Multiple range tests Multiple regression Multiple response optimization Multiple sample comparison Multiple variable analysis Multiple X-Y & X-Y-Z plots Multiplicative models Multivariate capability Multivariate control charts Multivariate EWMA chart Multivariate T-squared chart

NDC (no. of distinct categories) Negative binomial distribution Negative binomial regression Neural network classifier Non-normal capability indices Noncentral chi-square, t and F dists. Nonhomogenous Poisson process Nonlinear regression Nonlinear smoothing Nonparametric methods Nonparametric tolerance limits Normal distribution Normal probability plot

Normal tolerance limits Normalized control chart Notched box-and-whisker plots NP charts

OC curve OC plans Odds ratios OHLC plots One dimensional point processes One variable analysis Oneway ANOVA Open-high-low-close plots Operator and part plot Optimization Outlier identification Overdispersion test Overlaid contour plots

P' chart P charts P/T ratio Paired sample comparison Pairwise differences Parallel coordinates plot Parallel regression lines Pareto charts Pareto distribution Partial autocorrelations Partial correlations Partial least squares (PLS) Path of steepest ascent Pearson correlations Pearson curves Pearson residuals Percentiles Periodogram Perspective diagram Phase 1 & Phase 2 analysis Piechart Pillai trace Plackett-Burman designs

PLS Point processes Poisson distribution Poisson regression Polar coordinates plot Polynomial regression Power curve Power function model

Power transformations Prediction capability Prediction limits Prediction profile plot Prediction R-squared Prediction variance plot PRESS residuals
Principal components Probability distributions (45)

Probability plot Probit analysis Process mapping Process Z Profile plot

Q score statistic Quality function deployment (QFD) Quantile plot Quantile-quantile plot Quartiles Quartimax rotation

R R charts R-squared R&R plot Radar plot Random censoring Random number generators (45) Random walk models Randomized block designs Randomness tests Range chart Rank correlations Rank regression Rayleigh distribution Reciprocal models Regression analysis Relative inertia Relative risk Reliability analysis

Reliability test plans

Repeatability and reproducibility Repeated measures Residual autocorrelations Residual distance graphs Residual plots Resistant regression Resistant smoothing Response surface designs Response surface exploration Reverse arrangement test Ridge regression Ridge trace Risk analysis method Robust parameter designs Rootogram Rotation of factors Row and column profiles Rowwise statistics Roy's greatest root Run chart Running medians Runs tests

Renewal processes

Repairable systems

S S chart S curves S-squared chart Sample size determination Control charts Correlation coefficients One sample analysis Oneway ANOVA Rates and proportions Screening designs Two samples Sampling distributions Sbi Scale cusum chart Scatterplots Scheffe intervals Schwarz Bayesian criterion Scott's rule Scree plot Screening designs Seasonal adjustment Seasonal decomposition Seasonal indices plot

Seasonal subseries plot Sequential probability ratio tests Session log and audit trail Sextiles Shapiro-Wilks' test

Sigma plot Sigma quality level Sign test Signal theory method Signal-to-noise ratio Signed rank test

Simplex plot Simplex-centroid designs Simplex-lattice designs Simulation

Single factor categorical designs Six sigma calculator

Skewness Skychart

Smallest extreme value distribution Smoothing Somer's D

Spearman rank correlations Special cubic model Specific variance

Spenser's moving averages Spherical coordinate plot Sphericity correction Sphericity tests

Spider plot Splines Standard deviation

Standard error bars

Standardized regression coefficients Standardized residuals

Standardized skewness & kurtosis

Star plots Statistical tolerance limits Steepest descent method

Stem-and-leaf display Stepwise regression Strip plots Student-Neuman-Keuls Student's t distribution

Studentized residuals Sturges' rule Subset analysis Sunray plots Surface fitting Surface plot Survival functions Suspended rootogram Symmetry plot

T Chart t tests T-squared chart T-squared decomposition Tabular cusum chart Tabulation Taguchi designs Tail areas Tapering Ternary plot Tests for normality Tests for randomness Three-level factorial designs Time sequence plots Time series analysis Tolerance charts Tolerance intervals and bounds Toolwear charts Trace plot Trading bands Trend models Trend tests Triangular distribution Trimmed mean Truncated sampling Tukey's 3-median method Tukey's HSD intervals Tukey's nonlinear smoothers Two sample comparisons Two-level factorial designs Two-way table Type I and II censoring

U' chart U charts Uncertainty coefficient Uniform distribution Unusual residuals User profiles

Type I and III sums of squares

V-mask cusum chart Variance Variance check Variance components analysis Variance dispersion graph Variance inflation factor Variance map Variance ratio test Variation barchart Varimax rotation Variogram Vertical time sequence plot Video recording Visualization

Warning limits Watson's U2 test Weibayes method Weibull analysis Weibull distribution Weibull plot Weighted least squares Wilcoxon test Wilks' lambda Winsorized mean & sigma

X charts X-Y & X-Y-Z Plots X-bar charts

Yates' correction Yield plot

7 Z test Zero-based acceptance 7-scores