









DOC00042 AC.01		MODEL ¹	SENSEAR PART NUMBER
CONNECTOR PICTURE	MANUFACTURER		SM1 & Smart Plug ³
 MOTOROLA GP328	MOTOROLA	GP328, GP329, GP338, PTX760, MTX960, MTX850, MTX850LS, PRO5150, PRO7550, ATS2500, PR860, MTP700, GP1280, GP140, GP320, GP339, GP340, GP360, GP380, GP640, GP650, GP680, HT1250, HT1250LS, HT1250LS+, HT1550, HT1550XLS, HT750, MTX8250, MTX8250LS, MTX9250, MTX950, PRO5350, PRO5450, PRO5550, PRO5750, PRO7150, PRO7350, PRO7450, PRO9150, PTX700, PTX780, MTX950, MTX900, PRO7750, MTP850Ex, MTP810Ex	SRDK0003 (6 weeks) ²
	 MOTOROLA VISAR	MOTOROLA	MT2000, MTX838, MTX8000, XTS2250, XTS2500, XTS3000/Astro, XTS5000, MT1500, MTS1500, GP900, GP9000, HT1000, JT1000, MTS2000, MTX9000, MTXLS, XTS3500, XTS1500
	EF JOHNSON	51SL, 5000 series, 5100 series, 7700 series, Multi-net Ascend	
 MOTOROLA 2-PIN	BEARCOM	BC120, BC130	SRDK0005 (6 weeks) ²
	TEKK	XU100, XV100, XU1000, XV1000	
	RELM / BENDIX KING	RP6500	
	BLACKBOX	V, H	
	HYT	TC610, TC620, TC700, TC1600, TC500, TC508, TC518, TC600, TC626, TC580, TC446S, POWER446, TC2100, HYT2100, Titan, TR200, TR400, PD40x, PD50x, PD56x	
	MOTOROLA	CP200, MAGONE/BPR40, RDU2020, RDU4100, RDU4160, RDU4160-D, CP040, GP300, DTR650, EP450, GP3688, CP88, ECP100, CP100, CP125, CP150, CT150, CT250, CT450, CT450LS, GP68, GP88, GP88S, GP280, GP308, GP320, GP350 (requires Motorola adapter HLN9482), GP1280, GP2000, GTI, GTX, LTS2000, P040, P080, P110, P200, P1225, P1225LS, PR400, PRO1150, PRO2150, PRO3150, SP10, SP21, SP50, VL50, VL130, XTN445, XTN446, XTN500, XTN600, XU1100, XU2100, XU2600, XV1100, XV2100, XV2600, CLS Series, PMR446, Spirit MU-11C, MU-21CV, MU-22CVS, MU-24CVS, MV-11C, MV-21CV, MV-21CVS, MV-24CVS, XTN446, XTN500, XTN600, VL50, VL130, DTR Series, P1215, BC90, CP185, BC10, BC95, RDX Series, RDU Series, RDV Series, GP3188, CP200d, DP1400, XiR P3688, DEP450	
 KENWOOD MULTIPIN	KENWOOD	NexEdge NX210, NexEdge NX5300, TK-3140, NexEdge NX200/300, NexEdge NX410, TK-280, TK285N, TK-290, TK-480, TK-2140, TK-3180, TK-190, TK-380, TK-385, TK-390, TK-481, TK-2041, TK-2180, TK-3148, TK-5210, TK-5310, TK-5220, TK-390, TK-5400, TK-5320, TK-5410, TK-5310	SRDK0001 (6 weeks) ²



DOC00042 AC.01		MODEL ¹	SENSEAR PART NUMBER
CONNECTOR PICTURE	MANUFACTURER		SM1 & Smart Plug ³
KENWOOD 2-PIN 	HYT	TC265, TC266, TC268, TC368, TC620, TC700EX	SRDK0006 (6 weeks) ²
	KENWOOD	TK-360, TK-3170, TK-3202, TK-3207, TK-3303, TH-D7, TH-D7A, TH-D7AG, TH-D7E, TH-F6, TH-F6A, TH-F7, TH-F7E, TH-G71, TH-G71A, TH-G71E, TH-K2, TH-K2A, TH-K2AT, TH-K2E, TH-K2ET, TH-21, TH-21AT, TH-21BT, TH-22, TH-22A, TH-22AT, TH-22E, TH-25, TH-26, TH-27, TH-28, TH-28A, TH-31AT, TH-31BT, TH-41AT, TH-41BT, TH-42, TH-42A, TH-42AT, TH-42E, TH-45, TH-46, TH-47, TH-48, TH-48A, TH-55, TH-75, TH-77, TH-77A, TH-78A, TH-G71, TH-205, TH-225, TH-235, TH-235A, TH-235E, TH-315, TH-415, TK-208, TK-220, TK-240, TK-240D, TK-248, TK-250, TK-260, TK-260G, TK-270, TK-270G, TK-272G, TK-373G, TK-308, TK-320, TK-340, TK-340D, TK-348, TK-350, TK-353, TK-360G, TK-370, TK-370G, TK-372G, TK-373, TK-430, TK-431, TK-2130, TK-2160, TK-2170, TK-2200, TK-2207, TK-3130, TK-3160, TK-3173, TK-3200, TK-3201, TK-278G/378G/388G(Pro Talk), TK-2100/3100(Pro Talk), TK-2102/3102(Pro Power), TK-2107/3107(Pro Talk), TK-3101/3131(Free Talk), TK-2130/3130/3131(Pro Talk XLS), TK-3101(Free Talk XL), TK-2212, TK-2202, TK-2300, TK-2360, TK-3212, TK-3230, TK-3230XLS, TK-3350, TK-3360, TK-072A, TK-3300, TK-170, TK-2302, TK-3302, TK-2312, TK-3312, NexEdge NX220, NexEdge NX320	
	RELM / BENDIX KING	RPU416, RPV516, RPU499, RPV599X, RPV516A, RPV599A Plus, RPU416A, RPU499A Plus, RPU4200	
	UBZ	LF48	
MOTOROLA MOTOTRBO 	MOTOROLA	XPR7550 IS, XPR6580 IS, DP4401 EX, DP4801 EX, XiR P8608 EX, XiR P8668 EX, DGP8550 EX, XPR 6000 Series (XPR6100, XPR6350, XPR6380, XPR6550, XPR6580, XPR6500, XPR6300), XPR 7000 Series (XPR7550, XPR7350, XPR7580, XPR7380), DP3000 Series (DP3400, DP3401, DP3600, DP3601), DP4000 Series (DP4400, DP4401, DP4600, DP4601, DP4800, DP4801), DGP 4150, DGP4150+, DGP6150, DGP6150+, DGP8050/5050, DGP8550/5550, XiR P8200, XiR P8208, XiR P8260, XiR P8268, XiR P8600, XiR P8608, XiR P8620, XiR P8628, XiR P8660, XiR P8668, APX7000 Series, APX6000 Series, APX4000 Series, MTP850S, MTP850Ex, GP328D, GP338D, APX8000 Series, APX5000 Series, APX3000 Series, APX2000 Series, APX1000 Serie, SRX2200, APX7000L, MTP810Ex, MTP830S, MTP6000 Series	SRDK0004 (6 weeks) ²
RJ45 and 3.5mm mono Bluetooth PTT 	With KENWOOD	TK-8180, TM-271, TK-762, TK-862, TK-7160, TK-8160, TK-7162, TK-8162, TK-7180, TK-7189, TK-8189, TKR-750, TKR-850, TK-768G, TK-868G, TK-760, TK-860, TK-780, TK-880, TK-7102, TK-8102	SRDK0007 (6 weeks) ²



DOC00042 AC.01		MODEL ¹		SENSEAR PART NUMBER
CONNECTOR PICTURE	MANUFACTURER			SM1 & Smart Plug ³
DB25 Bluetooth PTT With 	KENWOOD	NX-700, TK-7180, TK-8180, TK-7189, TK-8189, NX-800, NX-900, NX-901		SRDK0008 (6 weeks) ²
Mototrbo Dash radio 26-pin Bluetooth PTT With 	MOTOROLA	XPR5350, XPR5550, DM3400, DM3401, DM3600, DM3601, XPR 4300, XPR4350, XPR4500, XPR 4550, XiR M8220, XiR M8228, XiR M8260, XiR M8268, DGM4100, DGM4100+, DGM6100+, DM4400, DM4401, DM4600, DM4601, XiR M8620, XiR M8628, XiR M8660, XiR M8668, DGM8000/5000, DGM8500/5500		SRDK0009 (6 weeks) ²
Motorola DP2000 Series 	MOTOROLA	DP2000 Series (DP2400, DP2600), XPR3000 Series (XPR3300, XPR3500), DP3441, XiR P6600, XiR P6620, XiR E8608, XiR E8600, DEP550, DEP570, DGP8050 ELITE, MTP3100, MTP3250, XiR E8600, XiR E8606,		SRDK00010 (6 weeks) ²

PS:

1. Cables in RED have not been tested
2. Denotes availability and lead time
3. Only compatible for SmartPlug with SW00.0104.01.07 or later main application firmware.