




COHESIVE
solutions

Unlocking potential. Achieving results

What's New in Maximo V7.6.0.9?

Patrick Kenney
Business Development Executive



Modernizing the Maximo User Experience

Assess and complete daily tasks without opening multiple applications.



Simple: Redesigned Maximo components so that interacting with the system is as simple as possible.



Role-based: Work Centers are designed for a specific persona incorporating their goals, needs, and interests.



Smarter: Pulls information and actions out of our existing app structure and makes them relevant to users at the moment they need them.



Data Driven: Information is filtered, transformed and aggregated based on the needs of the current process.



Responsive: Users have the same experience no matter what device they use.



Intuitive: Users can understand the behavior of the work centers without the need for special training.

From

The screenshot displays the 'Work Order Tracking' application interface. At the top, there is a navigation bar with a home icon, a menu icon, and the title 'Work Order Tracking'. Below this is a search bar labeled 'Find Work Order' and a toolbar with various icons. A secondary navigation bar contains tabs for 'List View', 'Work Order', 'Plans', 'Assignments', 'Related Records', 'Actuals', 'Safety Plan', 'Log', 'Data Sheet', 'Failure Reporting', 'Specifications', 'Service Address', and 'Map'. The 'List View' tab is currently active.

The main content area is divided into several sections:

- Left Sidebar:** Contains navigation and action options such as 'Go To Applications', 'Available Queries', 'All Records', 'All Bookmarks', 'My Work Orders', 'Common Actions' (including 'New Work Order', 'Clear Changes', 'Change Status', 'Select Owner', 'Take Ownership', 'Approve Work Order', 'Initiate Work Order', 'Complete Work Order', 'Close Work Order', 'Create Report'), and 'More Actions' (including 'Apply SLAs', 'View SLAs', 'Select/Deselect SLAs', 'Change Work Order Options', 'Create', 'View', 'Create Job Plan from Work Plan', 'Remove Work Plan', 'Select Safety Hazards', 'Remove Safety Plan', and 'Apply Route').
- Work Order Details:**
 - Work Order:** 1203, Failure with sealing system - see Fred
 - Location:** BPM3100 >> #1 Liquid Packaging Line
 - Asset:** 13120 >> Bottom Sealing System
 - Configuration Item:** >>
 - Parent WO:** >>
 - Classification:** >>
 - Class Description:** >>
 - Launch Entry Name:** >>
- Site:** BEDFORD
- Class:** WORKORDER
- Work Type:** EM
- GL Account:** 6400-300-???
- Failure Class:** PKG >>
- Problem Code:** >>
- Storeroom Material Status:** >>
- Direct Issue Material Status:** >>
- Work Package Material Status:** >>
- Material Status Last Updated:** >>

Attachments:

- Status: WAPPR
- Status Date: 9/21/17 1:06 PM
- Inherit Status Changes?
- Accepts Charges?
- Is Task?
- Under Flow Control?
- Suspend Flow Control?
- Flow Action: >>
- Flow Action Assist?
- Appointment Required?

Job Details:

- Job Plan: >>
- Job Plan Revision #: >>
- PM: >>
- Safety Plan: >>
- Contract: >>

Asset Details:

- Asset Up?
- Warranties Exist?
- SLA Applied?
- Charge to Store?
- Current Value: >>

Priority:

- Asset/Location Priority: 3
- Priority: >>
- Priority Justification: >>
- Risk Assessment: >>

To

IBM Maximo Asset Management Work Supervision > Ed Adams

Inspection Form Library

Approve work (3)

Search

Scheduled Start Date

- EM 91091 HVAC Overheating Priority 1
Location: 123 Main, F3 R402
Asset: HVAC System 2
Scheduled start date: 9/14/2016
\$5,000.00
[Approve](#)
- CM 93452 HVAC part replacement Priority 1
Location: 123 Main, F3 R402
Asset: HVAC System 2
Scheduled start date: 9/14/2016
\$5,000.00
[Approve](#)
- CM 93452 Leaking pipe Priority 3
Location: 123 Main, F3 R402
Asset: HVAC System 2
Scheduled start date: 9/14/2016
\$5,000.00
[Approve](#)
- CM 93452 Priority 3

Assign work (34)

Search

Priority

- EM 91091 Pump Overheating Priority 1
Location: 123 Main, F3 R402
Asset: Water Pump System 2
Craft: Electrician
[Find Lead](#)
- CM 93452 HVAC part replacement Priority 1
Location: 123 Main, F2 R210
Asset: HVAC System 2
Craft: Mechanic
[Find Lead](#)
- CM 93452 Leaking pipe Priority 3
Location: 123 Main, Basement
Asset: Not applicable
Craft: Plumber
[Find Lead](#)
- CM 93452 Priority 3

Close work (7)

Search


- EM 91091 HVAC Overheating Priority 1
Location: 123 Main, F3 R402
Asset: HVAC System 2
Completion: 100%
[Close work](#)
- CM 93452 HVAC Overheating Priority 1
Location: 123 Main, F3 R402
Asset: HVAC System 2
Completion: 100%
[Close work](#)
- CM 93452 HVAC Overheating Priority 3
Location: 123 Main, F3 R402
Asset: HVAC System 2
Completion: 100%
[Close work](#)
- CM 93452 HVAC Overheating Priority 3
Location: 123 Main, F3 R402
Asset: HVAC System 2
Completion: 100%
[Close work](#)

New Maximo Work Centers

Initial Offerings – a focus on Work Management and Analytics.



Work Supervision




Work Technician



Business Analyst

Work Center History

Time





COHESIVE
solutions

Unlocking potential. Achieving results

Questions

Patrick Kenney

pkenney@cohesivesolutions.com

(770) 380-5004

Safe Harbor

General Use

This presentation may contain forward-looking statements, particularly as related to, among other things, the business plans of the Company, statements relating to goals, plans and projections regarding the Company's financial position and business strategy. The words or phrases "would be," "will allow," "intends to," "may result," "are expected to," "will continue," "anticipates," "expects," "estimate," "project," "indicate," "could," "potentially," "should," "believe," "think", "considers" or similar expressions are intended to identify "forward-looking statements." These forward-looking statements fall within the meaning of Section 27A of the Securities Act of 1933 and Section 21E of the Securities Act of 1934 and are subject to the safe harbor created by these sections. Actual results could differ materially from those projected in the forward-looking statements as a result of a number of risks and uncertainties. Such forward-looking statements are based on current expectations, involve known and unknown risks, a reliance on third parties for information, transactions or orders that may be cancelled, and other factors that may cause our actual results, performance or achievements, or developments in our industry, to differ materially from the anticipated results, performance or achievements expressed or implied by such forward-looking statements.

Factors that could cause actual results to differ materially from anticipated results include risks and uncertainties related to the fluctuation of global economic conditions, the performance of management and our employees, our ability to obtain financing, competition, general economic conditions and other factors that are detailed in our periodic reports and on documents we file from time to time with the Securities and Exchange Commission. Statements made herein are as of the date of this press release and should not be relied upon as of any subsequent date. The Company cautions readers not to place undue reliance on such statements. The Company does not undertake, and the Company specifically disclaims any obligation, to update any forward-looking statements to reflect occurrences, developments, unanticipated events or circumstances after the date of such statement. Actual results may differ materially from the Company's expectations and estimates.