



## Genie/Terex Issue Product Safety Notice

### Issue affects 2019 Model Year Mobile Elevating Work Platforms (MEWP)

Genie has issued a safety notice regarding several instances where improperly torqued bolts could allow the turntable of the machine to become completely separated from the chassis, which could lead to tip-over or complete structural failure.

The issue affects the following **2019** models:

<b><u>Model</u></b>	<b><u>Serial Range</u></b>
S-65	S60H-39903 to 40455
S-60X	S60XH-39397 to 40454
S-60XC	S60XCH-45009 to 46426
S-65XC	S65XCH-45007 to 46425

Genie has outlined instructions in its safety notice on how to repair the machines, or how to file a claim with Genie.

Click [here](#) to review the safety notice, or click [here](#) to visit Genie's website for more information.

Safe**ALERT**<sup>SM</sup>



ORCIG 2020 SafeAlert Series

This material is intended to be a broad overview of the subject matter and is provided for informational purposes only. Old Republic Contractors Insurance Group, Inc. does not endorse or recommend any products or services nor does it make any representation or warranty regarding the accuracy or completeness of the information. Old Republic Contractors Insurance Group, Inc. shall have no liability or responsibility to any person or entity with respect to any loss, action or inaction alleged to be caused directly or indirectly as a result of the information contained herein.

