



poquet auto

## Vehicle Information

**Date:** May 21, 2020  
**Vehicle:** 2015 BMW X5 Series Utility 4D 35i AWD 3.0L I6 Turbo  
**VIN:** 5UXKR0C50F0P05233  
**Weight:** 4,790

## New Cars/Trucks Values

Powered by Chrome Data	Base	Options	Destination	Adjusted Value
Base MSRP	\$56,200	\$3,150	\$995	<b>\$60,345</b>

### NADA New Vehicle Values

High	N/A	N/A	N/A	<b>N/A</b>
------	-----	-----	-----	------------

## Optional Equipment

	Invoice	MSRP
REAR-VIEW CAMERA Code: 3AG	\$365.00	\$400.00
STANDARD PAINT Code: -PAINT	\$0.00	\$0.00
JET BLACK Code: 668	\$0.00	\$0.00
BLACK, DAKOTA LEATHER UPHOLSTERY Code: LCSW	\$1320.00	\$1450.00
MULTI-CONTOUR SEATS -inc: 20-way power, 10-way power seat functions, additional power adjustment functions for shoulder and thigh support, backrest width and lumbar support (contour and position) and 2-way manual lateral adjustment for comfort headrest, Code: 456	\$1185.00	\$1300.00
TRANSMISSION: 8-SPEED AUTOMATIC W/STEPTRONIC (STD) Code: 205	\$0.00	\$0.00
WHEELS: 18" X 8.5" LIGHT ALLOY (STYLE 446) -inc: Double spoke (STD) Code: 2AZ	\$0.00	\$0.00

## Standard Equipment

### ENTERTAINMENT

- Bluetooth Wireless Phone Connectivity
- Hi-Fi Sound System
- Radio w/Clock and Steering Wheel Controls
- Radio: Anti-Theft AM/FM Stereo w/CD/MP3
- Real-Time Traffic Display
- Satellite Radio Preparation
- Streaming Audio
- Window Grid Diversity Antenna

### EXTERIOR

- Black Grille w/Chrome Surround
- Body-Colored Door Handles
- Body-Colored Front Bumper w/Metal-Look Bumper Insert



- Body-Colored Power Heated Auto Dimming Side Mirrors w/Power Folding and Turn Signal Indicator
- Body-Colored Rear Bumper w/Metal-Look Bumper Insert
- Chrome Side Windows Trim and Black Front Windshield Trim
- Clearcoat Paint
- Cornering Lights
- Deep Tinted Glass
- Express Open/Close Sliding And Tilting Glass 1st And 2nd Row Sunroof w/Power Sunshade
- Fixed Rear Window w/Fixed Interval Wiper and Defroster
- Front Fog Lamps
- Fully Automatic Projector Beam High Intensity Low/High Beam Daytime Running Auto-Leveling Directionally Adaptive Headlamps w/Delay-Off
- Galvanized Steel/Aluminum/Composite Panels
- LED Brakelights
- Lip Spoiler
- Perimeter/Approach Lights
- Power Liftgate/Tailgate Rear Cargo Access
- Rocker Panel Extensions and Black Wheel Well Trim
- Roof Rack Rails Only
- Speed Sensitive Rain Detecting Variable Intermittent Wipers w/Heated Jets
- Tailgate/Rear Door Lock Included w/Power Door Locks
- Tires: P255/55R18 Run-Flat AS
- Wheels w/Silver Accents
- Wheels: 18" x 8.5" Light Alloy (Style 446) -inc: Double spoke

## INTERIOR

- 2 Seatback Storage Pockets
- 4 12V DC Power Outlets
- 40-20-40 Folding Split-Bench Front Facing Fold Forward Seatback Rear Seat
- Air Filtration
- Analog Display
- Ashtray
- BMW Online Full Service Internet Access
- Cargo Area Concealed Storage
- Cargo Space Lights
- Carpet Floor Trim
- Cruise Control w/Steering Wheel Controls
- Day-Night Auto-Dimming Rearview Mirror
- Delayed Accessory Power
- Driver / Passenger And Rear Door Bins
- Driver And Passenger Visor Vanity Mirrors w/Driver And Passenger Illumination
- Driver Foot Rest
- Driver Seat
- Dual Zone Front Automatic Air Conditioning w/Steering Wheel Controls
- Engine Immobilizer
- Fade-To-Off Interior Lighting
- FOB Controls -inc: Cargo Access, Windows and Sunroof/Convertible Roof
- Front And Rear Map Lights
- Front Bucket Seats -inc: 10-way power-adjustable front seats w/4-way lumbar support and memory system for driver's seat, steering wheel and outside mirrors
- Front Center Armrest and Rear Center Armrest
- Front Cigar Lighter(s)
- Front Cupholder
- Full Carpet Floor Covering -inc: Carpet Front And Rear Floor Mats
- Full Cloth Headliner
- Full Floor Console w/Covered Storage, Mini Overhead Console and 4 12V DC Power Outlets
- Garage Door Transmitter
- Gauges -inc: Speedometer, Odometer, Engine Coolant Temp, Tachometer, Trip Odometer and Trip Computer
- Heated Front Seats
- HVAC -inc: Underseat Ducts, Residual Heat Recirculation and Console Ducts
- Illuminated Locking Glove Box
- Interior Lock Disable
- Interior Trim -inc: Chrome/Metal-Look Interior Accents
- Leather/Chrome Gear Shifter Material
- Leatherette Door Trim Insert
- Lumbar Support
- Memory Settings -inc: Head Restraints
- Navigation System w/Touchpad
- Outside Temp Gauge
- Passenger Seat
- Perimeter Alarm
- Poplar Wood Trim
- Power 1st Row Windows w/Front And Rear 1-Touch Up/Down
- Power Anti-Whiplash w/Tilt Front Head Restraints and Manual Adjustable Rear Head Restraints
- Power Door Locks w/Autolock Feature
- Power Front Seats w/Driver Seat Memory
- Power Fuel Flap Locking Type
- Power Rear Windows and Fixed 3rd Row Windows
- Power Tilt/Telescoping Steering Column
- Proximity Key For Push Button Start Only
- Rear Cupholder



Licensed to J.D. Power

- Remote Keyless Entry w/Integrated Key Transmitter, 4 Door Curb/Courtesy, Illuminated Entry and Panic Button
- Remote Releases -Inc: Power Cargo Access
- Roll-Up Cargo Cover
- Sensatec Leatherette Upholstery
- Smart Device Integration
- Sport Leather/Metal-Look Steering Wheel w/Auto Tilt-Away
- Systems Monitor
- Tracker System
- Trip Computer
- Trunk/Hatch Auto-Latch
- Valet Function

## MECHANICAL

- 105-Amp/Hr Maintenance-Free Battery
- 1110# Maximum Payload
- 210 Amp Alternator
- 22.4 Gal. Fuel Tank
- 3.154 Axle Ratio
- 4-Wheel Disc Brakes w/4-Wheel ABS, Front And Rear Vented Discs, Brake Assist, Hill Descent Control, Hill Hold Control and Electric Parking Brake
- Double Wishbone Front Suspension w/Coil Springs
- Electric Power-Assist Speed-Sensing Steering
- Engine Auto Stop-Start Feature
- Engine: 3.0L DOHC I6 24V TwinPower Turbo
- Front And Rear Anti-Roll Bars
- Full-Time All-Wheel
- Gas-Pressurized Shock Absorbers
- GVWR: 6,063 lbs
- Multi-Link Rear Suspension w/Coil Springs
- Permanent Locking Hubs
- Quasi-Dual Stainless Steel Exhaust w/Chrome Tailpipe Finisher
- Transmission: 8-Speed Automatic w/STEPTRONIC

## SAFETY

- ABS And Driveline Traction Control
- Airbag Occupancy Sensor
- BMW Assist eCall Emergency Sos
- Curtain 1st And 2nd Row Airbags
- DSC-X Electronic Stability Control (ESC) And Roll Stability Control (RSC)
- Dual Stage Driver And Passenger Front Airbags
- Dual Stage Driver And Passenger Seat-Mounted Side Airbags
- Front And Rear Parking Sensors
- Outboard Front Lap And Shoulder Safety Belts -inc: Rear Center 3 Point and Pretensioners
- Rear Child Safety Locks
- Side Impact Beams
- Tire Specific Low Tire Pressure Warning

## Vehicle Information

### CRASH TEST RATING

US NHTSA CRASH TEST RESULTS:

Overall Rating: \*\*\*\*\*

Overall Frontal Barrier Crash Rating: \*\*\*\*\*

Overall Side Crash Rating: \*\*\*\*\*

Side Barrier Rating: \*\*\*\*\*

Combined Side Barrier and Pole Ratings:

Front Seat Rating: \*\*\*\*\* Rear Seat Rating: \*\*\*\*\*

Overall Rollover Rating: \*\*\*\*\*

Dynamic Test Result: No Tip

Risk of Rollover: 18.8%

Note Regarding Driver Rating:

Male: Average sized adult male dummy in 35-MPH crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs. Female: Small-sized adult female dummy in 35-mph crash into fixed barrier. Rating is evaluation of injury to head, neck, chest, legs.

Rollover Note: Dynamic (moving) test results (Tip or No Tip) and measured rollover-related properties determine vehicle's risk of rollover in single vehicle crash and its rollover rating. The Rollover



Resistance Rating utilizes a "fishhook" maneuver which is a series of abrupt turns at varying speeds to see how "top-heavy" a vehicle is.

## RECALL

US NHTSA CAMPAIGN ID:  
14V650000

Mfg's Report Date:  
OCT 16, 2014

Component:  
SEATS

Potential Number Of Units Affected:  
11

**Summary:**  
BMW of North America, LLC (BMW) is recalling certain model year 2015 X5 vehicles manufactured September 12, 2014, to September 21, 2014 and equipped with the optional rear comfort seat. The left rear seat belt attachment point in the affected vehicles may not have been sufficiently welded.

**Consequence:**  
In the event of a crash, the seat belt attachment could break and fail to restrain a seat occupant, increasing the risk of injury.

**Remedy:**  
BMW will notify owners, and dealers will replace the left rear seat frame, free of charge. The recall began November 2014. Owners may contact BMW customer service at 1-800-525-7417 or CustomerRelations@bmwusa.com.

Dates of Manufacture:  
SEP 11, 2014 to SEP 20, 2014  
US NHTSA CAMPAIGN ID:  
15V147000

Mfg's Report Date:  
MAR 12, 2015

Component:  
AIR BAGS

Potential Number Of Units Affected:  
46

**Summary:**  
BMW of North America, LLC (BMW) is recalling certain model year 2015 BMW X5 xDrive 35d Sports Activity Vehicles (SAV) manufactured August 19, 2014, to February 16, 2015, and 2014-2015 BMW X5 xDrive 35i, X5 sDrive 35i, X5 xDrive 50i, Sports Activity Vehicles (SAV) manufactured August 28, 2013, to February 16, 2015. In the affected vehicles, the Head Protection System (HPS) air bag may not be securely connected to the air bag inflator gas generator.

**Consequence:**  
Without a secure connection to the inflator, the HPS air bags may have insufficient inflation during a vehicle crash, increasing the risk of injury.

**Remedy:**  
BMW will notify owners, and dealers will replace the Head Protection System, free of charge. The recall began on June 24, 2015. Owners may contact BMW customer service at 1-800-525-7417.

Dates of Manufacture:  
AUG 27, 2013 to FEB 15, 2015  
US NHTSA CAMPAIGN ID:  
16V683000

Mfg's Report Date:  
SEP 20, 2016


Component:  
AIR BAGS:FRONTAL:DRIVER SIDE INFLATOR MODULE

Potential Number Of Units Affected:  
3606

**Summary:**  
BMW of North America, LLC. (BMW) is recalling certain model year 2015 BMW X3 sDrive28i, X3 xDrive28i, X3 xDrive35i, X3 xDrive28d, X4 xDrive28i and X4 xDrive35i vehicles, and model year 2014-2015 X5 xDrive35i, X5 sDrive35i, X5 xDrive50i, and 2014 X5 xDrive35d vehicles. The affected vehicles have a driver's frontal air bag inflator that may have been improperly welded.

**Consequence:**  
In the event of a crash necessitating deployment of the driver's frontal air bag, the inflator housing could separate from the base plate and result in metal striking the vehicle occupants, potentially resulting in serious injury or death.

**Remedy:**  
BMW will notify owners, and dealers will replace the driver's front air bag, free of charge. The recall began on November 1, 2016. Owners may contact BMW customer service at 1-800-525-7417.

**Dates of Manufacture:**

MAY 06, 2014 to NOV 17, 2014

**US NHTSA CAMPAIGN ID:**

18V755000

**Mfg's Report Date:**

OCT 24, 2018

**Component:**

ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL:GAS RECIRCULATION VALVE (EGR VALVE)

**Potential Number Of Units Affected:**

44368

**Summary:**

BMW of North America, LLC (BMW) is recalling certain 2013-2018 BMW 328d and 328d xDrive, 2014-2018 328d Sports Wagon and 328d xDrive Sports Wagon, 2014-2016 535d and 535d xDrive, 2015 740Ld xDrive, 2015-2017 X3 xDrive28d SAV and 2014-2017 X5 xDrive35d SAV vehicles equipped with an Exhaust Gas Recirculation (EGR) module with an integrated cooler. If the EGR cooler leaks internally, the coolant can mix with diesel engine soot. The high EGR temperatures may result in these particles possibly smoldering and melting the intake manifold.

**Consequence:**

The melting intake manifold can increase the risk of a fire.

**Remedy:**

BMW will notify owners, and dealers will inspect and replace the EGR cooler as necessary. If a leak has already occurred, the engine intake manifold will also be replaced. These repairs will be made free of charge. The recall began May 13, 2019. Owners may contact BMW customer service at 1-800-525-7417.

**Dates of Manufacture:**

MAY 06, 2013 to JUN 18, 2017

## WARRANTY

**Basic:**

4 Years/50,000 Miles

**Drivetrain:**

4 Years/50,000 Miles

**Corrosion:**

12 Years/Unlimited Miles

**Roadside Assistance:**

4 Years/Unlimited Miles

**Maintenance:**

4 Years/50,000 Miles

## Technical Specifications

### Brakes

- Brake ABS System (Second Line) N/A
- Brake ABS System 4-Wheel
- Brake Type 4-Wheel Disc
- Disc - Front (Yes or ) Yes
- Disc - Rear (Yes or ) Yes
- Drum - Rear (Yes or )
- Front Brake Rotor Diam x Thickness 13.7in
- Rear Brake Rotor Diam x Thickness 12.6in
- Rear Drum Diam x Width in

### Cargo Area Dimensions

- Cargo Area Length @ Floor to Seat 1 N/Ain
- Cargo Area Length @ Floor to Seat 2 N/Ain
- Cargo Area Length @ Floor to Seat 3 N/Ain
- Cargo Area Width @ Beltline N/Ain
- Cargo Box (Area) Height N/Ain
- Cargo Box Width @ Wheelhousings N/Ain
- Cargo Volume to Seat 1 76.7ft<sup>3</sup>
- Cargo Volume to Seat 2 35.8ft<sup>3</sup>
- Cargo Volume to Seat 3 35.8ft<sup>3</sup>

### Cooling System

- Total Cooling System Capacity N/Aqts



## Electrical

- Cold Cranking Amps @ 0Â° F (Primary) N/A
- Maximum Alternator Capacity (amps) 210

## Emissions

- EPA Greenhouse Gas Score N/A
- Tons/yr of CO2 Emissions @ 15K mi/year 8.4 (Est)

## Engine

- Displacement 3.0 L/182
- Engine Order Code
- Engine Type Intercooled Turbo Premium Unleaded I-6
- Fuel System Gasoline Direct Injection
- SAE Net Horsepower @ RPM 300 @ 5800
- SAE Net Torque @ RPM 300 @ 1200

## Exterior Dimensions

- Height, Overall 68.5in
- Length, Overall 191.1in
- Liftover Height N/Ain
- Min Ground Clearance N/Ain
- Rear Door Opening Height N/Ain
- Rear Door Opening Width N/Ain
- Track Width, Front 64.7in
- Track Width, Rear 65in
- Wheelbase 115.5in
- Width, Max w/o mirrors 76.1in

## Fuel Tank

- Aux Fuel Tank Capacity, Approx N/Agal
- Fuel Tank Capacity, Approx 22.4gal

## Interior Dimensions

- Front Head Room 40.5in
- Front Hip Room N/Ain
- Front Leg Room 40.4in
- Front Shoulder Room 60.5in
- Passenger Capacity 5
- Passenger Volume N/Aft<sup>3</sup>
- Second Head Room 38.8in
- Second Hip Room N/Ain
- Second Leg Room 36.6in
- Second Shoulder Room 58.3in

## Mileage

- Cruising Range - City 403.20mi
- Cruising Range - Hwy 604.80mi
- EPA Fuel Economy Est - City 18MPG
- EPA Fuel Economy Est - Hwy 27MPG
- EPA MPG Equivalent - City N/A
- EPA MPG Equivalent - Combined N/A
- EPA MPG Equivalent - Hwy N/A
- Fuel Economy Est-Combined 21MPG

## Steering

- Lock to Lock Turns (Steering) N/A
- Steering Ratio (:1), Overall N/A
- Steering Type Rack-Pinion
- Turning Diameter - Curb to Curb 41.7ft
- Turning Diameter - Wall to Wall N/Aft

## Suspension

- Shock Absorber Diameter - Front N/Amm
- Shock Absorber Diameter - Rear N/Amm



- Stabilizer Bar Diameter - Front N/Ain
- Stabilizer Bar Diameter - Rear N/Ain
- Suspension Type - Front (Cont.) Double Wishbone
- Suspension Type - Front Double Wishbone
- Suspension Type - Rear (Cont.) Multi-Link
- Suspension Type - Rear Multi-Link

## Tires

- Front Tire Order Code
- Front Tire Size P255/55HR18
- Rear Tire Order Code
- Rear Tire Size P255/55HR18
- Spare Tire Order Code
- Spare Tire Size

## Trailer

- Dead Weight Hitch - Max Tongue Wt. 595lbs
- Dead Weight Hitch - Max Trailer Wt. 5952lbs
- Maximum Trailering Capacity 5952lbs
- Wt Distributing Hitch - Max Tongue Wt. 595lbs
- Wt Distributing Hitch - Max Trailer Wt. 5952lbs

## Transmission

- Clutch Size N/Ain
- Drivetrain All Wheel
- Eighth Gear Ratio (:1) 0.67
- Fifth Gear Ratio (:1) 1.29
- Final Drive Axle Ratio (:1) 3.15
- First Gear Ratio (:1) 4.71
- Fourth Gear Ratio (:1) 1.67
- Reverse Ratio (:1) 3.29
- Second Gear Ratio (:1) 3.14
- Seventh Gear Ratio (:1) 0.84
- Sixth Gear Ratio (:1) 1.00
- Third Gear Ratio (:1) 2.11
- Trans Description Cont. Again
- Trans Description Cont. Automatic w/OD
- Trans Order Code 205
- Trans Type 8
- Transfer Case Gear Ratio (:1), High N/A
- Transfer Case Gear Ratio (:1), Low N/A

## Vehicle

- EPA Classification Standard Sport Utility Vehicles 4WD

## Weight Information

- Base Curb Weight 4790lbs
- Curb Weight - Front N/Albs
- Curb Weight - Rear N/Albs
- Curb Weight N/Albs
- Maximum Payload Capacity N/Albs
- Total Option Weight 0.00lbs

## Wheels

- Front Wheel Material Aluminum
- Front Wheel Size 18 X 8.5in
- Rear Wheel Material Aluminum
- Rear Wheel Size 18 X 8.5in
- Spare Wheel Material
- Spare Wheel Size in