



Bulletin No.: T03-2016
Date: 7/12/2016

TECHNICAL BULLETIN

SUBJECT: New Software Available

This bulletin is provided to communicate the availability of our latest software and firmware updates.

Description

Flux Power recommends all technicians download and install our latest Flux Power Pack Monitor software available at <http://www.fluxpwr.com/support-main/>. Enter the password: flux2016

Products Affected

None.

Remedy

Download and install the latest software, available on our website.

Please contact a technical support representative if you need assistance:

T: 877-505-3589

E: support@FLUXpwr.com

*****Repairs should only be performed by an authorized technician*****

If you have any questions regarding this Technical Bulletin, please contact your Flux Power representative.

Thank you!

Bulletin No.: T03-2016