


JANUARY 2018
Featured Product



KLEIN TOOLS
For Professionals... Since 1857™

Celebrating 50 Years

Non-Contact Voltage Tester With Infrared Thermometer

The NCVT-4IR provides non-contact determination of AC voltage in cables, cords, circuit breakers, switches, outlets, and wires; as well as Infrared (IR) thermometer measurements making it the perfect choice for HVAC professionals.

- Detects AC voltage from 12 to 1000 V with visual and audible indicators
- IR thermometer with user selectable °F / °C from -22 to 482°F (-30 to 250°C)
- Convenient laser acts as a laser pointer; also helps target IR temperature measurement
- Auto Power-off conserves and extends battery life
- Screw-thread battery cap with O-ring ensures water and dust resistant ingress protection
- Lightweight, compact tool with pocket clip provides easy storage and quick access



Infrared (IR) Thermometer
with 4:1 distance to spot ratio

Laser
Use as a laser pointer or to help target IR temperature measurement

IR Button
press and hold to take temperature reading. Press and hold IR button and NCV button to change to Celsius (°C)

Battery Cap
with O-Ring provides tight water and dust resistant seal to protect batteries



HVAC/IR

12 - 1000V AC

Non-Contact Tip
A high intensity, bright red LED illuminates and a warning tone sounds when voltage is detected.

Backlit LCD Screen
for easy viewing in low light

NCV Button
turns on and off the Non-Contact Voltage Tester. The tip will illuminate blue with a single beep when on and double beep and stop illuminating when off.

Pocket Clip



2x AAA Batteries
included

Contact your Pepco Sales Rep for more information about this product.