Profile







©2010 National Coatings Corporation All Rights Reserved.

GateGourmet

Size: 15,000 Square Feet

Location: LAX, Los Angeles, California

Challenge Metal Roof with Major Leaks

- Leaking metal roof.
- Localized corrosion.
- Deteriorated waterway paneling.

Solution AcryShield® Restoration System

- Repair and replacement of severely deteriorated paneling.
- Fastener and seam treatment and reinforcing.
- Localized rust-inhibitive priming.
- No more leaks.

This GateGourmet roof is a great example of a full systems approach to roof restoration--replace failed areas, prepare and reinforce fasteners and seams, prime as needed, and apply a Cool Roof coating.



