

## Profile



©2010 National Coatings Corporation.  
All Rights Reserved.

# SEQUOIA PACIFIC SYSTEMS

*Size: 340,000 Square Feet*

*Location: Exeter, California*

## Challenge *SBS Mod Bit Blistering*

- Severe membrane blistering and ridging.
- Ongoing thermal shock and stress.
- Major leak repairs expected.

## Solution *AcryShield® Restoration System*

- Reinforced blister repairs.
- No excess thermal shock.
- 10-15% energy savings.
- Avoided re-roof and saved valuable insulation.

*Sequoia Pacific restored a “terminally-ill” roof and now benefits from tens of thousands of dollars in lower energy bills without incurring the capital expense of a major re-roof project.*



**NATIONAL  
COATINGS**

1201 Calle Suerte, Camarillo, CA 93012  
(800) 423-9557, Fax (800) 294-3866

[www.nationalcoatings.com](http://www.nationalcoatings.com), [info@nationalcoatings.com](mailto:info@nationalcoatings.com)