XYZ **CONTRACTORS**

DAILY TIME & MATERIAL RECORD

94510

XYZ Contractors

"When you need it done right!" 4444 Fifth St., Suite 666 Lancaster, CA 93535 Phone (661) xxx-xxxx Cell (661) xxx-xxxx

Ca. Contr. Lic. #000000

CONCORD

Project Owner's Name: JOHN Q. CUSTOMER	Brief Description of Project: Replace windows damaged by stucco		
Project Address 747 BOEING ST, SUITE 757	Project City BENICI	Project Zip Code 94510	
General Contractor	General Contractor Address		
BIG TIME BUILDERS	6492 HAMMER LANE		

A. MATERIALS:

B. LABOR:

QTY.	DESCRIPTION OF MATERIALS	@	AMOUNT	WORKER	HOURS	RATE	AMOUNT
4	4-0 X 5-0 XOX SLIDERS	142.88	571.52	Jim Clydsdale	4	52.12	571.52
6	5-0 X 6-0 XOX SLIDERS	197.55	1185.30	Tom Jones	6	28.41	1185.30
2	2-0 X 3-0 XO SLIDERS	88.42	176.84	Tim Allen	2	28.41	176.84
5	1-0 X 4-0 FIXED	71.21	356.05	Bob Villa	5	28.41	356.05
2	4 X 4 GLASS BLOCK PANELS	548.40	1096.80	Norm Abrams	2	21.14	1096.80
1	5-0 X 5-0 GARDEN WINDOW	317.10	317.10	Joe Blow	1	18.14	317.10
			.	Joe Blow Nis is Form Naterial Invoice Ontractors			
		0.	in	Mis is Form T&M to ORDER Invoice ontractors Forms a			
		ALI	•	CAN'S A			
			AC	A Mate Orm			
			7	100 /a/ &/			
			180	Ontra Orange			
			0	ACTO A OCO			
				30 5			
				SGAOTIO			
				36 189	g.		
	TOTAL MATERI		TOTAL LA	BOR 3	703.61		

DESCRIPTION OF WORK PERFORMED							
Remove al	Ll w	vindows	damaged	by	stucco	contractor.	Supply new
windows and install.							

C. DAILY TOTALS:

TOTAL LABOR	3703.61
TOTAL MATERIALS	3703.61
DAILY TIME & MATERIALS TOTAL	7407.22

X		X	
Submitted by contractor or contractors agent	date	Acknowledged by General Contractor or Owner	date