

## Profile



© 2010 National Coatings Corporation.  
All Rights Reserved.

# SYSCO

*Size: 70,000 Square Feet*

*Location: Walnut, California*

## **Challenge** *Sun-Damaged BUR Capsheet*

- Sun-damaged and leaking BUR capsheet.
- R-value efficiency loss resulting from hot capsheet.
- Budget constraints.

## **Solution** *AcryPly® Restoration System*

- Reinforced seamless system.
- Phased installation.
- 50°F cooler peak roof surface temperatures.
- Improved energy efficiency.

*With their new Cool Roof System, Sysco has overlaid a failing roof with additional high strength waterproofing and improved their building's insulating efficiency.*

**NATIONAL  
COATINGS**

**COOL  
ROOF  
SYSTEMS®**

**NATIONAL**

**COATINGS**

1201 Calle Suerte, Camarillo, CA 93012

(800) 423-9557, Fax (800) 294-3866

[www.nationalcoatings.com](http://www.nationalcoatings.com), [info@nationalcoatings.com](mailto:info@nationalcoatings.com)