

Policy #:
1111111111

Insured:
Mr Tester

Address to Inspect:
5575 Shady ave lowville, NY 13367

Completed By:
Tom Guignard

ViewSpection #:
792

Property Snapshot



Year Built:
1945

Dogs:
Yes

of Outbuildings:
1

Solid Fuel Burner:
No

Survey Conditions

Actual Owner Name:
Tom G

Person Interviewed:
Mr Tester

Survey Comments

Survey Comments:
Survey completed from exterior. Dog was noted and photographed thru screen door.

Dwelling

Year Built:
1945

Occupancy:
By Owner



Front



Entrance Area



Entrance Area 2



Right



Rear



Left



Left 2

Outbuildings

Outbuilding 1



Outbuilding

Roofing



Roof

Outside

Steps

Yes



Steps



Steps 2



Steps 3

Deck

Yes

Sidewalk

Yes



Sidewalk



Sidewalk 2

Driveway

Yes



Driveway

Yard

Yes

Trampoline

Yes



Trampoline

Utility

Not completed

Solid Fuel Burner

Not completed

Dogs and Livestock

Dogs Outside:

Yes

Dogs Inside:

No



Dog Outside

Pool and Hot Tub

Pool on Premise:Yes

Pool Fenced from Neighbors:
Yes

Fence Between House and Pool:
Yes

Pool Gate Secured:
Yes

Hot Tub on Premise:No



Pool



Pool Fence



Fence Around Pool



Pool Gate

All Photos



Front



Entrance Area



Entrance Area 2



Right



Rear



Left



Left 2



Outbuilding



Roof



Steps



Steps 2



Steps 3



Sidewalk



Sidewalk 2



Driveway



Trampoline



Dog Outside



Pool



Pool Fence



Fence Around Pool



Pool Gate