

Gipson Construction

2272 Moores Mill Road, Suite 201

Auburn, AL 36830

Phone: 1.800.700.8321

Email: hgipson@uda1.com



Summit at Smiths Square - Phase 2 - Thursday, April 18, 2019

2272 Moores Mill Road

Auburn, AL 36830

Client(s): Caitlyn Owens, Polly ClientLink,

Van Plomy, Wayne Davis

Phone: 800-700-8321110

Punch Lists ▶ Safety ▶ Safety Inspection Checklist

1. Personal Protective Equipment

Are the following supplied by employer and worn by workers, if required at this job site?

- Hard Hats
- Boots
- Hearing Protection
- Eye Protection
- Respiratory Protection

Due: None Priority: **Medium** Status: None

Assigned Resource(s): Ian Schaefer

Room / Location: None

2. Ladders

Are ladders present at this job site? Check that they are:

- Correct size for job
- Fully opened and spreader bars locked
- Firm foundation for ladder feet
- Proper climbing procedures observed
- Free from obvious defects

Due: None Priority: **High** Status: None

Assigned Resource(s): None

Room / Location: None

3. Scaffolds

Are scaffolds present at this job site? Check the following:

- Fall protection used if over 10 ft. tall
- Set up on level, stable footing
- Platform is appropriate width for type of scaffold

Due: None Priority: **High** Status: None

Assigned Resource(s): None

Room / Location: None

4. Fall Protection

Is fall protection needed at this job site? If yes, check the following:

- Provided for heights of 10 ft. or more
- Harness worn properly and attached to secure anchorage
- Slide guards are installed across full width and all sides

Due: None Priority: Status: None

Assigned Resource(s): None

Room / Location: None

5. Electrical Hazards

Are overhead and underground electrical power lines located, identified, and avoided?

Are ladders, scaffolds, equipment and materials more than 10 feet from any electrical power lines?

Due: None Priority: **High** Status: None

Assigned Resource(s): None

Room / Location: None

6. Excavations

Are soil and conditions inspected daily? Are safe exits (ladders) provided for excavations greater than 4 ft. deep? Is shoring, shielding, and inclination assessed for excavations greater than 5 ft. deep?

Due: None Priority: Status: None

Assigned Resource(s): None

Room / Location: None

Completion Approval

Contractor's Signature

Date

Owner's Signature

Date